

Coates Hire Pre Divestment Inspection Checklist

Trucks / Motor Vehicles

Description 2T Tipper Asset # 1146341 Service Job # 4097605

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: ***** Copy Data Plate information in this section *****

Make/ Model ISUZU NLR200 Engine/Motor - Make/Model _____
 Year 2014 Engine Serial Number _____
 Serial Number JAAANR85EE7101291 Meter Reading 63845

Comments: _____

Features:
 Pickup Flat Bed Dump Boom Other Comments: _____
 Drive System 2WD 4WD Power Take Off Yes No
 Axle Weights Rating: Front _____
 Axle Weights Rating: Rear _____
 Registration Information Number _____ Year _____

Overall Appearance:

	Good	Fair	Poor	Comments:
Control Station/Operator Station	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<u>damage to RHS mirror, dent to RHS panel</u>
Sheet metal/Fiberglass Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Paint	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	
Lights	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	

Operator Station

	Good	Fair	Poor	N/A	Comments:
Seat Condition	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	i
Steering Controls	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Powertrain Controls	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Hydraulic Controls	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

	Operates			Operates		
	Yes	No	N/A	Yes	No	N/A
Safety Belt	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Gauges	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Air Conditioner	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
Heater	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
				Horn	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				Warning Alarms	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				Odometer	<input checked="" type="checkbox"/>	<input type="checkbox"/>
				Wipers	<input checked="" type="checkbox"/>	<input type="checkbox"/>

Engine or Electric Motor:
 Power: Diesel Gas Comments: _____
 Does it start? Yes No
 Did it need to be jumped? Yes No
 Acceptable Power Yes No
 Unusual Noises Yes No
Alt belt needs replacing, Drive belt needs replacing
engine sump damaged needs replacing

Transmission
 Transmission Auto Manual Hydrostatic No. Speeds _____ Comments: _____
 Operates Yes No N/A
 Forward Yes No N/A
 Reverse Yes No N/A
 Shifting Yes No N/A
 Clutch Yes No N/A
 Parking Brake Yes No N/A
 Brakes Yes No N/A
transmission ups - debris found in trans oil
damage to internal components

Chassis

	Good	Fair	Poor	Inoper	Missing	N/A	Comments:
Bumpers	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Windshield Condition	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Trailer Electrical Connections	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	
Work Body Function	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	

Tyre Condition:

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- <u>Bridge Stone</u>	Brand- <u>B&T</u>	Brand- <u>Bridge Stone</u>	Brand- <u>Milage plus</u>
Size- <u>195/75 R16</u>	Size- <u>195/75 R16</u>	Size- <u>195/75 R16</u>	Size- <u>195/75 R16</u>
Condition- <u>Good</u>	Condition- <u>Fair</u>	Condition- <u>Good</u>	Condition- <u>Good</u>

Full Name of Employee completing inspection: _____ Branch where inspection completed: _____

Any other known issues, faults:

