Coates Hire Pre Divestment Inspection Checklist			
Traffic (Arrow boards, traffic lights and VMS)			
Name		Branch Madry	
Description VMS &	DOARD SISA	Asset # 1146746 Service Job #	
This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.			
General Information: *** Copy Data Plate information in this section ***			
Make/ Model	ERMAL Engine	ine/Motor - Make/Model	
Year		ine Serial Number	
Serial Number 259 VIN Comments:	132021 Meter 1	er Reading	
Features: List features or opt	tions for the machine:	Yes No Battery Pack (Electric) □ □	
- Ra	101	Battery Pack (Electric)	
Some KA	WELL NOT	Number of Batteries	
WISPULA	MINK	Battery Size 7/05	
		Fuel Tank Capacity	
Overall Assessment			
Overall Appearance: Control Station\Operator Station Sheet metal\Fiberglass Condition Paint Lights	Good Fair Poor	Comments:	
Control Station Operates Comments:			
Operator Controls Gauges Operational? Controller	No N/A	·	
Engine or Electric Motor:			
Power: Diesel Yes Does it start? Z Did it need to be jumped? Acceptable Power Unusual Noises	Gas	Solar 🗹	
Chassis:	Good Fair Poor Inope	per Missing N/A Comments:	
Landing Gear / Outriggers Frame Condition Trailer Lights Trailer Electrical Connections Trailer Brakes Switches Arrow Board Message Center Solar Panel Battery and Connections			
Tyre Condition: Left - Front	Left - Rear	Comments:	
Brand-	Brand-		
Size-	Size-		
Condition- Far 2	Condition- A-7-		
Definium Device fitted? Yes	No	Definium device returned to BU ASM	
Issue 1.1		1/1/2013 AST-CL-011A Asset Inspection Checklist - Traffic	