



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (**Jungheinrich**) official notice that the second-hand plant offered for sale through this transaction (direct sale or auction) may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Safety & Compliance of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The **enclosed Condition Report** sets out the current condition of this plant, including any identified faults.

While all efforts have been made to identify faults, there may be other faults present that did not show up at time of inspection

Operational Safety Notice

The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use.

By participating in this sale and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

Operating condition of the plant

Note: this condition report is a safety report only and does not represent overall appearance or operating condition of the plant

For any questions please contact Jungheinrich



Used Sale Safety & Compliance Check

MHE-000262 / 82820481 / Workshop Brisbane / 27/03/2026 / Jungheinrich / ETR335D

Complete

Flagged items	0
Report ID	MHE-000262
Technician Name	Workshop Brisbane
Conducted on	27/03/2026 10:33 AM AEST
Branch	Brisbane
Unit Details	
Equipment No.	82820481
Brand	Jungheinrich
Model	ETR335D
Mast ID	CS18D9300023

Include Images of the Front, Rear & Sides of the Unit



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6

Observations Summary

Truck Category

Category 5 - Electric Reach Truck

Emergency Stop, Horn/Warning device, lights, reverse alarm and flashing lights operational

Yes

No reverse lights fitted

Foot switch allows operation only when depressed

Yes

Seat switch and seat belt operate sequentially (site dependent)

N/A

Mast switch operation for travel speed reduction to 3km/h above specified height

Yes

Are brakes and park brake functioning correctly?

Yes

Are tyre treads within limits and/or free from damage?

Yes

Are fork tynes in good condition and within specification?

Yes

Are mast chains in good condition, within specification and working correctly?

Yes

Are all controls inc. lift, tilt & sideshift/auxilliary functions working correctly

Yes

Confirm safety systems not bypassed or malfunctioning?

Yes

Additional Observations & Actions

List any other notable defects or faults e.g. ROPS/FOPS damage etc.

Main chains 1% wear

Technician Sign off



27/03/2026 10:56 AM AEST

Media summary



Photo 1



Photo 2



Photo 3



Photo 4




Photo 5



Photo 6