



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (**Jungheinrich**) official notice that the second-hand plant offered for sale through this transaction (direct sale or auction) may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Safety & Compliance of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The **enclosed** Condition Report sets out the current condition of this plant, including any identified faults.

While all efforts have been made to identify faults, there may be other faults present that did not show up at time of inspection

Operational Safety Notice

The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use.

By participating in this sale and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

Operating condition of the plant

Note: this condition report is a safety report only and does not represent overall appearance or operating condition of the plant

For any questions please contact Jungheinrich



Used Sale Safety & Compliance Check

MHE-000169 / 133594 - 91653198 / Oluwatobi Olagbegi /
22/01/2026 / Jungheinrich / EKM202

Complete

Flagged items

0

Report ID

MHE-000169

Technician Name

Oluwatobi Olagbegi

Conducted on

22/01/2026 2:19 PM ACDT

Branch

Adelaide

Unit Details

Equipment No.

133594 - 91653198



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7

Brand

Jungheinrich

Model

EKM202



Photo 8

Include Images of the Front, Rear & Sides of the Unit



Photo 9



Photo 10



Photo 11

Observations Summary

Truck Category

Category 8 - Access Equipment

Enter date of commission and ensure photo of compliance plate uploaded

24/07/2024

Is regulatory servicing up to date

No




Photo 12




Photo 13

Are emergency controls and retrieval system functioning correctly	Yes
Are visual and audible alarms (inc. flashing light/strobe and beeper/squawker) functioning correctly	Yes
Are harness anchor points in good condition	Yes
Are all cables, wiring harness etc. in good condition and secure	Yes
Are wheels and tyres in serviceable condition	Yes
Do brakes function	Yes
Are all placards, labels, warnings and control markings legible	Yes



Photo 14



Photo 15

Are operator's manual in machine and legible	Yes
Are outriggers/stabilisers in serviceable condition	Yes
Is guardrail system including gates with self-closing action in serviceable condition	Yes
For boomlifts, is slew lock pin with machine and in serviceable condition	Yes



Photo 16



Photo 17

For boomlifts, is slew brake system in serviceable condition	Yes
Are there any visual structural defects or damage	No
Do all drive, speed and lift functions work correctly including any speed limiting devices	Yes
If a secondary guarding system is fitted is it functioning correctly	N/A

Additional Observations & Actions

List any other notable defects or faults e.g. ROPS/FOPS damage etc.



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22

Technician Sign off



oluwatobi
23/01/2026 7:35 AM ACDT

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11




Photo 12

OWNER MUST BE REPORTED AND CORRECTED ON THE PLATFORM WITHDRAWN FROM SERVICE		Signature:	
Reporting Fault / Problem (Name in Cap)	Dept./Other Info (Cap)	Service Person (Name in Cap)	
Problem Reported to (Name in Cap)	Dept./Other Info (Cap)	Qualifications (Cap)	
	Time Reported	Date Recalled	Time Recalled
Details of Fault/Problem:		Action Taken (Summary in Cap)	
OWNER INSTRUCTIONS / ROUTINE MTCE & SAFETY CHECKS:			
<p>Checks relative to frequency and severity of use, but in no case more than 3 months apart, the owner (or owner's authorized agent) must:</p> <p>1. Owner Routine Maintenance & Safety Checks (see back cover). Record and sign below.</p> <p>2. Specify any Faults/Problems in Section 2 (p.14 pages).</p> <p>3. ANY SAFETY RELATED FAULTS MUST BE REPORTED AND CORRECTED OR THE PLATFORM WITHDRAWN FROM SERVICE.</p> <p>Details of last 'Owner Routine Maintenance & Safety Check' (Brought forward from previous Logbook):</p>			
Date: 24/01/24	Service Person (Name in Cap): BEN S	Co./Dept. (Cap): JHA	Is this E2OP still within the three monthly service requirement? Yes
Date: 24/01/24	Qualifications (Cap): AUTO ELEC	Signature: [Signature]	Notes / Service Reference (Optional): Annual Inspection
OWNER ROUTINE MTCE & SAFETY CHECKS:			

Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22