

## CarHistory Dealer Report & PPSR Certificate

Report generated on 04/03/2025

REPORT ID  
**13746515**

|                          |                   |
|--------------------------|-------------------|
| VIN                      | 6g1fb5e34e1006051 |
| Make                     | HOLDEN            |
| Model                    | COMMODORE         |
| Variant/series           | SV6VF             |
| Body                     | 4D SEDAN          |
| Transmission             | 6 SP AUTOMATIC    |
| Year (first retail date) | 2014              |
| Colour                   | WHITE             |



\*Picture provided is a sample only

### QUICK SUMMARY



No stolen status reported



Written-off status reported



No financial interests reported



No odometer rollback reported



Registration status unavailable

## VEHICLE DETAILS

 Registration status unavailable

### VEHICLE REGISTRATION

|                          |    |
|--------------------------|----|
| Registration plate       | -  |
| Registration state       | WA |
| Registration expiry date | -  |

### FIRST SALE INFORMATION

|                        |             |
|------------------------|-------------|
| First sale date        | 23-12-2014  |
| Postcode of first sale | 4006        |
| First buyer type       | NON-PRIVATE |

### ENGINE DETAILS

|                  |                 |
|------------------|-----------------|
| Engine number    | LFX142320034    |
| Engine size      | 3.6L            |
| Cylinders/rotors | V6              |
| Fuel type        | UNLEADED PETROL |
| Power (KW)       | 210             |
| Torque (Nm)      | 350             |

### VEHICLE RATINGS


|                      |   |
|----------------------|---|
| ANCAP safety rating  | - |
| Overall green rating | - |
| Air pollution rating | - |
| Greenhouse rating    | - |



#### CarHistory notes:

Vehicle registration information is sourced via the PPSR. Refer to the PPSR Certificate below.

## REPORTED ODOMETER HISTORY

 No odometer rollback reported

### LAST REPORTED ODOMETER READING


|               |            |
|---------------|------------|
| Kilometres    | 72,233     |
| Date reported | 29/08/2019 |

### READING ENTERED BY YOU

|               |            |
|---------------|------------|
| Kilometres    | 211,395    |
| Date reported | 04/03/2025 |

The odometer history for this vehicle has been supplied to CarHistory by various sources within the automotive industry.

| Kilometres | Date reported | Alerts |
|------------|---------------|--------|
| 211,395    | 04/03/2025    |        |
| 72,233     | 29/08/2019    |        |
| 39,713     | 04/02/2017    |        |



**CarHistory notes:**  
*CarHistory relies on data received from third parties. We recommend you review the vehicle's log book and service history to determine the accuracy of the vehicle's odometer reading.*

## REPORTED SALES LISTINGS

No known sales listings for this vehicle.

**CarHistory notes:**  
*Reported sales listings are sales advertisements derived from various ecommerce sites and provide an indication of how often the vehicle has been listed for sale.*

## FINANCE CHECK

**✓ No financial interests reported**

PPSR has reported that this vehicle is not encumbered.

**CarHistory notes:**  
*Financial encumbrance information is sourced via the PPSR. Refer to the PPSR Certificate below.*

## WRITTEN-OFF CHECK

**❗ Written-off status reported**

PPSR has reported that this vehicle has been written-off.

|                    |  |
|--------------------|--|
| <b>Written-off</b> | Impact   Seat belt pre-tensioner   Major mechanical damage<br>Impact   Airbag front   Major mechanical damage<br>Impact   Chassis/structural rail (passenger)   Light structural |
|--------------------|--|

|                       |   |
|-----------------------|---|
|                       | Impact   Interior   Heavy panel<br>Impact   Passenger side   Heavy panel<br>Impact   Passenger rear   Light panel<br>Impact   Passenger front   Heavy panel |
| <b>Date recorded</b>  | 01 Oct 2020   |
| <b>State recorded</b> | WA  |
| <b>Type</b>           | Inspected   |

|                       |   |
|-----------------------|---|
| <b>Written-off</b>    | Impact   Passenger front   Heavy panel<br>Impact   Passenger rear   Light panel<br>Impact   Passenger side   Heavy panel<br>Impact   Interior   Heavy panel<br>Impact   Chassis/structural rail (passenger)   Light structural<br>Impact   Airbag front   Major mechanical damage<br>Impact   Seat belt pre-tensioner   Major mechanical damage |
| <b>Date recorded</b>  | 01 Oct 2020   |
| <b>State recorded</b> | QLD   |
| <b>Type</b>           | Inspected   |

|                       |   |
|-----------------------|---|
| <b>Written-off</b>    | Impact   Passenger front   Heavy panel<br>Impact   Passenger rear   Light panel<br>Impact   Passenger side   Heavy panel<br>Impact   Interior   Heavy panel<br>Impact   Chassis/structural rail (passenger)   Light structural<br>Impact   Airbag front   Major mechanical damage<br>Impact   Seat belt pre-tensioner   Major mechanical damage |
| <b>Date recorded</b>  | 13 Aug 2020   |
| <b>State recorded</b> | QLD   |
| <b>Type</b>           | Repairable Write-off  |



**CarHistory notes:**

*Written-off information is sourced via the PPSR. Refer to the PPSR Certificate below.*

*WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).*

**STOLEN CHECK**

## No stolen status reported

PPSR has reported that this vehicle is not stolen.



### CarHistory notes:

*Stolen information is sourced via the PPSR. Refer to the PPSR Certificate below.*

*WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).*

---

## ACCESS YOUR REPORT ONLINE

To allow an individual to view this report online, simply provide them with the following link:

<https://secure.carhistory.com.au/vcn?vcn=A3-WFCJ>

---

## GENERAL DISCLAIMERS

This report has been supplied on the [Terms and Conditions](#) set out on the CarHistory website, and accepted by you before you purchased this report.

The data used to compile this report has been sourced from various independent and Government sources, as a result CarHistory can accept no responsibility for the accuracy or completeness of information.

---

## PPSR CERTIFICATE

The following certificate has been issued by the Australian Financial Security Authority.

---



04/03/2025

## Serial Number Search Certificate

This is a serial number search certificate for a serial number search

This Search certificate is provided under section 174 of the *Personal Property Securities Act 2009*

Search certificate number: 8299670630900001  
Search number: 829967063090

This search certificate reflects the data contained in the PPSR at 04/03/2025 18:05:05 (Canberra Time).

### Search Criteria Details

Serial number search type: VIN  
Motor vehicle: 6g1fb5e34el006051  
PPSR registration state searched: Current

### PPSR Registration Details

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

### Additional Motor Vehicle Details – NEVDIS

|                            |                                  |                           |                   |
|----------------------------|----------------------------------|---------------------------|-------------------|
| Identifier number:         | 6G1FB5E34EL006051                | Identifier type:          | VIN               |
| Vehicle type:              | CAR / SMALL<br>PASSENGER VEHICLE | Make:                     | HOLDEN            |
| Body type:                 | CAR/SEDAN                        | Model:                    | COMDOR            |
| Colour:                    | WHITE                            | Engine number:            | LFX142320034      |
| Registration plate number: | No data recorded.                | State vehicle registered: | WA                |
| Registration expiry:       | No data recorded.                |                           |                   |
| Year of manufacture:       | 2014                             | Year/Month of compliance: | No data recorded. |

### Important NEVDIS notifications about the Vehicle

#### Written-off:

WA, 01 Oct 2020, Inspected

- I41F [Impact | Seat belt pre-tensioner | Major mechanical damage]
- I38F [Impact | Airbag front | Major mechanical damage]
- I17D [Impact | Chassis/structural rail (passenger) | Light structural]
- I09A [Impact | Interior | Heavy panel]
- I06A [Impact | Passenger side | Heavy panel]
- I05B [Impact | Passenger rear | Light panel]
- I01A [Impact | Passenger front | Heavy panel]

QLD, 01 Oct 2020, Inspected

- I01A [Impact | Passenger front | Heavy panel]
- I05B [Impact | Passenger rear | Light panel]

This search certificate reflects the data contained in the PPSR at 04/03/2025 18:05:05 (Canberra Time).

- I06A [Impact | Passenger side | Heavy panel]
- I09A [Impact | Interior | Heavy panel]
- I17D [Impact | Chassis/structural rail (passenger) | Light structural]
- I38F [Impact | Airbag front | Major mechanical damage]
- I41F [Impact | Seat belt pre-tensioner | Major mechanical damage]

QLD, 13 Aug 2020, Repairable Write-off

- I01A [Impact | Passenger front | Heavy panel]
- I05B [Impact | Passenger rear | Light panel]
- I06A [Impact | Passenger side | Heavy panel]
- I09A [Impact | Interior | Heavy panel]
- I17D [Impact | Chassis/structural rail (passenger) | Light structural]
- I38F [Impact | Airbag front | Major mechanical damage]
- I41F [Impact | Seat belt pre-tensioner | Major mechanical damage]

**Stolen:**

- Not recorded as stolen.

Tasmanian stolen vehicle information is currently unavailable from this service. For information about the status of Tasmanian vehicles, go to:

<https://www.transport.tas.gov.au/MRSWebInterface/public/regolookup/registrationlookup.jsf> (Note: you will need to provide the vehicle registration plate number to search this site).

A stolen vehicle notification, or the absence of one, does not necessarily mean a vehicle is or is not stolen.

If there is a stolen vehicle notification you wish to enquire about, you should contact the police force in the State or Territory indicated immediately after the date in the notification. The reference number at the end of the notification should be quoted as a part of your enquiry.

Please note that there may be multiple stolen notifications shown. A stolen notification can be for a VIN, Plate, Chassis and/or Engine.

Vehicle information is requested from Austroads NEVDIS database for each transaction involving a vehicle VIN or Chassis Number on the PPSR. The data is not part of interests registered on the PPSR and it is presented without any guarantee regarding its accuracy.

The NEVDIS data is intended to assist users with checking that the VIN or Chassis Number they entered, along with information they have about the vehicle from other sources, is accurate and to provide users with any data held on NEVDIS about a vehicle's stolen or written off status.

State and territory road agencies are the main source of NEVDIS data and the primary point of contact for enquiries, errors, and corrections.

Access to and use of data provided through the PPSR is subject to the PPSR General Conditions of Use and applicable third party data conditions (which can be obtained at [www.ppsr.gov.au](http://www.ppsr.gov.au)). To the extent permitted by law, all data provided through the PPSR is made available without any representation or warranty of any kind (without limitation in respect to accuracy) and the Commonwealth, and our third party data providers (which includes any person mentioned in the Third Party Data Conditions as providing information through the PPSR), have no liability to you in respect of any loss or damage that you might suffer no matter how arising (including negligence) that is directly or indirectly related to the NEVDIS Data.

**How to verify this certificate on the PPSR**

You can use the search number from an original search (as shown on this certificate) to retrieve the original search results and to issue a copy of the search certificate at <https://transact.ppsr.gov.au/pps/Home>.

There is no fee, however this process will not provide any update to the information in the original search.

This search certificate reflects the data contained in the PPSR at 04/03/2025 18:05:05 (Canberra Time).

### **Privacy and Terms and Conditions**

The Australian Financial Security Authority is subject to the *Privacy Act 1988* which requires that we comply with the Australian Privacy Principles (APPs) set out in the Act. The APPs set out how Australian Government agencies should collect, use, store and disclose personal information and how individuals can access records containing their personal information.

Access to and use of the PPSR is subject to the General Conditions of Use, as well as other relevant terms and conditions. All relevant terms and conditions can be found at [www.ppsr.gov.au](http://www.ppsr.gov.au).

End of search certificate

EMAIL: [enquiries@ppsr.gov.au](mailto:enquiries@ppsr.gov.au)

WEBSITE: [www.ppsr.gov.au](http://www.ppsr.gov.au)

---

GPO Box 1944 Adelaide SA 5001

1300 00 77 77