K & S CORPORATION LIMITED

Work Order History Report

Asset W/O No Description DoneReading

WESTERN AUSTRALIA WA 129 KSF - BROOKES TRANSPORT

D2672	IVECO POWERSTAR E4 6X4 DAY CAB PRIME MOVER	

129		K2E - BROOKE2 LKAN25OK1		
2	IVECO POWERSTAR E	4 6X4 DAY CAB PRIME MOVER		
	1217549	Fit beacon to truck-wo attached	21/07/2021	Kilometres
	1221384	A Service - 10,000km OR 3 Months - Prime Mover WA-completed as per service sheet-wo attache	7/09/2021	542,269 Kilometres
	1223708	Fabricate grab bar for behind cab	7/09/2021	Kilometres
	1228747	check oil - topped up	16/09/2021	Kilometres
	1229408	Electrical issues repaired	21/09/2021	Kilometres
	1231099	Replace right hand headlight globe	30/09/2021	Kilometres
	1209586	Turntable Inspection Light - Prime Movers-completed-wo attached	6/12/2021	Kilometres
	1236040	Roadworthy Inspection - 6 Month - Prime Mover WA-completed as per service sheet-wo attached	6/01/2022	548,949 Kilometres
	1240676	A Service - 10,000km OR 3 Months - Prime Mover WA-completed as per service sheet-wo attache	6/01/2022	548,949 Kilometres
	1236352	right hand external door mirror cracked, replace fuel bowl - repaired-wo attached	1/03/2022	Kilometres
	1261056	A Service - 10,000km OR 3 Months - Prime Mover WA-completed as per service sheet-wo attache	4/05/2022	557,524 Kilometres
	1267920	turbo charger bypassing oil seals - remove breather hose, clean oil from hoses-wo attached	5/05/2022	Kilometres
	1269989	Replaced RHF head light globe-wo attached	17/05/2022	Kilometres
	1271930	Truck wont start -wo attached	27/05/2022	Kilometres
	1273628	Roadworthy Inspection - 6 Month - Prime Mover WA_completed as per service sheet-wo attached	21/07/2022	561,040 Kilometres
	1280692	B Service - 20,000km OR 12 Months - Prime Mover WA-completed as per service sheet-wo attack	26/08/2022	562,493 Kilometres
	1289697	replaced chassis deck plate locks-wo attached	8/09/2022	Kilometres
	1290272	Repaired tail light-wo attached	13/09/2022	Kilometres
	1295298	Fuel leak - replaced fuel pump-wo attached	24/10/2022	Kilometres
	1305469	Repaired drivers seat belt-wo attached	7/12/2022	Kilometres
	1300678	A Service - 10,000km OR 3 Months - Prime Mover WA-completed as per service sheet-wo attache	7/01/2023	571,930 Kilometres
	1308212	Roadworthy Inspection - 6 Month - Prime Mover WA-completed as per service sheet-wo attached	7/01/2023	571,930 Kilometres
	1309963	Replaced suzi lines and air con bracket-wo attached	7/01/2023	Kilometres
	1312172	driver reports that the right hand door glass is inoperative-wo attached	21/01/2023	Kilometres
	1325106	Replaced electrical plug-wo attached	6/04/2023	Kilometres
	1322785	A Service - 10,000km OR 3 Months - Prime Mover WA-completed as per service sheet-wo attache	13/04/2023	580,029 Kilometres
	1323344	Tune Up - 100,000km - WA-completed	13/04/2023	580,029 Kilometres
	1332883	DVSR 37205 - driver reports - battery charging dash light illuminated - indicator faults - cab leaki	25/05/2023	Kilometres
	1336062	Replaced head light globe-wo attached	12/06/2023	Kilometres
	1341806	DFSR 37207 - driver reports reverse buzzer not working - replaced buzzer-wo attached	17/07/2023	Kilometres
	1350425	B Service - 20,000km OR 12 Months - Prime Mover WA-completed as per service sheet-wo attach	16/10/2023	592,620 Kilometres
	1335969	Roadworthy Inspection - 6 Month - Prime Mover WA-completed as per service sheet-wo attached	17/10/2023	592,620 Kilometres
	1360809	MTData -not tracking	3/11/2023	Kilometres
	1360631	DFSR 37210 - replaced left low beam light-wo attached	7/11/2023	Kilometres
	1379781	Tyre blow out damage - tail light repaired-wo attached	8/03/2024	Kilometres
	1370701	C Service - 100,000km - Prime Mover WA-completed as per service sheet-wo attached	15/03/2024	603,938 Kilometres
	1380892	Repaired rear bar and lights-wo attached	19/03/2024	Kilometres
	1383320	not starting - batteries-wo attached	3/04/2024	Kilometres
	1379328	DFSR 37211 and 37214 - window winder broken - regulator replaced-wo attached	12/06/2024	Kilometres
	1392737	A Service - 10,000km OR 3 Months - Prime Mover WA-completed as per service sheet-wo attache	16/07/2024	610,813 Kilometres
	1381260	Roadworthy Inspection - 6 Month - Prime Mover WA-completed as per service sheet-wo attached	16/07/2024	610,813 Kilometres
	1399582	Light repaired-wo attached	16/07/2024	Kilometres
	1399402	Replaced brake booster-wo attached	17/07/2024	Kilometres
	1400859	Light housing repaired-wo attached	25/07/2024	Kilometres