

Coates Hire Pre Divestment Inspection Checklist

Materials Handling (eg. Forklifts, Telehandlers)

Description 2.5T RT Forklift Asset # F25110 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Use Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate information in this section ***

Make/Model Mantow MH25-4T Engine/Motor - Make/Model Kubota
 Year 2010 Engine Serial Number AE1276
 Serial Number 590609 Meter Reading 6952

Comments: _____

Features:

Drive System 2WD ☒ 4WD ☒
 Cab ☐ Yes ☒ No
 Multi-Purpose Bucket ☐ Front Bucket width at widest point NA
 Rear Box Blade ☐ Rear Box Blade width at widest point NA

Comments: _____

Overall Appearance:

| | Good | Fair | Poor | Comments: |
|----------------------------------|--------------------------|--------------------------|-------------------------------------|--|
| Control Station/Operator Station | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <u>TOP CAB window smashed, Paint & cover Behind CAB</u> <u>Back Damaged</u> |
| Sheet metal/Fiberglass Condition | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Paint | <input type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | |
| Lights | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |

Operator Station

| | Good | Fair | Poor | N/A | Comments: |
|---------------------|--------------------------|--------------------------|--------------------------|--------------------------|--|
| Seat Condition | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <u>Seat Damaged, Indicator/Light switch base worn.</u> |
| Steering Controls | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Control Lock Lever | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Powertrain Controls | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Hydraulic Controls | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| | Operates | | | | |
| | Yes | No | N/A | | |
| Safety Belt | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Operates |
| Gauges | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | Yes |
| Air Conditioner | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | No |
| Heater | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | N/A |
| | | | | | Operates |
| | | | | | Yes |
| | | | | | No |
| | | | | | N/A |
| | | | | | Operates |
| | | | | | Yes |
| | | | | | No |
| | | | | | N/A |

Engine

Power: Diesel ☒ Gas ☐
 Does it start? Yes ☒ No ☐
 Did it need to be jumped? Yes ☒ No ☐
 Acceptable Power Yes ☒ No ☐
 Unusual Noises Yes ☒ No ☐
 Comments: Fuel Filter Assy Needs Replacing,

Transmission

| | Operates? | Comments: |
|---------------|-------------------------------------|--------------------------|
| | Yes | No |
| Forward | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Reverse | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Shifting | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Parking Brake | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| Brakes | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Hydraulics

| | Operates? | Leaks? | Comments: |
|----------------|-------------------------------------|--------------------------|--------------------------|
| | Yes | No | N/A |
| Pump | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Hoses | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Cylinders | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Drive Motors | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Brakes | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| Parking Brakes | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

control valve leaks, control linkages worn
Hyd site glass leaking, Bad oil leak under CAB
somewhere

Chassis

| | Condition | Good | Fair | Poor | Inoper | Missing | N/A | Comments: |
|---|-----------|--------------------------|-------------------------------------|--------------------------|--------------------------|--------------------------|--------------------------|--|
| Tynes | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <u>Fuel TANK Rusted out & leaking, fuel cap</u> <u>and Rubber Around Neck Need Replacing</u> <u>load and compliance plates Damaged</u> |
| Lift guard | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Outriggers and Pads | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Loader Lift Arms | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Rear Boom & Stick | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Boom Lock | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Front Bucket | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <u>General Appearance Poor</u> <u>CAB MOUNTS Worn CAB Twisted and won't line</u> <u>UP with Rear locating</u> <u>Pins.</u> |
| Rear Bucket | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Wear | | Minimal | Moderate | Excessive | | | | |
| Tynes | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Bucket Tilt Linkage Pins & Bushing Wear | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Loader Bucket Pins & Bushing Wear | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Extend-a-hoe Stick Guide Wear | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |
| Boom & Stick Pins & Bushing Wear | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | |

Tyre Condition:

| Left - Front | Left - Rear | Right - Front | Right - Rear |
|-------------------------|---------------------------|-------------------------|-----------------------|
| Brand- <u>Michelin</u> | Brand- <u>Removed for</u> | Brand- <u>Michelin</u> | Brand- <u>CAMSO</u> |
| Size- <u>280-80-R22</u> | Size- <u>Another fork</u> | Size- <u>280/80 R22</u> | Size- <u>27-10-12</u> |
| Condition- <u>FAIR</u> | Condition- <u>LIK</u> | Condition- <u>FAIR</u> | Condition- <u>OK</u> |

Any other known issues, faults: _____