



27 Staite Street, Wingfield SA 5013
PO Box 412, Hahndorf SA 5245
Phone: 08 8246 0761

ABN: 49 125 382 747

admin@aceess.com.au

ANNUAL MACHINE INSPECTION : BOOM LIFT

OWNER NAME AND ADDRESS	INSPECTOR NAME AND ADDRESS	MACHINE MODEL:- HTA13P
	RUSSELL JACKSON	SERIAL NO:- 2072017-00097
DATE : 16/7/2025	ACE EQUIPMENT	COMMISSION DATE:- 2019
		DATE OF LAST INSPECTION:-
		HOURLY METER READING:- 575

ANNUAL INSPECTION	
Y=YES N=NO C-CORRECTED N/A=NOT APPLICABLE	
PLATFORM	
1 LUBRICATE CONTROLS AND ENSURE THEY RETURN TO NEUTRAL POSITION, OPERATE PROPERLY, AND SAFETY DETENTS OPERATE PROPERLY	Y
2 LOAD CAPACITY MARKINGS INSTALLED AND LEGIBLE	Y
3 "DEADMAN" ENABLE SWITCH OPERATES PROPERLY	Y
4 EMERGENCY STOP OPERATES PROPERLY (SHUTS OFF CONTROLS AND ENGINE)	Y
5 CHECK INTEGRITY OF PLATFORM, INCLUDING LANYARD ATTACH POINTS. GATE CLOSURES AND LATCHES PROPERLY	Y
6 PLATFORM AND BOOM UPRIGHT LEVELLING SYSTEMS OPERATE PROPERLY	Y
7 CONTROL BOX DECAL LEGIBLE	Y
8 ALL FUNCTION AND SPEED CUT OUTS OPERATE PROPERLY	Y
TURNTABLE AND CHASSIS	
9 WHEEL RIM NUTS TORQUED PROPERLY	Y
10 TYRES IN GOOD CONDITION	Y
11 ALL FLUID LEVELS CORRECT: HYDRAULIC TANK, HUBS, COOLANT AND BATTERIES	Y
12 GREASE AND LUBE PER SERVICE MANUAL	Y
13 ENGINE IDLE, THROTTLE AND RPM'S SET PROPERLY	Y
14 FUEL AND HYDRAULIC TANK CAPS TIGHT AND BREATHER CLEAR	Y
15 EXHAUST SYSTEM FREE OF LEAKS	Y
16 MANUAL DESCENT, AUXILIARY POWER SYSTEM AND GROUND CONTROLS OPERATE PROPERLY AND DECAL LEGIBLE	Y
17 CHECK THAT ALL FILTERS ARE SERVICEABLE	Y
18 OSCILLATING AXLE OPERATES PROPERLY (EG CYLINDERS HOLD AND INTERLOCK VALVE OPERATES) IF FITTED	Y
19 AXLE EXTENSION AND INTERLOCKS OPERATE PROPERLY IF FITTED	Y
20 DRIVE BRAKES AND SLEW BRAKE OPERATE PROPERLY	Y
(CONTINUED NXT PAGE)	

ANNUAL MACHINE INSPECTION

GENERAL	
Y=YES N=NO C=CORRECTED N/A=NOT APPLICABLE	
21 VISUALLY CHECK ALL NUTS BOLTS, PINS, SHAFTS, SHIELDS, BEARINGS, WEAR PADS, LOCKING DEVICES, FOR PROPER INSTALLATION, TIGHTNESS, EXCESSIVE WEAR, CRACKS OR DISTORTION - ALL OK.	Y
22 INSTRUMENTS, SWITCHES, GAUGES, MOTION ALARM AND BEACON, HORN AND LIGHTS OPERATE PROPERLY	Y
23 VISUALLY CHECK SWITCHES AND CONTROLS SEALED ADEQUATELY	Y
24 CONDITION OF CONTROL ENCLOSURE AND PROTECTIVE BOOTS SERVICEABLE	Y
25 VISUALLY CHECK GENERAL STRUCTURAL CONDITION INCLUDING WELDS SHOWS NO DISCREPANCIES	Y
26 BATTERY CABLES ARE PROPERLY INSULATED, SECURED, SO THEY DO NOT RUB. TERMINALS TIGHT CLEAN AND TREATED.	Y
27 VISUALLY CHECK SWING BEARING BOLTS	Y
28 TEST 240 VOLT CABLE AND RCD FOR PROPER INSULATION AND FUNCTION - ALL OK (IF FITTED)	Y
29 CHECK SPECIAL OPTIONS FOR SAFE OPERATION	Y
30 DRIVE AND OPERATE UNIT TO TEST ALL SYSTEMS AND FUNCTIONS ALL OK	Y
31 WHEN ELEVATED ABOVE HORIZONTAL, AT MAXIMUM DRIVE SPEED THE UNIT TRAVELS LESS THAN 20 METRES PER MINUTE	Y
32 TILT LIGHT AND ALARM OPERATE	Y
33 CHECK BOOM CHAINS/CABLES FOR PROPER ADJUSTMENT	Y
34 CORRECT OPERATING AND SAFETY MANUAL IN STORAGE COMPARTMENT. UPDATE SIGN AND RECORD INSPECTION DATE IN EWPA LOG BOOK.	Y
35 CHECK SAFETY HARNESS' IF FITTED	Y
36 MACHINE IS FREE OF UNAUTHORISED MODIFICATIONS OR ADDITIONS.	Y
37 ALL APPLICABLE SERVICE BULLETINS COMPLETED.	Y

AS2550.10 – 1994 STATES THAT EACH ELEVATING WORK PLATFORM (EWP) SHALL BE SUBJECTED TO A MAJOR INSPECTION AFTER A MAXIMUM OF 10 YEARS SERVICE AND EVERY 5 YEARS THEREAFTER.

COMMENTS : Greased machine. Checked engine and associated components. Was serviced in April. Checked hydraulic system and hoses. Replaced hydraulic filter. Checked wheel bearing free play minor movement monitor. Checked outriggers and pads. Checked boom, all ok

THE UNDERSIGNED CERTIFIES THAT THIS MACHINE HAS BEEN THOROUGHLY INSPECTED ACCORDING TO THE OPERATING, SERVICE AND MAINTENANCE MANUALS PROCEDURES AND CRITERIA AND ALL DISCREPANCIES HAVE BEEN BROUGHT TO THE ATTENTION OF THE OWNER. OWNER ACKNOWLEDGES A RECEIPT OF A COPY OF THIS REPORT.

INSPECTOR SIGNATURE *RUSSELL JACKSON*

Stock No: TMP1	12m Trailer Mount Work Platform	Serial No: 04-39700	Reg No: S50SFV
----------------	---------------------------------	---------------------	----------------

Cat: TMP	Year: 2018	Provisional?:	Supplier: BPF	Model: NIFTY NL120TPE	Under Repair? <input checked="" type="checkbox"/>
----------	------------	---------------	---------------	-----------------------	---

Log

Date	Type	Description	Meter	Labour	Parts
25/07/2025	Repair	Job 13558 (Open). ACE Equipment carried out Annual Inspection			
16/07/2025	Inspection	Job 13394 (Open).			
14/07/2025	Inspection	Job 13362 (Open).			
8/07/2025	Inspection	Job 13297 (Open).			
29/05/2025	Inspection	Job 12647 (Open).			
28/05/2025	Inspection	Job 12542. Passed. Carried out inspection as per ewpa's maintenance and logbook. Filled out log book. Checked engine over all good. Tested limit switches and inspected boom segments / man basket,		\$86.00	
14/05/2025	Inspection	Job 12390 (Open).			
30/04/2025	Inspection	Job 12112. Passed.		\$45.00	
28/04/2025	Inspection	Job 12085 (Open).			
24/04/2025	Inspection	Job 12062 (Open).			
11/04/2025	Inspection	Job 11911 (Open).			
2/04/2025	Inspection	Job 11733 (Open).			
1/04/2025	Repair	Job 11709 (Open). Test and tagged Spark plug replaced Air filter gasket fitted 90days inspection carried out			
1/04/2025	Inspection	Job 11294. Passed.		\$22.50	
21/02/2025	Inspection	Job 11128 (Open).			
19/02/2025	Inspection	Job 11085 (Open).			
20/01/2025	Inspection	Job 10694 (Open).			
6/01/2025	Inspection	Job 10515 (Open).			
20/12/2024	Inspection	Job 10336. Passed.		\$33.75	
26/11/2024	Inspection	Job 10074. Passed. Carried out inspection Adjusted wheel bearings		\$43.00	
11/10/2024	Inspection	Job 9271. Passed. Inspection		\$33.75	

Stock No: TMP1		12m Trailer Mount Work Platform	Serial No: 04-39700		Reg No: S50SFV
24/09/2024	Inspection	Job 8865. Passed. Carried out inspection.	\$43.00		
		Tested all functions.			
10/09/2024	Inspection	Job 8614. Passed. Carried out pre hire inspection	\$43.00		
22/08/2024	Inspection	Job 8417. Passed.	\$45.00		
19/08/2024	OTHER	Next 90 day inspection - date postponed from 24-Jul-24			
16/08/2024	Inspection	Job 8362. Passed.	\$45.00		
18/07/2024	OTHER	Next Annual inspection - date postponed from 17-Oct-24			
18/07/2024	OTHER	Next Annual inspection - date postponed from 22-Sep-24			
17/07/2024	Repair	Job 8187. 2 hours, JLG carried out annual inspection, engine serviced, oil changed, hydraulic oil and filters changed	\$431.82		
24/05/2024	Inspection	Job 7083. Passed. Inspection	\$21.50		
21/05/2024	Repair	Job 7007. Transport latch replaced Safety lever free up Tested	\$75.25	\$62.50	
21/05/2024	Inspection	Job 6822. Passed.	\$32.25		
1/05/2024	Inspection	Job 6687. Passed. quick check for eye sky	\$15.00		
26/04/2024	Inspection	Job 6279. Passed. Emergency manual pump handle missing, new handle made up by Steve			
28/03/2024	Inspection	Job 6126. Passed. Carried out pre hire inspection	\$43.00		
25/03/2024	Inspection	Job 6046. Passed.	\$43.00		
20/03/2024	Repair	Job 6034. Transport latch replaced Tested	\$43.00	\$62.50	
20/03/2024	Inspection	Job 5918. Passed.	\$21.50		
12/03/2024	Inspection	Job 5896. Passed.	\$43.00		
14/02/2024	Inspection	Job 5511. Passed. Pre hire inspection done	\$21.00		
22/09/2023	Repair	Job 5129. JLG carried out annual inspection	\$288.50		

Stock No: TMP2		12m Trailer Mount Work Platform	Serial No: 2072017		Reg No: S72SHD	
18/01/2024	Repair	Job 5381. Wheel cylinders replaced at 487.8hrs Wheel bearings greased Hub seals replaced Motor electric choke control rod replaced Test and tagged Inspection carried out	\$252.00	\$336.92		
20/06/2023	Repair	Job 4889. 2 x new tyres fitted plus 1 x spare		\$978.69		
31/05/2023	Repair	Job 4952. 458 hours, JLG carried out annual inspection		\$404.50		
6/07/2022	Repair	Job 4078. JLG carried out annual inspection		\$389.00		
6/07/2022	Repair	Job 4070. Annual Inspection carried out JLG				
10/02/2022	Repair	Job 3761. 254.3 hrs Carried service on petrol engine Replaced engine oil	\$64.00	\$3.50		
11/11/2021	Repair	Carried out 90 day inspection Job 3545. 173.2 hrs Carried out 90 day inspection As per manual All tested (ok)	\$48.00			
15/07/2021	Repair	Job 3243. Annual Inspection		\$290.00		
30/09/2020	Repair	Job 2489. 90 day inspection				
15/07/2020	Repair	Job 2298. Fitted 2 x tow chains, fitted round trailer plug, fitted wheel chocks and holder	\$48.00	\$120.95		
6/07/2020	Repair	Job 2208. Stickers installed		\$350.00		
18/06/2020	Repair	Job 2488. Commissioning Date NEW				
			\$767.00	\$6,951.44		

Stock No: TMP2		12m Trailer Mount Work Platform		Serial No: 2072017		Reg No: S72SHD	
Cat: TMP	Year: 2019	Provisional?:	Supplier: Haulotte	Model: Haulotte HTA13P	Under Repair? <input checked="" type="checkbox"/>		

Log					
Date	Type	Description	Meter	Labour	Parts
25/07/2025	Repair	Job 13559 (Open). ACE Equipment carried out Annual Inspection			
14/05/2025	Inspection	Job 12389 (Open).			
3/04/2025	Repair	Job 11759. 90 days inspection carried out Generator service done		\$90.00	\$22.55
3/04/2025	Inspection	Job 10080. Passed.		\$22.50	
22/11/2024	Inspection	Job 10036 (Open).			
27/09/2024	Repair	Job 9025. Tow hitch channel slides replaced Hitch bolts tightened greased		\$90.00	\$220.09
27/09/2024	Inspection	Job 9026. Passed. Inspection		\$45.00	
18/07/2024	OTHER	Next Annual inspection - date postponed from 15-May-25			
18/07/2024	OTHER	Next 90 day inspection - date postponed from 15-Aug-24			
17/07/2024	Repair	Job 8184. 530 hours, JLG carried out annual inspection			\$484.46
29/05/2024	Repair	Job 7200. Hydraulic filter replaced at 536.8hrs Tested		\$43.00	\$172.50
27/05/2024	Repair	Job 6994. 530 hours, JLG replaced main gear pump			\$2,700.72
15/05/2024	Repair	Job 6993. 530 hours, JLG carried out Annual inspection,			\$477.56
28/03/2024	Inspection	Job 5653. Passed. 513.1hrs Carried out pre hire inspection		\$64.50	