



#### **DISCLAIMER: Second-Hand Plant Condition and Safety**

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

#### **Important Information**

##### **Condition of the Plant**

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

##### **Operational Safety Notice**

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

##### **Manufacturer Information and Records**

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

## Incoming Inspection Check

22/01/2025 / FN916183 / 370136 / Sydney / STR / Yes / Yes / Battery covered in corrosion and water level is low / 3 / No

Complete

Serial Number	FN916183 15 - REACH TRUCKS
Hour Meter Read	2550 hr
Service Job No.	370136
Location	Sydney
Conducted on	22/01/2025 1:05 PM ACDT
Conducted By	Terry Pinchin
Truck Category	STR
Function	
Full function Test & Safety Check	Pass
Truck due for service?	No
Appearance	
Condition of the Unit, Wheels, Paint	Fair

UNIT IN FAIR CONDITION NEEDS CLEAN AND PAINT TOUCH UP



Photo 1



Photo 2



Photo 3



Photo 4

Operation

Test & Tag valid? No

Has damage or repair work been identified? Yes

Refer to wear and tear

Was any wear & tear identified? Yes

Battery has corrosion over the top of it

(Internal) Parts required

Battery covered in corrosion and water level is low



Photo 5



Photo 6

(Internal) Est. Labour Requirements to repair (hrs) 3 hr

Maybe longer depends how deep the corrosion goes

Was any damage identified? No

## Media summary



Photo 1



Photo 2

22/01/2025 / FN916183 / 370136 / Sydney / STR / Yes / Yes / Battery covered in corrosion and water level is low / 3 / No

Private & confidential





Photo 3



Photo 4

22/01/2025 / FN916183 / 370136 / Sydney / STR / Yes / Yes / Battery covered in corrosion and water level is low / 3 / No

Private & confidential



Photo 5



Photo 6