



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report.

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly.

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

De-Hire Inspection Check

31/05/2025 / 383029 / Sydney / UE / Battery Electric / FN942337 /
Artemio Drio

Complete

Serial Number	FN942337
Hour Meter Read	2496 hr
Service Job No.	383029
Location	Sydney
Conducted on	31/05/2025 6:10 AM ACST
Conducted By	Artemio Drio

Truck Category

UE



Photo 1




Photo 2

Truck Make

Battery Electric

Equipment Exterior

General Appearance / Paintwork

WEAR & TEAR

Include Images of the Front, Rear & Sides of the Unit



Photo 3



Photo 4




Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13

Wheels/Tyres

Front Wheels / Tyres

OK



Photo 14



Photo 15

Rear Wheels / Tyres

OK



Photo 16

Wheel Bearings

N/A

Chassis/Structure

Overhead Guard

WEAR & TEAR

Rust on the LH opening . Frame slightly bent .



Photo 17



Photo 18




Photo 19

Chassis

WEAR & TEAR

Rust every where on the counter weight , front tire fender and platform .




Photo 20



Photo 21



Photo 22



Photo 23



Photo 24




Photo 25




Photo 26



Photo 27

Battery Cover

N/A

Driver Seat & Fixing

N/A

Not installed on the machine . Fabric tear .



Photo 28



Photo 29



Photo 30



Photo 31

Panels and Covers (Left & Right)

OK

Accessories (Mirrors, Blue Lights)

WEAR & TEAR

Missing mirror .



Photo 32

Windscreen

N/A


Rear Screen	N/A
Arm Rest	N/A
Connection Elements	OK
Drive Unit	
Transmission Operation Dead battery .	N/A
Transmission Noise & Leaks Dead battery .	N/A
Drive Motor Condition Dead battery .	N/A
	
Photo 33	
Brake	
Brake Function & Adjustment Dead battery .	N/A
Steering	
Steer Motor Operation/Noise Dead battery .	N/A
Steering Cylinder	N/A
Steer Axle	N/A
Steering Wheel/Controls Visual ok . Dead battery .	OK
Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings Dead battery .	N/A
Forks & Fork Carriage	OK



Photo 34



Photo 35

Lift Chains Free & Secondary

Visual condition ok . Dead battery .

OK



Photo 36



Photo 37

Hydraulic Cylinder Free Lift

OK



Photo 38

Hydraulic Cylinders Secondary Light Right & Left

OK



Photo 39

Hydraulic Hoses Conditions

OK



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44



Photo 45

Reach Carriage & Cylinder

N/A

Sideshift Carriage & Cylinder

N/A

Dead battery . . Visually ok .



Photo 46



Photo 47

Tilt Function & Cylinders

N/A

Dead battery . . Visually ok .




Photo 48



Photo 49

Hydraulic System

Valve Block

N/A

Dead battery . . Visually ok .

Pump Motor Operation

N/A



Photo 50

Pump Operation

N/A

Dead battery .

Hydraulic Function Levers

N/A

Missing lift label and non visible logo of tilt .



Photo 51

Electric System

Multi-pilot & Solo-pilot

N/A

Dead battery .

Strobe & Working Lights / Alarms

N/A

Dead battery .

Drive Display, Console & Instruments

N/A

Dead battery . . Visually ok .



Photo 52

Main Contactor & Connectors

N/A

Dead battery .

Charger Condition & Operation

N/A

No charger .

Battery

Battery Condition & Cables

N/A

Dead battery .



Photo 53

Battery Carriage

OK

Battery Lock System

N/A

Additions or Attachments

Any other related attachments

Yes

Attachment

Telescopic tines .



Photo 54



Photo 55



Photo 56

Condition

Dead battery .

N/A

Were any issues identified?

Dead battery . Bad paint , rust especially at counter weight , seat not installed and mirror is missing .

Wear & Tear

(Internal) Parts required - BE

- Painting
- Seat installation
- Seat fabric tear
- Mirror

Media summary

TRUCK TYPE ☐ NEW ☐ STR ☐ USED EQ. ☐ FOR REPAIR (CUST OWNED OR LTR UNDER CONTRACT)

UE check
383029
INCOMING CHECK DATE: **31-5-2025**
SERIAL NO.: **FN942337**
EQUIPMENT NO.: **127291**
CUSTOMER NAME: **Sydney**
CUSTOMER LOCATION: **Artemio**
CHECKED BY: **Artemio**

LABEL COLOUR CODE FOR ZONES:
WHITE = STOCK
RED = TO WORK ON / SERVICE WORK
GREEN = ORDER RECEIVED B/FOR WAITING FOR DELIVERY (ALLOCATED TO CUSTOMER INCLUDE CUSTOMER NAME)
YELLOW = DECISION ZONE (NO LABEL)

DUNGHEINRICH

Photo 1

CANNIBALISATION AUTHORITY

Date: _____

PARTS REQUIRED

Part Number	Description
51498052	SEAT RAILS

Requesting Branch: _____

Service Manager: _____

Unit No. _____

Model _____

Van No. **127291**

Technician **ECG**

Job No. **DCS1JH**

Date **19/12/24**

Notes **367307**

Unit No. _____

Model _____

Van No. **125386**

Technician **DCS1JH**

Job No. **367307**

Date **19/12/24**

Replacement Action _____

Order Number _____

Parts Order Date _____

Parts ETA _____

MANITOU TCM

Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24




Photo 25




Photo 26




Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32




Photo 33



Photo 34



Photo 35



Photo 36



Photo 37



Photo 38



Photo 39



Photo 40



Photo 41



Photo 42



Photo 43



Photo 44




Photo 45



Photo 46



Photo 47




Photo 48



Photo 49



Photo 50



Photo 51



Photo 52



Photo 53



Photo 54

