

DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant, was designed or manufactured:
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation
 manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers
 are encouraged to review this documentation thoroughly.

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

DUNGHEINRICH

De-Hire Inspection Check

31/05/2025 / Sydney / UE / Battery Electric / 91079011 / Larry Labayo

Serial Number	91079011
Hour Meter Read	5344 hr

Location Sydney

Conducted on 31/05/2025 7:44 AM ACST

Conducted By

Larry Labayo

Truck Category UE

Truck Make Battery Electric

Equipment Exterior

General Appearance / Paintwork WEAR & TEAR

Include Images of the Front, Rear & Sides of the Unit



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5

Complete

Wheels/Tyres		
Front Wheels / Tyres	ОК	
Rear Wheels / Tyres	ОК	
Wheel Bearings	ОК	
Chassis/Structure		
Overhead Guard	ОК	
Chassis	ОК	
Battery Cover	ОК	
Driver Seat & Fixing	ОК	
Panels and Covers (Left & Right)	ОК	
Accessories (Mirrors, Blue Lights)	ОК	
Windscreen	ОК	
Rear Screen	N/A	
Arm Rest	ОК	
Connection Elements	ОК	
Drive Unit		
Transmission Operation	ОК	
Transmission Noise & Leaks	ОК	
Drive Motor Condition	ОК	
Brake		
Brake Function & Adjustment	ОК	
Steering		
Steer Motor Operation/Noise	ОК	
Steering Cylinder	ОК	
Steer Axle	ОК	
Steering Wheel/Controls	ОК	

Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	ОК
Forks & Fork Carriage	ОК
Lift Chains Free & Secondary	ОК
Hydraulic Cylinder Free Lift	ОК
Hydraulic Cylinders Secondary Light Right & Left	ОК
Hydraulic Hoses Conditions	ОК
Reach Carriage & Cylinder	ОК
Sideshift Carriage & Cylinder	ОК
Tilt Function & Cylinders	ОК
Hydraulic System	
Valve Block	OK
Pump Motor Operation	OK
Pump Operation	ОК
Hydraulic Function Levers	ОК
Electric System	
Multi-pilot & Solo-pilot	ОК
Strobe & Working Lights / Alarms	ОК
Drive Display, Console & Instruments	ОК
Main Contactor & Connectors	ОК
Charger Condition & Operation There is no charger present at the time of inspection	N/A
Battery	
Battery Condition & Cables Battery flat	WEAR & TEAR
Battery Carriage	ОК
Battery Lock System	ОК

Any other related attachments No Were any issues identified? (Internal) Parts required - BE Battery flat. May need new one. Recommended to regen battery then check S.G.

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5