



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

De-Hire Inspection Check

31/05/2025 / 383040 / Sydney / UE / Battery Electric / FN952028 /
Eduardo Morillo

Complete

Serial Number

FN952028



Photo 1



Photo 2




Photo 3

Hour Meter Read

422 hr

Service Job No.

383040

Location

Sydney

Conducted on

31/05/2025 7:55 AM ACST

UE Inspection

Conducted By

Eduardo Morillo

Truck Category

UE



Photo 4



Photo 5




Photo 6



Photo 7

Truck Make

Battery Electric



Photo 8

Equipment Exterior

General Appearance / Paintwork

WEAR & TEAR



Photo 9

Include Images of the Front, Rear & Sides of the Unit



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14

Wheels/Tyres

Front Wheels / Tyres

OK



Photo 15



Photo 16




Photo 17

Rear Wheels / Tyres

OK

Wheel Bearings

OK



Photo 18



Photo 19

Chassis/Structure

Overhead Guard

N/A

Chassis

OK

Battery Cover

OK



Photo 20

Driver Seat & Fixing

N/A

Panels and Covers (Left & Right)

OK



Photo 21



Photo 22

Accessories (Mirrors, Blue Lights)

N/A

Windscreen

N/A

Rear Screen

N/A

Arm Rest

N/A

Connection Elements

N/A

Drive Unit

Transmission Operation

OK

Transmission Noise & Leaks

OK

Drive Motor Condition

OK

Brake

Brake Function & Adjustment

OK

Steering

Steer Motor Operation/Noise

N/A

Steering Cylinder	N/A
Steer Axle	N/A
Steering Wheel/Controls	N/A
Hoist Frame/Load Lifting Device	
Mast To Full Height & Bearings	OK
Forks & Fork Carriage	OK
	
Photo 23	
Lift Chains Free & Secondary	N/A
Hydraulic Cylinder Free Lift	N/A
Hydraulic Cylinders Secondary Light Right & Left	N/A
Hydraulic Hoses Conditions	OK
Reach Carriage & Cylinder	N/A
Sideshift Carriage & Cylinder	N/A
Tilt Function & Cylinders	N/A
Hydraulic System	
Valve Block	OK
Pump Motor Operation	OK
Pump Operation	OK
Hydraulic Function Levers	OK



Photo 24

Electric System

Multi-pilot & Solo-pilot

N/A

Strobe & Working Lights / Alarms

N/A

Drive Display, Console & Instruments

OK

Main Contactor & Connectors

OK

Charger Condition & Operation

OK

Battery

Battery Condition & Cables

OK



Photo 25

Battery Carriage

OK

On board

Battery Lock System

N/A

Additions or Attachments

Any other related attachments

No

Were any issues identified?

No Issues Identified

Media summary



Photo 1



Photo 2



Photo 3



Photo 4



Photo 5



Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15




Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25