

#### DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

#### Important Information

#### Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

#### Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

#### Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant, was designed or manufactured:
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation
  manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers
  are encouraged to review this documentation thoroughly.

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich

# **De-Hire Inspection Check**

30/05/2025 / 382974 / Sydney / STR / Yes / Yes / Load wheels. Clean battery terminals / 4 / Yes / Bonnet repair or replace. Sticker. 51287248 / 3 / 90469376 / Terrence Pinchin

51287248737904693767 Terrence Pinchin	Complete
Serial Number	90469376
Hour Meter Read	4722 hr
Service Job No.	382974
Location	Sydney
Conducted on	30/05/2025 1:17 PM ACST
Conducted By	Terrence Pinchin
Truck Category	STR
Function	
Full function Test & Safety Check No drive	Pass
Truck due for service?	No
Appearance	
Condition of the Unit, Wheels, Paint	Poor

Unit in poor condition paint damage wheels replacing battery has corrosion on terminals







Photo 2



Photo 3



### Operation

Test & Tag valid? No Has damage or repair work been identified? Yes

REFER to wear and tear and customer damage

## Was any wear & tear identified?

Yes

Load wheels need replacing Battery has corrosion on some terminals HAS paint damage







### (Internal) Parts required

Load wheels. Clean battery terminals

## (Internal) Est. Labour Requirements to repair (hrs)

4 hr

Yes

## Was any damage identified?



Photo 7



Photo 8



Photo 9

## (External) Parts Required

30/05/2025 / 382974 / Sydney / STR / Yes / Yes / Load wheels. 50307456 x 4 Clean battery terminals / 4 / Yes / Bonnet repair or replace. 51010275 Sticker. 51287248 / 3 / 90469376 / Terrence Pinchin

2/9 Private & confidential

#### Bonnet repair or replace. 51010275 Sticker. 51287248







Photo 11

Private & confidential

3/9

## Media summary




Photo 1



Photo 2

Private & confidential 4/9



Photo 3



Photo 4

Private & confidential 5/9




Photo 5




Photo 6

Private & confidential 6/9



Photo 7




Photo 8

Private & confidential 7/9



Photo 9



Photo 10

Private & confidential 8/9




Photo 11

Private & confidential 9/9