



DISCLAIMER: Second-Hand Plant Condition and Safety

This document is Jungheinrich Australia Pty Ltd's (Jungheinrich) official notice that the second-hand plant offered for sale through this auction may contain faults or deficiencies that could pose risks to health and safety.

Important Information

Condition of the Plant

Given the plant is second-hand, please be aware it may include wear and tear, or be missing safety features that were not present or required at the time of original manufacture.

Jungheinrich has taken all reasonably practicable steps to identify any faults in the plant. The enclosed Condition Report sets out the current condition of this plant, including any identified faults.

Identified specific faults are included in the supplied condition report

Operational Safety Notice

It is the responsibility of the purchaser to ensure that the plant is inspected, serviced, and, if necessary, modified to meet current safety standards before use. The plant should not be used until all identified faults have been rectified and the equipment is deemed safe for operation.

Manufacturer Information and Records

Any available records, including:

- information concerning each purpose for which the plant was designed or manufactured;
- information concerning any conditions necessary to ensure that the plant is without risks to health and safety when used for the purposes for which it was designed or manufactured or when carrying out any activity; and
- calculations, analysis or testing records, including data sheets, test certificates, operation manuals, service reports, and safety manuals or guides are enclosed with the plant. Purchasers are encouraged to review this documentation thoroughly

By participating in this auction and purchasing the second-hand plant, the purchaser acknowledges receipt of this notice and accepts full responsibility for ensuring the plant is safe for use.

For any questions please contact Jungheinrich



De-Hire Inspection Check

31/05/2025 / 383037 / Sydney / UE / Battery Electric / FN549047 /
Eduardo Morillo

Complete

Serial Number FN549047



Photo 1

Hour Meter Read 5265 hr



Photo 2

Service Job No. 383037

Location Sydney

Conducted on 31/05/2025 6:15 AM ACST
UE Inspection

Conducted By Eduardo Morillo

Truck Category UE



Photo 3



Photo 4



Photo 5




Photo 6



Photo 7



Photo 8



Photo 9

Truck Make

Battery Electric



Photo 10



Photo 11

Equipment Exterior

General Appearance / Paintwork

WEAR & TEAR



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17

Include Images of the Front, Rear & Sides of the Unit



Photo 18



Photo 19



Photo 20

Wheels/Tyres

Front Wheels / Tyres

WEAR & TEAR



Photo 21



Photo 22

Rear Wheels / Tyres

WEAR & TEAR



Photo 23



Photo 24




Photo 25



Photo 26

Wheel Bearings

WEAR & TEAR

Chassis/Structure

Overhead Guard

OK




Photo 27



Photo 28



Photo 29



Photo 30

Chassis

OK

Battery Cover	OK
Driver Seat & Fixing	OK
Panels and Covers (Left & Right)	OK
Accessories (Mirrors, Blue Lights)	OK
Windscreen	N/A
Rear Screen	N/A
Arm Rest	OK
Connection Elements	OK
Drive Unit	
Transmission Operation	OK
Transmission Noise & Leaks	OK
Drive Motor Condition	OK
Brake	
Brake Function & Adjustment	OK
Steering	
Steer Motor Operation/Noise	OK
Steering Cylinder	OK
  Photo 31 Photo 32	
Steer Axle	OK
Steering Wheel/Controls	OK



Photo 33

Hoist Frame/Load Lifting Device

Mast To Full Height & Bearings

OK



Photo 34




Photo 35



Photo 36




Photo 37

Forks & Fork Carriage

OK



Photo 38



Photo 39



Photo 40

Lift Chains Free & Secondary

OK



Photo 41




Photo 42

Hydraulic Cylinder Free Lift

OK



Photo 43



Photo 44



Photo 45

Hydraulic Cylinders Secondary Light Right & Left

OK



Photo 46



Photo 47



Photo 48

Hydraulic Hoses Conditions

OK



Photo 49




Photo 50

Reach Carriage & Cylinder

OK

Sideshift Carriage & Cylinder

OK



Photo 51



Photo 52



Photo 53



Photo 54

Tilt Function & Cylinders

OK

Hydraulic System

Valve Block

OK

Pump Motor Operation

OK

Pump Operation

OK

Hydraulic Function Levers

OK



Photo 55

Electric System

Multi-pilot & Solo-pilot

OK

Strobe & Working Lights / Alarms

OK

Drive Display, Console & Instruments

OK

Main Contactor & Connectors	OK
Charger Condition & Operation	WEAR & TEAR
Battery	
Battery Condition & Cables	OK
1- Battery charger not working.	
Battery Carriage	N/A
Battery Lock System	OK
Additions or Attachments	
Any other related attachments	No
Were any issues identified?	Wear & Tear
(Internal) Parts required - BE	
2 Rear Tyres 18-7-8	
	
Photo 56	

Media summary



Photo 1




Photo 2



Photo 3



Photo 4



Photo 5




Photo 6



Photo 7



Photo 8



Photo 9



Photo 10



Photo 11



Photo 12



Photo 13



Photo 14



Photo 15



Photo 16



Photo 17



Photo 18



Photo 19



Photo 20



Photo 21



Photo 22



Photo 23



Photo 24



Photo 25



Photo 26



Photo 27



Photo 28



Photo 29



Photo 30



Photo 31



Photo 32



Photo 33



Photo 34




Photo 35



Photo 36




Photo 37



Photo 38



Photo 39



Photo 40



Photo 41




Photo 42



Photo 43



Photo 44




Photo 45



Photo 46



Photo 47



Photo 48




Photo 49



Photo 50



Photo 51




Photo 52



Photo 53



Photo 54



Photo 55



Photo 56