

Coates Hire Pre Divestment Inspection Checklist

Tools & Equipment (Electric, Pneumatic, Hydraulic or Internal Combustion)

Name ANTOINE WONG Branch MILWAUKEE
Description 6X4 TRAILER Asset # 1154858 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate information in this section ***

Type of Tool: TRAILER CRANE
Make/ Model: TRIK TRAILERS Engine/Motor - Make/Model: N/A
Year: 2015 Engine Serial Number: N/A
Serial Number: 6JCTR1KBXFM00 Meter Reading: N/A
6587

Comments:

Features:

List features or options for the machine:

Comments:

Machine Type:

Frame Mount ☐

AC / DC Range

Engine Horsepower

Auxiliary Power

Leads Length

Trailer Mount ☒

Overall Appearance:

Switches/cords ☐ Good ☒ Fair ☒ Poor ☒
Sheet metal/Fiberglass Condition ☐ ☒ ☒
Paint ☐ ☒ ☒
Fit for Designed Purpose ☒ ☒ ☒

Comments:

Control Station

Operator Controls ☐ Yes ☐ No ☒ Operates ☒ N/A
Gauges Operational? ☐ ☐ ☒
Safety Devices ☐ ☐ ☒

Comments:

Engine or Electric Motor:

Power: Diesel ☐ Petrol ☐ Hydraulic ☐ Electric ☐ Air ☐
Does it start? ☐ Yes ☐ No ☒ NA
Did it need to be jumped? ☐ ☐ ☒ NA
Acceptable Power ☐ ☐ ☒ NA
Unusual Noises ☐ ☐ ☒ NA

Comments:

Hydraulics

Operates ☐ Yes ☐ No ☒ N/A Leaks ☐ Yes ☐ No ☒ N/A
Pump ☐ ☐ ☒ ☐ ☐ ☒ NA
Hoses ☐ ☐ ☒ ☐ ☐ ☒ NA
Cylinders ☐ ☐ ☒ ☐ ☐ ☒ NA
Drive Motors ☐ ☐ ☒ ☐ ☐ ☒ NA
Brakes ☐ ☐ ☒ ☐ ☐ ☒ NA
Parking Brakes ☐ ☐ ☒ ☐ ☐ ☒ NA

Comments:

Wiring & Lights

Damaged? ☐ Yes ☐ No ☒ ☒
Wiring ☒ ☐
Lights ☒ ☐

Comments:

Chassis:

Frame Condition ☐ Good ☒ Fair ☐ Poor ☐ Inoper ☐ Missing ☐ N/A
Handles Condition ☐ ☒ ☐ ☐ ☐ ☒
Lift Points Condition ☐ ☒ ☐ ☐ ☐ ☒
Guards Condition ☐ ☒ ☐ ☐ ☐ ☒
Mounting Points ☐ ☒ ☐ ☐ ☐ ☒
Winching Cable ☐ ☒ ☐ ☐ ☐ ☒

Comments:

Tyre Condition:

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- <u>LUHE</u>	Brand- <u>LUHE</u>	Brand- <u>LUHE</u>	Brand- <u>LUHE</u>
Size- <u>185R-14LT</u>	Size- <u>185R-14LT</u>	Size- <u>185R-14LT</u>	Size- <u>185R-14LT</u>
Condition- <u>FAIR</u>	Condition- <u>FAIR</u>	Condition- <u>FAIR</u>	Condition- <u>FAIR</u>