

W/O No	Asset No	Description	Asset Description	Status	Finished Date	Duration	Job Type	Department
12075	MS91	6M SERVICE (LIGHT TRAILER) . 09.12.2023_MWR_SP - CONDUCT INSPECTION AS PER CHECK LIST. (SM)	TEAGLE TOMAHAWK T8500SC TRAILED BALE PROCESSOR	Completed	9/12/2023	2	PM	Workshop Mbh
10409	MS91	Connect to MS70 and commission/test operation. 12.04.2023_MWR_SP/SC - Attached shackles for break away chains. Connected to MS70 and ran up and function test all functions ready for site. (SM)	TEAGLE TOMAHAWK T8500SC TRAILED BALE PROCESSOR	Completed	12/04/2023	3	Repairs	Daunia
10408	MS91	Needs 2x Hooks welded on top rear of Hay Blower. Note: There is one existing hook, needs a couple more for holding up bail netting. 12.04.2023_MWR_SC/SP - Welded hooks to rear gate. (SM)	TEAGLE TOMAHAWK T8500SC TRAILED BALE PROCESSOR	Completed	12/04/2023	1.5	Repairs	Daunia
10325	MS91	Onboarding Inspection & Service. 12.04.2023_MWR_SC/SP - Drained and refilled drop box for pto. Removed oil cooler as it was leaking from cooler fins/ re directed hyd hoses to by pass cooler. (SM) 31.03.2023_MWR_SP - Repairs made to undercarriage, repaired cracks in floor and strengthened with 30x30x3 shs to stop tray falling out when in operation. Fit call sign stickers. Tidied up wiring underneath to avoid damage. Removed old hi-vis striping. (SM) 29.03.2023_MWR_SP - Fit lights and wiring harness to mulcher. Fit reflective tape. Repack wheel bearings and refit wheels. Fit safety chains. (SM) 28.02.2023_MWR_SC/SP - Conduct site compliance work scope to ms 91. Fabricate and fit wheel choke holders Fabricate and fit light mounts. Inspect wheel bearings and suspension. (SM) 28.03.2023_MWR_SC - Inspect and report on machine. (SM) 28.03.2023_Ordered 3x ID stickers from Create a Sign. (SM)	TEAGLE TOMAHAWK T8500SC TRAILED BALE PROCESSOR	Completed	12/04/2023	18	Service	Daunia