

CARHISTORY.COM.AU DEALER REPORT INCLUDING A PPSR SEARCH






VEHICLE DESCRIPTION - JM0BP2S7A01104545

VIN	:	Jm0bp2s7a01104545
Make	:	MAZDA
Model	:	MAZDA3
Variant / Series	:	G20 PURE/ BP
Body	:	4D SEDAN
Year (first retail date)	:	2019
Colour	:	
- Primary		BLACK
- Secondary		



*Picture provided is a sample only

REPORT SUMMARY

-  No odometer history reported
-  No Encumbrances reported
-  Written-Off Status reported
-  No Stolen Status recorded
-  Insurance Claims not available

IDENTIFICATION

Engine Number	:	PE21319985
Plate	:	
Registered State	:	VIC

VEHICLE STATUS

Last Odometer Reading	:	28118
Last Sale Listing	:	
Rego. Expiry Date	:	
Warranty Expiry Date	:	

VEHICLE RATINGS

ANCAP Safety Rating	:	
Air Pollution Rating	:	
Greenhouse Rating	:	
Overall Green Rating	:	

VEHICLE DETAILS

Fuel Type	:	UNLEADED PETROL
Engine Size	:	2.0L
Cylinders/Rotors	:	4
Fuel Consumption	:	
Transmission	:	6 SP AUTOMATIC
Power (KW)	:	114
Torque (Nm)	:	200


FIRST SALE DATA

First Sale Date	:	25-06-2019
First Sold in Postcode	:	3029
First Buyer Type	:	PRIVATE

REPORTED ODOMETER HISTORY

 No odometer history reported

Kilometers	Date Reported	Notes
28118	01/08/2022	



REPORTED SALES LISTING

The below is a list of known sales listings for your vehicle

Price	Date Reported	Where
-------	---------------	-------

REPORTED INSURANCE CLAIMS

 Insurance Claims Not Available

FINANCE CHECK

 No Encumbrances reported

PPSR has reported that this vehicle has no encumbrances

Encumbrance: NO

VEHICLE HISTORY

Written-Off Status

Written-off: Impact | Passenger front | Heavy panel
Impact | Passenger rear | Heavy panel
Impact | Passenger side | Heavy panel
Impact | Floor pan (passenger front) | Light structural
Impact | Airbag side | Major mechanical damage
Impact | Airbag curtain | Major mechanical damage
Impact | Seat belt pre-tensioner | Major mechanical damage

Date recorded: 07 Feb 2022

State recorded: QLD

Type: Inspected

Written-off: Impact | Passenger front | Heavy panel
Impact | Passenger rear | Heavy panel
Impact | Passenger side | Heavy panel
Impact | Floor pan (passenger front) | Light structural
Impact | Airbag side | Unrepairable
Impact | Airbag curtain | Unrepairable

Impact | Seat belt pre-tensioner | Unrepairable

Date recorded: 29 Jun 2021

State recorded: VIC

Type: Repairable Write-off

Stolen Status NO STOLEN STATUS RECORDED ON THIS VEHICLE

CERTIFICATE NUMBER (VCN)

For any individual to be able to access this report, simply provide them with the following link or Certificate Number (VCN).

URL Link: <https://secure.carhistory.com.au/VCN.aspx?VCN=A6-NKGH>

VCN:A6-NKGH



01-08-2022

Serial Number Search Certificate

This is a serial number search certificate for a serial number search

This search certificate is provided under section 174 of the *Personal Property Securities Act 2009*

Search certificate number: 5837733484560001
Search number: 583773348456

This search certificate reflects the data contained in the PPSR as 01-08-2022 13:04:01 (Canberra Time)

Search Criteria Details

Serial number search type: VIN
Motor vehicle: Jm0bp2s7a01104545
PPSR Registration state searched: Current

PPSR Registration Details

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

Additional Motor Vehicle Details - NEVDIS

Identifier number:	Jm0bp2s7a01104545	Identifier type:	VIN
Vehicle type:	CAR / SMALL PASSENGER VEHICLE	Make:	MAZDA
Body type:	CAR/SEDAN	Model:	3
Colour:	BLACK	Engine number:	PE21319985
Registration plate number:	No data recorded.	State vehicle registered:	VIC
Registration expiry:	No data recorded.	Year/Month of compliance:	2019-05
Year of manufacture:	2019		

NEVDIS Written off Vehicle Notification:

QLD, 07 Feb 2022, Inspected

- I01A [Impact | Passenger front | Heavy panel]
- I05A [Impact | Passenger rear | Heavy panel]
- I06A [Impact | Passenger side | Heavy panel]
- I15D [Impact | Floor pan (passenger front) | Light structural]
- I39F [Impact | Airbag side | Major mechanical damage]
- I40F [Impact | Airbag curtain | Major mechanical damage]
- I41F [Impact | Seat belt pre-tensioner | Major mechanical damage]

VIC, 29 Jun 2021, Repairable Write-off

- I01A [Impact | Passenger front | Heavy panel]
- I05A [Impact | Passenger rear | Heavy panel]
- I06A [Impact | Passenger side | Heavy panel]
- I15D [Impact | Floor pan (passenger front) | Light structural]
- I39E [Impact | Airbag side | Unrepairable]
- I40E [Impact | Airbag curtain | Unrepairable]
- I41E [Impact | Seat belt pre-tensioner | Unrepairable]

NEVDIS Stolen Vehicle Notification:

- Not recorded as stolen.

Tasmanian stolen vehicle information is currently unavailable from this service. For information about the status of Tasmanian vehicles, go to: <https://www.transport.tas.gov.au/MRSWebInterface/public/regoLookup/registrationLookup.jsf> (Note: you will need to provide the vehicle registration plate number to search this site)

A stolen vehicle notification, or the absence of one, does not necessarily mean a vehicle is or is not stolen.

If there is a stolen vehicle notification you wish to enquire about, you should contact the police force in the State or Territory indicated immediately after the date in the notification. The reference number at the end of the notification should be quoted as a part of your enquiry.

Please note that there may be multiple stolen notifications shown. A stolen notification can be for a VIN, Plate, Chassis and/or Engine.

Vehicle information is requested from Austroads NEVDIS database for each transaction involving a vehicle VIN or Chassis Number on the PPSR. The data is not part of interests registered on the PPSR and it is presented without any guarantee regarding its accuracy.

The NEVDIS data is intended to assist users with checking that the VIN or Chassis Number they entered, along with information they have about the vehicle from other sources, is accurate and to provide users with any data held on NEVDIS about a vehicle's stolen or written off status.

State and territory road agencies are the source of NEVDIS data and the primary point of contact for enquiries, errors and corrections.

Access to and use of data provided through the PPSR is subject to the PPSR General Conditions of Use and applicable third party data conditions (which can be obtained at www.ppsr.gov.au). To the extent permitted by law, all data provided through the PPSR is made available without any representation or warranty of any kind (without limitation in respect to accuracy) and the Commonwealth, and our third party data providers (which includes any person mentioned in the Third Party Data Conditions as providing information through the PPSR), have no liability to you in respect of any loss or damage that you might suffer no matter how arising (including negligence) that is directly or indirectly related to the NEVDIS Data.

How to verify this certificate on the PPSR

You can use the search number from an original search (as shown on this certificate) to retrieve the original search results and to issue a copy of the search certificate at <https://transact.ppsr.gov.au/ppsr/Home>. There is no fee, however this process will not provide any update to the information in the original search.

Privacy and Terms and Conditions

The Australian Financial Security Authority is subject to the [Privacy Act 1988](#) which requires that we comply with the Australian Privacy Principles (APPs) set out in the Act. The APPs set out how Australian Government agencies should collect, use, store and disclose personal information and how individuals can access records containing their personal information.

Access to and use of the PPSR is subject to the General Conditions of Use, as well as other relevant terms and conditions. All relevant terms and conditions can be found at www.ppsr.gov.au

End of search certificate

EMAIL: enquiries@ppsr.gov.au WEBSITE: www.ppsr.gov.au

GPO Box 1944 Adelaide SA 5001 1300 00 77 77

TERMS AND DEFINITIONS

Terminology	Definition
Air Pollution Rating	The Air Pollution Rating is based on the level of air pollutant emissions allowable under the standard to which the particular vehicle has been successfully tested to for supply to the Australian market.
ANCAP Safety Rating	The Australasian New Car Assessment Program (ANCAP) gives consumers consistent information on the level of occupant protection provided by vehicles in serious front and side crashes. The score is a star rating, between 1 to 5 stars. The higher scores are awarded more stars.
Body	A vehicle's body type.
Cylinders/Rotors	Engine cylinder configuration.
Dealer Price	An indicative vehicle value for non-franchise dealer trade or wholesale transactions. Trade low must be adjusted for (Back 10 Years) kilometres and condition. Please refer to the 'Guide Condition' definition.
Dealer Trade Price	A median value achieved by a franchise dealer, e.g. Ford dealer would achieve for a Ford, (Back 10Years) for a vehicle in 'Guide Condition' and average kilometres. Please refer to the 'Guide Condition'.
Encumbrance reported	Vehicle has an outstanding finance. Ensure finance is cleared prior to purchase of vehicle.
Fuel Consumption	Vehicle fuel consumption.
Fuel Type	Recommended fuel type.
Make	Manufacturers name.
Model	Vehicle family.
No Registrations Found (PPSR Certificate)	Means that there is no encumbrance registered on the PPSR for that serial number.
Odometer Discrepancy Reported	The vehicle has odometer-related problems. These may include discrepancies such as not actual miles, a broken odometer, a mileage discrepancy, or suspect miles.
Overall Green Rating	The Overall Rating is based on the sum of the air pollution and greenhouse ratings.
Personal Price	The median price paid for a vehicle when purchased through a private transaction.
Plate	Vehicle Registration No.
Purpose of use	Type of use as registered with State Registration Offices.
Refer jurisdiction	Contact the registration authority displayed in the 'state of registration'.
Registered State	State of vehicle registration.
Registration Found (PPSR Certificate)	Means that there are encumbrances registered on the PPSR for that serial number.
Sales Listings	Sales listing data displays sales advertisements derived from various vehicle eCommerce sites.
Series Name	Series Name, Eg. VZ, VE, MY05, MY08.
Variant Name	Variant Name, Eg. GL, CSi, SPORTIVO, SS, Executive.
Vehicle Identification Number (VIN)	A unique alphanumeric combination of 17 characters assigned to a vehicle. It does not contain the letters I, O or Q.
Year (first retail date)	Is the first year the vehicle was sold and may or may not be the year in which the vehicle was manufactured.

GENERAL DISCLAIMERS

Glass's	Glass's Information Services has exercised all reasonable care and skill in producing this information. Glass's Information Services gathers its information from independent sources within the motor trade, unconnected with it, and as a result can accept no responsibility for the accuracy or completeness of information. Furthermore, information on valuations supplied are intended as a guide only to current market value; they can not be considered in any way a substitute for a full and detailed
---------	---

GENERAL DISCLAIMERS

inspection of any vehicle.

Insurance Claim Information

Equifax's Auto service gathers its Insurance Claim information from independent sources within the insurance industry and as a result can accept no responsibility for the accuracy or completeness of information.

General

This report is supplied on the Terms set out on the Auto website and accepted by you before you purchased this report.

No odometer discrepancies reported

Equifax's Auto service gathers odometer history from independent third party sources within the automotive industry and as a result can accept no responsibility for the accuracy or completeness of information. Equifax's Auto service recommends you review the vehicle's log books and service history in conjunction with the CarHistory report to determine the accuracy of the vehicle's odometer reading.