

Authorised Inspection Station e-Safety Check Report



This inspection report shows if the vehicle has passed a NSW Safety Check. It is not a comprehensive report on the vehicle's mechanical condition. Once passed the report is valid for 6 months. However, for the purpose of selling the vehicle the report must not be older than 42 days. For more information contact Transport for NSW on 13 22 13 or visit rms.nsw.gov.au

e-Safety Check number: AS8237348

Inspection date: 25/02/2025

e-Safety Check status: Pass

Amount paid: 49.00

Inspection station:

Number: A52112

Vehicle details:

Name: Cromer Motors Pty Ltd
Address: 36 Orlando Road
CROMER , NSW 2099

Number plate: CP03JO

Class: Light Vehicle

Make: HINO

Model: 300 SER 2 C/CAB WIDE
1

Reason for inspection: Registration Renewal

Odometer reading: 185119

Comment:

Compliance date: 6 /2014

Examiner's certification:

I certify that the report is a true record of the vehicle's compliance with the inspection standards of the Rules for Authorised Inspection Stations at the time of inspection.

Examiner's signature:

Examiner's number:

A22498

— S/N 00719 —

— S/N 00719 —

Brake-Testa

Date 25 Feb 25 09:57
Next Cal Due 14 Feb 24
Examiner A22498

Rego CP03JO

PASS

Newton's Max=400 (Pk=150)
Decel Max = 127 %g
Avge Decel = 99 %g
Duration 1.2 sec
Est. Speed = 43 km/h
Light Veh, Serv Brake

Signature:

Circuitlink Int. P/L

— S/N 00719 —

Renewing registration is easy. Go to myRTA.com
requirements


Registration renewal payment options



Complete renewal requirements then:




Visit myRTA.com or call 1300 360 782 to obtain
BPAY details.



Internet payments: Visit myRTA.com to pay using a
valid credit card.



Telephone payments: Phone 1300 360 782 to pay
using a valid credit card.



In person: At your nearest registry.