

Coates Hire Pre Divestment Inspection Checklist

Scissor Lift (Electric or Internal Combustion)

Description SCISSOR Asset # 5191803 Service Job # _____

Note that this internal checklist is merely a physical and not structural inspection of the machine with disclosure of any known issues at the time to assist in making a commercial decision on the viability of that item. At the discretion of Coates Hire, this report may be available to potential buyers. It is the buyer's or bidder's sole responsibility to further assess and repair the item and ensure its compliance with all relevant legislation before being used and to ensure that it is maintained in a fully operational, safe and serviceable condition.

General Information: *** Copy Data Plate information in this section ***

Make/ Model SKYJACK SJ3219 Engine/Motor - Make/Model _____
 Year 2014 Engine Serial Number _____
 Serial Number 22069435 Meter Reading 144

Comments: _____

Features:

Max Lift Height 5.7
 Drive System 2WD 4WD Platform size (L x W) _____
 Platform Extension Yes No Battery Charger Yes No
 AC Chord to Platform Generator
 Air to Platform Outriggers
 Non-marking Tyres

Overall Appearance:

Control Station/Operator Station Good Fair Poor Comments: _____
 Sheet metal/Fiberglass Condition Good Fair Poor
 Paint Good Fair Poor

Control Station

Operates Yes No N/A Comments: _____
 Operator Controls: Platform Yes No N/A
 Operator Controls: Ground Yes No N/A
 Gauges Operational? Yes No N/A

Engine or Electric Motor:

Power: Diesel Gas Dual Fuel Electric
 Does it start? Yes No Comments: _____
 Did it need to be jumped? Yes No
 Acceptable Power Yes No
 Unusual Noises Yes No

Hydraulics

Operates Yes No N/A Leaks Yes No N/A Comments: _____
 Pump Yes No N/A Yes No
 Hoses Yes No N/A Yes No
 Cylinders Yes No N/A Yes No
 Drive Motors Yes No N/A Yes No
 Brakes Yes No N/A Yes No
 Parking Brakes Yes No N/A Yes No

Chassis:

Frame Condition Good Fair Poor Inoper Missing N/A Comments: _____
 Scissor Linkage Good Fair Poor Inoper Missing N/A
 Steering Linkage Good Fair Poor Inoper Missing N/A
 Work Platform Condition Good Fair Poor Inoper Missing N/A
 Outriggers and Pads Condition Good Fair Poor Inoper Missing N/A

Tyre Condition:

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- <u>U/S</u>	Brand- <u>U/S</u>	Brand- <u>U/S</u>	Brand- <u>U/S</u>
Size- <u>U/S</u>	Size- <u>U/S</u>	Size- <u>U/S</u>	Size- <u>U/S</u>
Condition- _____	Condition- _____	Condition- _____	Condition- _____

Any other known issues, faults:

