

Coates Hire Pre Divestment Inspection Checklist

Scissor Lift (Electric or Internal Combustion)

Name PULL Branch DNDG
 Description SCISSOR LIFT Asset # 532373 Service Job # _____

This checklist is a record of a visual inspection which identifies defects reasonably known to Coates at the time. It should only be used as a guide. The buyer should rely on their own inspection and assessment of the equipment. The equipment is used and sold as is. Coates does not warrant that the equipment is new, fit for purpose, of merchantable quality, free from defects in materials and workmanship, or complies with all relevant laws, Australian Standards, licence or permit requirements. Nothing herein shall limit those provisions of the Competition and Consumer Act 2010, nor statutes, rules or regulations from time to time in force in Australia which imply certain conditions or warranties or impose obligations on Coates which conditions, warranties and obligations cannot, or cannot to a limited extent be excluded, restricted or modified. The Coates Hire Used Equipment Terms and Conditions of Sale apply to the sale of all used equipment and this checklist should be read in conjunction with these terms which are available upon request or at www.coateshire.com.au.

General Information: *** Copy Data Plate Information in this section ***

Make/Model SKYSAK 321 Engine/Motor - Make/Model _____
 Year 2015 Engine Serial Number _____
 Serial Number 70020600 Meter Reading 345

Comments: _____

Features:

Max Lift Height _____
 Drive System 2WD 4WD Platform size (L x W) _____
 Platform Extension Yes No
 AC Chord to Platform
 Air to Platform
 Battery Charger Yes No
 Generator
 Outriggers
 Non-marking Tyres

Overall Appearance:

Control Station/Operator Station Good Fair Poor
 Sheet metal/Fiberglass Condition
 Paint

Control Station

Operates Yes No N/A
 Operator Controls: Platform
 Operator Controls: Ground
 Gauges Operational?

Engine or Electric Motor:

Power: Diesel Gas Dual Fuel Electric

Does it start? Yes No
 Did it need to be jumped?
 Acceptable Power
 Unusual Noises

Comments: SLOW TO DRIVE

Hydraulics

Operates Yes No N/A
 Leaks Yes No
 Pump
 Hoses
 Cylinders
 Drive Motors
 Brakes
 Parking Brakes

Chassis:

Good Fair Poor Inoper Missing N/A Comments:
 Frame Condition
 Scissor Linkage
 Steering Linkage
 Work Platform Condition
 Outriggers and Pads Condition

Tyre Condition:

Left - Front	Left - Rear	Right - Front	Right - Rear
Brand- _____	Brand- _____	Brand- _____	Brand- _____
Size- _____	Size- _____	Size- _____	Size- _____
Condition- <u>GOOD</u>	Condition- <u>GOOD</u>	Condition- <u>GOOD</u>	Condition- <u>GOOD</u>

Defective Device fitted?

Defective Device returned to BU/ASM?

10 YR OLD