

SERVICE SCHEDULE FOR YQ26AG - A SERVICE @ 5 WEEKLY INTERVALS WITH 10% TOLERANCE

Vawdrey B Trailer (VIN # 6HJVAWAUS4SE00792)

Name	Rego#	Type	Date Done	Code\SubCode	Description	WorkOrder
MP113 - YQ26AG	YQ26AG	TR	13-Feb-23	Body\Misc	Roadworthy Repairs	2519
MP113 - YQ26AG	YQ26AG	TR	13-Feb-23	VehService\AS	VehService\AS	2518
MP113 - YQ26AG	YQ26AG	TR	31-Oct-22	TY\	Supply + Fit New Tyres x 6	2498
MP113 - YQ26AG	YQ26AG	TR	13-Aug-22	Inspection\AI	Annual Inspection	2427
MP113 - YQ26AG	YQ26AG	TR	13-Aug-22	VehService\AS	VehService\AS	2426
MP113 - YQ26AG	YQ26AG	TR	8-Jun-22	DL\Misc	Defect Clearance	2467
MP113 - YQ26AG	YQ26AG	TR	7-Jun-22	TY	Tyre	2338
MP113 - YQ26AG	YQ26AG	TR	30-May-22	Brakes	Replace Brake Booster + Adjust Trailer Brakes	2340
MP113 - YQ26AG	YQ26AG	TR	1-Apr-22	TY	Tyres x 2	2242
MP113 - YQ26AG	YQ26AG	TR	7-Feb-22	Body	Curtain Repairs	2152
MP113 - YQ26AG	YQ26AG	TR	23-Nov-21	Body\Misc	Body - Roof Support Repairs	1782
MP113 - YQ26AG	YQ26AG	TR	13-Oct-21	Body\Misc	Adjust Brakes + Air Bag Height	1641
MP113 - YQ26AG	YQ26AG	TR	24-Sep-21	TY\	New Tyres x 6	1587
MP113 - YQ26AG	YQ26AG	TR	24-Sep-21	Chassis\Misc	Remove and Replace Axles	1586
MP113 - YQ26AG	YQ26AG	TR	24-Sep-21	VehService\AS	VehService\AS	1585
MP113 - YQ26AG	YQ26AG	TR	13-Sep-21	Brakes\Reline	Full Brake Alignment	1518
MP113 - YQ26AG	YQ26AG	TR	13-Sep-21	Inspection\AI	Annual Inspection	1517
MP113 - YQ26AG	YQ26AG	TR	25-May-21	VehService\AS	A Service	1162
MP113 - YQ26AG	YQ26AG	TR	4-May-21	TY\Punct	Puncture Repair	1127
MP113 - YQ26AG	YQ26AG	TR	14-Apr-21	TY\	New Trailer Tyres x 3	1074
MP113 - YQ26AG	YQ26AG	TR	15-Mar-21	VehService\AS	A Service	907
MP113 - YQ26AG	YQ26AG	TR	2-Feb-21	VehService\AS	A Service	813
MP113 - YQ26AG	YQ26AG	TR	18-Dec-20	VehService\AS	A Service	646
MP113 - YQ26AG	YQ26AG	TR	13-Nov-20	VehService\AS	A Service	486
MP113 - YQ26AG	YQ26AG	TR	14-Oct-20	VehService\AS	A Service	247
MP113 - YQ26AG	YQ26AG	TR	8-Oct-20	TY\	Wheel Alignment	219
MP113 - YQ26AG	YQ26AG	TR	7-Sep-20	DL\	Shock ABS Issues	127
MP113 - YQ26AG	YQ26AG	TR	2-Sep-20	Body\Misc	Fit Arm Bushes	602
MP113 - YQ26AG	YQ26AG	TR	26-Aug-20	Inspection\AI	Annual Inspection	232