

5013

5-7 CAPELLI ROAD WINGFIELD SA

TAX INVOICE NUMBER L69912

For Enquiries

PHONE A/C 02-87880000 PHONE SERVICE 08-81696400

Customer Feedback

PHONE 1300 137 838 EMAIL customerfeedback@crown.com Customer No. 313534

Reference No.

| ORDER DATE | ORDER NO. | INVOICE DATE | JOB LOCATION | JOB ADDRESS |
|------------|---------------|--------------|------------------------------|------------------|
| 31/08/2023 | HAYLEY | 31/08/2023 | *GEPPS CROSS SA | 7 O'Connor Court |
| FLEET No. | SERIAL NUMBER | MODEL NUMBER | | GEPPS CROSS SA |
| | 5A514372R | TRADEIN | BREAKDOWN SERVICE CHARGES | 5094 |

| PART NUMBER | DESCRIPTION | LOC | QTY. | UNIT PRICE | TOTAL PRICE |
|-----------------|--------------------------|---------------|------|------------|-------------|
| 805117 | O-RING | 320 | 1 | 25.35 | 25.35 |
| 805115-003 | MOTOR SCREW | 320 | 2 | 7.49 | 14.98 |
| 305115-002 | MOTOR SCREW | 320 | 1 | 40.24 | 40.24 |
| 144067-001 | DRIVE UNIT ASM WP DC | 320 | 1 | 1,100.00 | 1,100.00 |
| 155066-002 | Hand Grip LHS | 320 | 1 | 60.18 | 60.18 |
| 325649 | Loadwheel | 320 | 2 | 310.94 | 621.88 |
| 065081-070 | BEARING | 320 | 4 | 17.51 | 70.04 |
| 155066-001 | Hand Grips RHS | 320 | 1 | 60.18 | 60.18 |
| 00000 | LABOUR | 320 | 7.0 | | 1,365.00 |
| 313128 | CASTER WHEEL | 320 | 2 | 221.64 | 443.28 |
| VASTE-01 | ENVIRONMENTAL CHARGE | | 1 | 16.75 | 16.75 |
| -UEL-01 | FUEL SURCHARGE | | 1 | 3.25 | 3.25 |
| SUPPLIES-01 | SUNDRIES AND CONSUMABLES | | 1 | 25.40 | 25.40 |
| | | | | | |
| Supply Value \$ | 3 846 53 GST RA | TE 10.0 % GST | | | 384.65 |

| Supply Value \$ 3,846.53 | | 3,846.53 | GST RATE 10.0 % | GST AMOL | GST AMOUNT | | 384.65 | |
|--|-----------|------------------------|--|-----------------------|---|-----|----------|--|
| | | | | TOTAL INV | OICE AMOUNT | AUD | 4,231.18 | |
| Payment due date is 30/09/2023. Additional Surcharge on Credit Card payments | | | | | | | | |
| Please pay on the No statement with the statement w | | | AMEX - 2.2%Visa/Master Credit Card - 1.1% | Bank Name: BSB No: | unds to Crown Equipn National Australia 082-276 | | | |
| NOTE This invoic | امدامه: م | aa a Fual Curaharaa du | to the engeing chile in fuel wither equation | Account No: | 509265108 | | | |

NOTE: This invoice includes a Fuel Surcharge due to the ongoing spike in fuel prices across the country.

Please email remittance advice to banking@crown.com or fax remittance advice to (02) 8788-0642.



5-7 CAPELLI ROAD WINGFIELD SA 5013

Job Address:

7 O'Connor Court GEPPS CROSS SA

5094

SERVICE JOB REPORT

Job Number: X 7538637

 Date:
 31/08/2023

 Time:
 12:20

 Order Number:
 HAYLEY

13 - BREAKDOWN SERVICE Model: SX3030TT4250

Serial Number: 5A514372R Fleet Number: Reference No.: L69912

| PART NUMBER | DESCRIPTION | QTY | LOCATION |
|-------------|--------------------------|------|----------|
| 805117 | O-RING | 1.00 | A08 |
| 805115-003 | MOTOR SCREW | 2.00 | A08 |
| 805115-002 | MOTOR SCREW | 1.00 | A08 |
| 144067-001 | DRIVE UNIT ASM WP DC | 1.00 | 320 |
| 155066-002 | Hand Grip LHS | 1.00 | A08 |
| 825649 | Loadwheel | 2.00 | A08 |
| 065081-070 | BEARING | 4.00 | A08 |
| 155066-001 | Hand Grips RHS | 1.00 | A08 |
| 00000 | LABOUR | 7.00 | A08 |
| 813128 | CASTER WHEEL | 2.00 | 320 |
| WASTE-01 | ENVIRONMENTAL CHARGE | | |
| FUEL-01 | FUEL SURCHARGE | | |
| SUPPLIES-01 | SUNDRIES AND CONSUMABLES | | |
| | TOTAL LABOUR HOURS | 7.00 | |

SERVICE REQUEST:

Fault Diagnosis:

M3BE Drv Unt & Comp's bat elec, 300 Drive Unit Assy., Damage, Impact.

Repair Notes:

Arrived on site, located unit and brought to work area. Upon removing drive motor found a chunk of the gearbox had broke n off, talked to Nick and Hayley, recieved verbal approval to replace gearbox. Travelled to workshop and removed motor f rom new gearbox. Returned to site and fitted new drive tyre and old motor to gearbox, then fitted to unit. Replace had g rips, load wheels and caster wheels as quoted.

CUSTOMERS NAME: Nick

SIGNATURE:

N

DATE: 31/08/2023

| BATTERY DETAILS | | | | | CHARGER DETAILS | | | | |
|-----------------|------|------|------------|-------|-----------------|---------------|---------------|-----------|--|
| | | | BATTERY #1 | | | BATTERY #2 | MANUFACTURER | | |
| MODEL | | | | | | | MODEL | | |
| SERIAL | | | | | | | SERIAL | | |
| AMP HRS | | | | | | | TEST TAG DATE | | |
| DATE CODE | | | | | | | HOUR METER | | |
| SPECIFIC GRA | VITY | .000 | | | .000 |) | | | |
| VOLT STATIC | | .0 | | | .0 | | 2 | 782 | |
| VOLT U/LOAD | | .0 | | | .0 | | - | | |
| SERVICEMAN | LABO | DUR | TRAVEL | TOTAL | | WARRANTY TYPE | FAILURE CODE | FAIR WEAR | |
| 2373 | | 6.5 | .5 | 7 | 7.0 | 01 | 300 | Y | |



5-7 CAPELLI ROAD WINGFIELD SA 5013

Job Address:

7 O'Connor Court GEPPS CROSS SA

5094

SERVICE JOB REPORT

Job Number: X 7538637

 Date:
 31/08/2023

 Time:
 12:20

 Order Number:
 HAYLEY

13 - BREAKDOWN SERVICE

| Model: | SX3030TT4250 |
|----------------|--------------|
| Serial Number: | 5A514372R |
| Fleet Number: | |
| Reference No.: | L69912 |

<

| | | | | OFFICE USE ONLY: | < |
|-------|-----|----|-----|------------------|---|
| | | | | | |
| TOTAL | 6.5 | .5 | 7.0 | | |

A DIVISION OF CROWN EQUIPMENT PTY. LTD.

Service Job Inspection Report

Safety and Function Inspection

Customer:

Job Number: X 7538637

| DESCRIPTION | INSP | ACT | DESCRIPTION | INSP | ACT | DESCRIPTION | INSP | ACT |
|---------------------------------|--------------|-------|--------------------------------|--------------|-----|-------------|------|-----|
| Operation | | | -Control handle base clearance | ~ | | | I | |
| Horn, Alarms, Lights | | | IC Trucks | v | | | | |
| Park Brake | 4 | | -Drive unit mounted securely | | NA | | | |
| Travel Speed - SCR / Transisto | v | | -Fuel / battery caps are secur | | NA | | | |
| -Creep & Plugging in both dire | ./ | | Wheel Condition | | | | | |
| Travel Speed - Resistor Trucks | v | | -Wheel bolts, axle retainers, | 1 | | | | |
| -1st, 2nd, 3rd speeds in both | ./ | | -Bearing lubricated | · | | | | |
| Speed Cut Out | × | | -Serviceable condition | · | | | | |
| IC Product | v | | -Caster rigs in good condition | · / | | | | |
| -Check operation of transmissi | | NA | Wiring Harness | • | | | | |
| -Check direction control | | NA | -Routed correctly | \checkmark | | | | |
| -Check unit does not start in | | NA | -PVC insulation serviceable | , , | | | | |
| Hydraulic - test all functions | | | Controls | • | | | | |
| Pallet Trucks | \checkmark | | -All controls are clearly labe | \checkmark | | | | |
| -Check heel & toe heights | | NA | -Actuators have a positive act | | | | | |
| -Check raise cut out | | NA | Battery | · | | | | |
| Limit / Safety Switch | | | -Retainers are secure | \checkmark | | | | |
| Brake | \checkmark | | -Plugs & leads free of damage | | | | | |
| -Check operation of handle or | | | -Water levels are correct | | | | | |
| -Stopping distance in both dir | v | | IC Product | • | | | | |
| Steering | V | | -Check condition of belts | | NA | | | |
| -Check operation | | | Power Disconnect | | | | | |
| -Check for leaks | v | | -Functioning correctly | \checkmark | | | | |
| Safety Decals | ✓ | | IC Product | | | | | |
| -Capacity plates and Decals ar | | | -Pre-Heater / Auto stop on die | | NA | | | |
| | ✓ | | -Fuel lock off operating | | NA | | | |
| Visual Inspection Load Guard | | | Mast mount / Chassis | | | | | |
| -Fitted & Secure | | | -Mounting bolts are secure | \checkmark | | | | |
| Mast assembly (forklift) | ✓ | | Electric Motor | | | | | |
| -Operates correctly to full he | | | -Brush and Stator condition | \checkmark | | | | |
| Fork assembly (pallet truck) | V | | Control Panel | | | | | |
| -Operates correctly to full he | | NA | -Contactors & Relay condition | \checkmark | | | | |
| Leaks | | | Operators display | | | | | |
| -Attachments | | | -Hour / Battery indicator oper | \checkmark | | | | |
| -Chassis and Mast | v | | Completion | | | | | |
| IC Product | V | | Clean work area | \checkmark | | | | |
| -Water or Coolant | | NA | Test truck functions | \checkmark | | | | |
| -Fuel or Vapour | | NA | Complete job card & check shee | \checkmark | | | | |
| Fork condition | | IN/ Y | | | | | | |
| -Lock and are secure to carria | | | | | | | | |
| -Heel clearance correct | V | | | | | | | |
| Lift Chains | V | | | | | | | |
| -Serviceable condition / adjus | | | | | | | | |
| Safety Screen | V | | | | | | | |
| -Does it allow good vision | | | | | | | | |
| Structural condition | v | | | | | | | |
| -Platform mat / anti-slip guar | / | | | | | | | |
| -Panel damage | * | | | | | | | |
| -Straddle legs / Nose caps ben | * | | | | | | | |
| -Mounting hardware secured | V | | | | | | | |
| Walkie Trucks | v | | | | | | | |
| | | | | | | | | |

Component identification and location with regards to appropriate inspection and action codes: Operation, IC Product, Check operation of transmission, Not Applicable. Operation, IC Product, Check direction control, Not Applicable. Operation, IC Product, Check unit does not start in gear/drive, Not Applicable. Operation, Pallet Trucks, Check heel & toe heights, Not Applicable. Operation, Pallet Trucks, Check raise cut out, Not Applicable. Visual Inspection, Fork assembly (pallet truck), Operates correctly to full height, Not Applicable.



Service Job Inspection Report

Safety and Function Inspection

Customer:

Job Number: X 7538637

Visual Inspection, IC Product, Water or Coolant, Not Applicable. Visual Inspection, IC Product, Fuel or Vapour, Not Applicable. Visual Inspection, IC Trucks, Drive unit mounted securely, Not Applicable. Visual Inspection, IC Trucks, Fuel / battery caps are secure, Not Applicable. Visual Inspection, IC Product, Check condition of belts, Not Applicable. Visual Inspection, IC Product, Pre-Heater / Auto stop on diesels, Not Applicable. Visual Inspection, IC Product, Fuel lock off operating, Not Applicable.



5013

5-7 CAPELLI ROAD WINGFIELD SA

TAX INVOICE NUMBER L69491

 For Enquiries

 PHONE A/C
 02-87880000

 PHONE SERVICE
 08-81696400

 FAX ACCOUNTS
 08-83594542

Customer Feedback

PHONE 1300 137 838 EMAIL customerfeedback@crown.com Customer No. 313534

Reference No.

| ORDER DATE | ORDER NO. | INVOICE DATE | JOB LOCATION | JOB ADDRESS |
|------------|---------------|--------------|-------------------------------------|------------------|
| 9/08/2023 | Na | 17/08/2023 | *GEPPS CROSS SA | 7 O'Connor Court |
| FLEET No. | SERIAL NUMBER | MODEL NUMBER | | GEPPS CROSS SA |
| | 5A514372R | TRADEIN | PREVENTATIVE MAINTENANCE CHARGES | 5094 |

| PART NUMBER | DESCRIPTION | LOC | QTY. | UNIT PRICE | TOTAL PRICE |
|----------------|--------------------------|-----------|--------|------------|-------------|
| 00001 | LABOUR | 320 | | | 254.60 |
| | | | | | |
| | Nick Sok | | | | |
| | Please note that a | | | | |
| | service charge has been | | | | |
| | made on this invoice as | | | | |
| | per your PMP agreement. | | | | |
| NASTE-01 | ENVIRONMENTAL CHARGE | | 1 | 16.75 | 16.75 |
| FUEL-01 | FUEL SURCHARGE | | 1 | 3.25 | 3.25 |
| SUPPLIES-01 | SUNDRIES AND CONSUMABLES | | 1 | 25.40 | 25.40 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| upply Value \$ | 300.00 GST RATE | 10.0% GST | AMOUNT | | 30.00 |

| Supply Value \$ 300.00 | GSTRATE 10.0 % | GST AMOUNT | 30.00 | | | |
|---|---|--|-------------|--|--|--|
| | | TOTAL INVOICE AMOUNT | AUD 330.00 | | | |
| Payment due date is 16/09/2023. | Additional Surcharge on Credit Card payments | FOR ALL DIRECT DEPOSITS | Page 1 of 1 | | | |
| Please pay on this invoice. No statement will be issued. | AMEX - 2.2% Visa/Master Credit Card - 1.1% | Deal News Network Austral's De | | | | |
| NOTE: This invoice includes a Fuel Surcha | rge due to the ongoing spike in fuel prices across | Account No: 509265108 Please email remittance advice to b | | | | |

the country.

or fax remittance advice to (02) 8788-0642.



5-7 CAPELLI ROAD WINGFIELD SA 5013

Job Address:

7 O'Connor Court GEPPS CROSS SA 5094

SERVICE JOB REPORT

Job Number: X 7493444

 Date:
 09/08/2023

 Time:
 14:13

 Order Number:
 Na

34 - PREVENTIVE MAINT.Model:SX3030TT4250Serial Number:5A514372RFleet Number:Fleet Number:Reference No.:L69491

| PART NUMBER | DESCRIPTION | QTY | LOCATION < |
|-------------|--------------------------|------|------------|
| 00001 | LABOUR | 1.50 | |
| WASTE-01 | ENVIRONMENTAL CHARGE | | |
| FUEL-01 | FUEL SURCHARGE | | |
| SUPPLIES-01 | SUNDRIES AND CONSUMABLES | | |
| | | | |
| | TOTAL LABOUR HOURS | 1.50 | |

SERVICE REQUEST:

Repair Notes:

TOTAL

Located unit and brought to work area. Blew out unit and greased all appropriate locations. Free lift chains at 1% stret ch. Drive motor gearbox seal leaking oil into the motor and mounting bolt heads stripped out. Cleaned out motor best as possible. Tynes close to being worn out. No water in battery, voltage dropped from 25v to 19v.Caster wheels flat spotted and tearing on edges. Quote to be sent to replace damaged items. Safety and funct ion tested, wiped down, and returned to service.

CUSTOMERS NAME: Nick

1.0

.5

1.5

SIGNATURE:

M

DATE: 09/08/2023

| | BATTERY DETAILS | | | | | CHARGER DETAILS | | | |
|--------------|-----------------|-------|----------------|------------|-----|------------------|-----------------|-----------|--|
| BATTERY #1 | | | | BATTERY #2 | | MANUFACTURER | | | |
| MODEL | | Centu | ury | | | | MODEL | • | |
| SERIAL | | B276 | 58-1 | | | | SERIAL . | | |
| AMP HRS | | 223 | | | | | TEST TAG DATE . | | |
| DATE CODE | | 7/20 | | | | | HOUR METER | | |
| SPECIFIC GRA | VITY | .000 | | | .00 |) | | | |
| VOLT STATIC | | 25.4 | | | .0 | | 2 | 779 | |
| VOLT U/LOAD | | 19.8 | | | .0 | | - | | |
| SERVICEMAN | LABC | OUR | R TRAVEL TOTAL | | | WARRANTY TYPE | FAILURE CODE | FAIR WEAR | |
| 2373 | | 1.0 | .5 | | 1.5 | 01 | | Y | |
| | | | | | | OFFICE USE ONLY: | QU | QU | |



5-7 CAPELLI ROAD WINGFIELD SA 5013

SERVICE JOB REPORT

Job Number: X 7493444

 Date:
 09/08/2023

 Time:
 14:13

 Order Number:
 Na



A DIVISION OF CROWN EQUIPMENT PTY. LTD.

ST/SX 3000 Series

Service Job Inspection Report

Customer:

| DESCRIPTION | INSP | ACT | DESCRIPTION | INSP | ACT |
|---|--------------|-----|-------------------------------------|--------------|-----|
| VISUAL INSPECTION | | | Power Cable Connections Secure | \checkmark | |
| Oil Leaks | \checkmark | | Wiring Conditions | \checkmark | |
| Mast Assembly & Guard | \checkmark | | Wiring Connections Secure | \checkmark | |
| Load Backrest (Optional) | \checkmark | | Wiring Harness Condition | \checkmark | |
| Forks & Latches | \checkmark | | Remote Coil Cord & Switch Cond | \checkmark | |
| Limit Switch | \checkmark | | CONTACTOR PANEL & POWER | CONTA | С |
| Lift Chain & Mounts | \checkmark | | Line Contactor Tip Condition | \checkmark | |
| Control Arm & Handle | \checkmark | | Pump Contactor Tip Condition | \checkmark | |
| Tyre & Wheel Condition | | | TRACTION CONTROLLER | | |
| -LH Load Wheel | \checkmark | | Creep Speed | \checkmark | |
| -LH Caster (Optional) | | | Plugging | \checkmark | |
| -Drive Tyre & Lug Bolts | <i>.</i> | | Blow Dust Off Panel | \checkmark | |
| -RH Caster (Optional) | 1 | | CONTROL HANDLE | | |
| -RH Load Wheel | ¥ | | Switch Condition | \checkmark | |
| Safety Decals & Capacity Plate | · | | Switch Adjustment | \checkmark | |
| Bent or Damage Parts | \checkmark | | Potentiometer | \checkmark | |
| Tape, String, etc. Around Driv | | | Spring Return | \checkmark | |
| Battery Cable Condition (Truck | • | | BRAKES | | |
| Battery Connector Condition (T | × | | Adjustment | \checkmark | |
| Battery Retainers | × | | Friction Plate | | |
| CLEAN & LUBRICATE | v | | Rotor | | |
| Blow Off Truck | 1 | | Hub Key | | |
| Lubricate | v | | Mounting Screws | | |
| -Lubricate Mast & Roller Assem | | | Electrical Connection | | |
| -Caster Wheels | * | | Switch | 1 | |
| -Steer Bearing | \checkmark | | MAST ASSEMBLY | | |
| -Control Handle Coil Springs | v | | Roller & Tracking - Wear or Da | \checkmark | |
| -Lubricate Lift Chains | v | | Lift Chain Condition - Wear | | |
| -Load Wheel Bearings | 1 | | Lift Chain Adjustment | | |
| -Mast Free Lift Stud (TT) | 1 | | Lift Cylinder & Mount Conditio | | |
| Apply Armorall or Clear Guard | v | | Mounting Bolts to Power Unit S | ✓ | |
| | ✓ | | Control Cables & Hoses | ✓ | |
| HYDRAULIC SYSTEM Pump & Motor Mounting Secure | | | Limit Switch | \checkmark | |
| Oil Level & Condition | v | | Load Backrest Secure (Optional | \checkmark | |
| Hoses & Fitting Condition | v | | Poly Stops | \checkmark | |
| u | √ | | FREEZER CONDITION (Optiona | al) | |
| Leaks-Cylinder, etc. | √ | | Heater Operation | | NA |
| Breather Cap Suction & Return Filters | √ | | Wiring Condition | | NA |
| Brush & Armature Condition | √ | | OPERATIONAL CHECK & TEST | DRIVE | |
| Blow Brush Dust From Motor | √ | | BDI or Hour Meter (Optional) | \checkmark | |
| | \checkmark | | Horn | \checkmark | |
| DRIVE UNIT Fluid Level | | | Safety Reversing Switch | \checkmark | |
| | √ | | Lift - Lower Operation | \checkmark | |
| Leaks Motor Mounting Secure | ✓ | | Power Disconnect | \checkmark | |
| Motor Mounting Secure Brush & Armature Condition | √ | | Verify Brake Operation | \checkmark | |
| | ✓ | | Stopping Distance | \checkmark | |
| Mounting to Power Unit Secure | √ | | Brake Switch | \checkmark | |
| Blow Brush Dust From Motor | √ | | Limit Switch Cut-Out | \checkmark | |
| Steer Bearings | √ | | Travel Speeds | \checkmark | |
| Wheel Lug Bolts | √ | | Rated Capacity | \checkmark | |
| POWER CABLES & CONTROL V | VIRING | | Charger | \checkmark | |
| Power Cable Conditions | \checkmark | | | | |

Job Number: X 7493444

| DESCRIPTION | INSP | ACT |
|---------------------------|--------------|-----|
| Travel Alarm (Optional) | _ | |
| naver viann (Optional) | ✓ | |
| Flashing Light (Optional) | \checkmark | |
| ATTACHMENTS | | |
| Operation | \checkmark | |
| Leaks | \checkmark | |
| Condition | | |
| CUSTOMER CARE | | |
| Wipe Off Truck | \checkmark | |
| Clean Area | \checkmark | |

Component identification and location with regards to appropriate inspection and action codes: FREEZER CONDITION (Optional), Heater Operation, Not Applicable. FREEZER CONDITION (Optional), Wiring Condition, Not Applicable.



5013

5-7 CAPELLI ROAD WINGFIELD SA

TAX INVOICE NUMBER L58820

 For Enquiries

 PHONE A/C
 02-87880000

 PHONE SERVICE
 08-81696400

 FAX ACCOUNTS
 08-83594542

Customer Feedback

PHONE 1300 137 838 EMAIL customerfeedback@crown.com Customer No. 313534

Reference No.

| ORDER DATE | ORDER NO. | INVOICE DATE | JOB LOCATION | JOB ADDRESS | |
|------------|--|--------------|------------------------------|------------------|--|
| 26/04/2022 | NICK SOK | 27/04/2022 | *GEPPS CROSS SA | 7 O'Connor Court | |
| FLEET No. | SERIAL NUMBER MODEL NUMBER 5A514372R TRADEIN | | | GEPPS CROSS SA | |
| | | | BREAKDOWN SERVICE CHARGES | 5094 | |

| PART NUMBER | DESCRIPTION | LOC | QTY. | UNIT PRICE | TOTAL PRICE |
|-------------|--------------------------|-----|------|------------|-------------|
| 0000 | LABOUR | 320 | .6 | | 68.15 |
| 03013 | TENSION SPRING | 320 | 3 | 101.30 | 303.90 |
| VASTE-01 | ENVIRONMENTAL CHARGE | | 1 | 13.50 | 13.50 |
| UEL-01 | FUEL SURCHARGE | | 1 | 3.25 | 3.25 |
| SUPPLIES-01 | SUNDRIES AND CONSUMABLES | | 1 | 21.00 | 21.00 |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |

| Supply Value | \$ | 409.80 | GST RATE 10.0 % | GST AMOUNT | 40.98 | | |
|--|----|--------|--|--|-------------|--|--|
| | | | | TOTAL INVOICE AMOUNT | AUD 450.78 | | |
| Payment due date is 27/05/2022. | | | Additional Surcharge on Credit Card payments AMEX - 2.2% | FOR ALL DIRECT DEPOSITS Please remit funds to Crown Equipr | Page 1 of 1 | | |
| Please pay on this invoice. No statement will be issued. | | | Visa/Master Credit Card - 1.1% | Bank Name: National Australia BSB No: 082-276 Account No: 509265108 | | | |
| NOTE: This invoice includes a Fuel Surcharge due to the ongoing spike in fuel prices across the country. | | | | Please email remittance advice to banking@crown.com or fax remittance advice to (02) 8788-0642. | | | |



5-7 CAPELLI ROAD WINGFIELD SA 5013

Job Address:

7 O'Connor Court GEPPS CROSS SA 5094

....

SERVICE JOB REPORT

Job Number: X 7084561

Date: 26/04/2022 Time: 13:15 Order Number: NICK SOK

13 - BREAKDOWN SERVICE Model: SX3030TT4250 Serial Number: 5A514372R Fleet Number: **Reference No.:** L58820

| PART NUMBER | DESCRIPTION | QTY | LOCATION < |
|-------------|--------------------------|------|------------|
| 00000 | LABOUR | 0.60 | |
| 803013 | TENSION SPRING | 3.00 | A18 |
| WASTE-01 | ENVIRONMENTAL CHARGE | | |
| FUEL-01 | FUEL SURCHARGE | | |
| SUPPLIES-01 | SUNDRIES AND CONSUMABLES | | |
| | | | |
| | TOTAL LABOUR HOURS | 0.60 | |

SERVICE REQUEST:

Fault Diagnosis:

M2BE Hydraulic Sys & Comp's, 250 Linkage, Damage, Impact.

Repair Notes:

Replaced broken handle springs

| CUSTOMERS NAME: | Nick |
|-----------------|------|
|-----------------|------|

| CUSTOMERS NAME: | Nick | SIGNATURE: | | DATE: 26/04/2022 | |
|------------------|-----------------|-----------------|---------------|------------------|--|
| | | | | | |
| | BATTERY DETAILS | CHARGER DETAILS | | | |
| | BATTERY #1 | BATTERY #2 | MANUFACTURER | | |
| MODEL | | | MODEL | | |
| SERIAL | | | SERIAL | | |
| AMP HRS | | | TEST TAG DATE | | |
| DATE CODE | | | HOUI | RMETER | |
| SPECIFIC GRAVITY | .000 | .000 | | | |
| VOLT STATIC | .0 | .0 |] 2 | 2727 | |
| VOLT U/LOAD | .0 | .0 | | | |
| | | | | | |

AD

| SERVICEMAN | LABOUR | TRAVEL | TOTAL | WARRANTY TYPE | FAILURE CODE | FAIR WEAR |
|------------|--------|--------|-------|------------------|--------------|-----------|
| 1328 | .6 | .0 | .6 | 01 | 250 | Y |
| | | | | OFFICE USE ONLY: | | |
| | | | | | | |
| TOTAL | .6 | .0 | .6 | | | |

A DIVISION OF CROWN EQUIPMENT PTY. LTD.

ST/SX 3000 Series

Service Job Inspection Report

Customer: 3

| DESCRIPTION | INSP | ACT | DESCRIPTION | INSP | ACT |
|--|--------------|-----|-------------------------------------|--------------|-----|
| VISUAL INSPECTION | | | Power Cable Connections Secure | \checkmark | |
| Oil Leaks | \checkmark | | Wiring Conditions | ✓ | |
| Mast Assembly & Guard | ✓ | | Wiring Connections Secure | ✓ | |
| Load Backrest (Optional) | √ | | Wiring Harness Condition | \checkmark | |
| Forks & Latches | ✓ | | Remote Coil Cord & Switch Cond | \checkmark | |
| Limit Switch | ✓ | | CONTACTOR PANEL & POWER | CONTA | С |
| Lift Chain & Mounts | | | Line Contactor Tip Condition | \checkmark | |
| Control Arm & Handle | | | Pump Contactor Tip Condition | \checkmark | |
| Tyre & Wheel Condition | | | TRACTION CONTROLLER | | |
| -Drive Tyre & Lug Bolts | \checkmark | | Creep Speed | \checkmark | |
| -RH Load Wheel | 1 | | Plugging | \checkmark | |
| -LH Load Wheel | | | Blow Dust Off Panel | \checkmark | |
| -RH Caster (Optional) | | | CONTROL HANDLE | | |
| -LH Caster (Optional) | | | Switch Condition | \checkmark | |
| Safety Decals & Capacity Plate | ✓ | | Switch Adjustment | \checkmark | |
| Bent or Damage Parts | ¥ | | Potentiometer | \checkmark | |
| Tape, String, etc. Around Driv | , , | | Spring Return | \checkmark | |
| Battery Cable Condition (Truck | , , | | BRAKES | | |
| Battery Connector Condition (T | · | | Adjustment | \checkmark | |
| Battery Retainers | • | | Friction Plate | \checkmark | |
| CLEAN & LUBRICATE | v | | Rotor | \checkmark | |
| Blow Off Truck | ./ | | Hub Key | \checkmark | |
| Lubricate | v | | Mounting Screws | \checkmark | |
| -Load Wheel Bearings | ./ | | Electrical Connection | \checkmark | |
| -Lubricate Mast & Roller Assem | * | | Switch | \checkmark | |
| -Lubricate Lift Chains | v √ | | MAST ASSEMBLY | | |
| -Mast Free Lift Stud (TT) | √ | | Roller & Tracking - Wear or Da | \checkmark | |
| -Caster Wheels | v √ | | Lift Chain Condition - Wear | \checkmark | |
| -Control Handle Coil Springs | v √ | | Lift Chain Adjustment | \checkmark | |
| -Steer Bearing | * | | Lift Cylinder & Mount Conditio | \checkmark | |
| Apply Armorall or Clear Guard | * | | Mounting Bolts to Power Unit S | \checkmark | |
| HYDRAULIC SYSTEM | v | | Control Cables & Hoses | \checkmark | |
| Pump & Motor Mounting Secure | 1 | | Limit Switch | \checkmark | |
| Oil Level & Condition | * | | Load Backrest Secure (Optional | \checkmark | |
| Hoses & Fitting Condition | * | | Poly Stops | \checkmark | |
| Leaks-Cylinder, etc. | v | | FREEZER CONDITION (Optional |) | |
| Breather Cap | v | | Heater Operation | \checkmark | |
| Suction & Return Filters | * | | Wiring Condition | \checkmark | |
| Brush & Armature Condition | * | | OPERATIONAL CHECK & TEST | DRIVE | |
| Blow Brush Dust From Motor | × | | BDI or Hour Meter (Optional) | \checkmark | |
| | V | | Horn | \checkmark | |
| DRIVE UNIT Fluid Level | / | | Safety Reversing Switch | \checkmark | |
| Leaks | V | | Lift - Lower Operation | \checkmark | |
| Motor Mounting Secure | v | | Power Disconnect | \checkmark | |
| Brush & Armature Condition | V, | | Verify Brake Operation | \checkmark | |
| Mounting to Power Unit Secure | v | | Stopping Distance | \checkmark | |
| Blow Brush Dust From Motor | V | | Brake Switch | \checkmark | |
| Steer Bearings | V, | | Limit Switch Cut-Out | \checkmark | |
| | v | | Travel Speeds | \checkmark | |
| Wheel Lug Bolts | √ | | Rated Capacity | \checkmark | |
| POWER CABLES & CONTROL V Power Cable Conditions | VIRING | | Charger | \checkmark | |
| | √ | | | | |

Job Number: X 7084561

| DESCRIPTION | INSP | ACT |
|---------------------------|--------------|-----|
| Travel Alarm (Optional) | ./ | |
| Flashing Light (Optional) | ¥ | |
| ATTACHMENTS | · | |
| Operation | \checkmark | |
| Leaks | \checkmark | |
| Condition | \checkmark | |
| CUSTOMER CARE | | |
| Wipe Off Truck | \checkmark | |
| Clean Area | \checkmark | |

Component identification and location with regards to appropriate inspection and action codes: