

Make: GROVE
Model: GMK 4100
Year: 2017
Serial Number: 4100 4064

Body: All Terrain

DATE	DESCRIPTION			
15/03/2023	Odometer: 28,642	Total: \$0.00	Job No: 1004766	Inv No: 4725
Inspect wire rope broken strand, Photographic Record, Repairs Mechanical				
13/12/2022	Odometer: 28,248	Total: \$0.00	Job No: 1004660	Inv No: 4613
Crane Safe, Crane Safe Repairs, Photographic Record				
08/12/2022	Odometer:	Total: \$0.00	Job No: 1004495	Inv No: 4458
Replace external light bar, Auto Electrical, Photographic Record				
02/07/2022	Odometer: 27,043	Total: \$0.00	Job No: 1004159	Inv No: 4123
500 Hour Service, 500 Hour Service, Photographic Record				
31/05/2022	Odometer:	Total: \$0.00	Job No: 1004014	Inv No: 4000
Repair Brake Fault code, Brake Systems, Photographic Record				
24/05/2022	Odometer:	Total: \$0.00	Job No: 1004001	Inv No: 3971
Hydraulic oil leak, Hydraulic Repair, Photographic Record				
03/05/2022	Odometer:	Total: \$0.00	Job No: 3895-1	Inv No: 3871-1
Exhaust Leak, Exhaust Systems, Photographic Record				
28/04/2022	Odometer:	Total: \$0.00	Job No: 1003895	Inv No: 3871
Hydraulic Oil Leak, Hydraulic Repair, Photographic Record				

12/04/2022	Odometer: 25,807	Total: \$0.00	Job No: 1003791	Inv No: 3797	Boom Fault, Auto Electrical, Photographic Record
22/03/2022	Odometer: 25,072	Total: \$0.00	Job No: 1003719	Inv No: 3690	Counter weight fault - will not pressurise in the up position, Auto Electrical, Hydraulic Repair, Photographic Record
23/02/2022	Odometer:	Total: \$0.00	Job No: 1003529	Inv No: 3641	Overheating Issues, Mechanical Repairs, Photographic Record
12/02/2022	Odometer: 23,214	Total: \$0.00	Job No: 3432-1	Inv No: 3406-1	Cransafe Inspection, Photographic Record
07/01/2022	Odometer: 23,548	Total: \$0.00	Job No: 1003432	Inv No: 3406	Front wiper repair and fire extinguisher, Auto Electrical, Photographic Record
14/12/2021	Odometer: 23,532	Total: \$0.00	Job No: 1003365	Inv No: 3395	Boom tele cylinder can bus fault, Auto Electrical, Photographic Record
08/11/2021	Odometer:	Total: \$0.00	Job No: 1003237	Inv No: 3211	Exhaust Pipe Repair and Water pump, Mechanical Repairs, Photographic Record
03/11/2021	Odometer: 20,847	Total: \$0.00	Job No: 1003185	Inv No: 3155	Diagnose & Repair, Mechanical Repairs
21/10/2021	Odometer:	Total: \$0.00	Job No: 1002518	Inv No: 2559	Mudguard repair and replace mudflaps, Painting
06/10/2021	Odometer: 21,073	Total: \$0.00	Job No: 1003117	Inv No: 3101	Strange noise in upper, Auto Electrical
24/09/2021	Odometer: 20,880	Total: \$0.00	Job No: 1002852	Inv No: 3051	Steering Fault codes, Auto Electrical, Hydraulic Repair
30/04/2021	Odometer: 20,373	Total:	Job No: 1002456	Inv No:	Hydraulic filter restriction sensor, Auto Electrical

29/03/2021	Odometer: 20,159	Total: \$0.00	Job No: 1002327	Inv No: 2320
Battery replacement, Auto Electrical				
27/03/2021	Odometer: 20,122	Total: \$0.00	Job No: 2306-1	Inv No: 2299-1
1000 Hour Service, 1000 Hour Service				
23/03/2021	Odometer: 19,738	Total: \$0.00	Job No: 1002306	Inv No: 2299
Cooling fan leak and tele fault, Hydraulic Repair				
12/02/2021	Odometer:	Total: \$0.00	Job No: 1809-2	Inv No: 2069-1
Panel damage, Painting				
03/02/2021	Odometer:	Total: \$0.00	Job No: 1809-1	Inv No: 2069-2
AD Blue Fuel leak, Mechanical Repairs				
24/11/2020	Odometer: 18,235	Total: \$0.00	Job No: 1001764	Inv No: 2049
Crane Safe, Carry out Crane Safe Inspection				
11/11/2020	Odometer: 19,738	Total: \$0.00	Job No: 1001809	Inv No: 2069
Intermittent tele lock pin fault, Hydraulic Repair				
15/09/2020	Odometer:	Total: \$0.00	Job No: 1001605	Inv No: 1616
Boom Recovery and Repair, Auto Electrical, Hydraulic Repair				
15/09/2020	Odometer:	Total: \$0.00	Job No: 1605-1	Inv No: 1616-1
750 Hour Service, 750 Hour Service				
13/08/2020	Odometer: 17,545	Total: \$0.00	Job No: 1001439	Inv No: 1459
Air-Con, Air Conditioning				
11/08/2020	Odometer:	Total: \$0.00	Job No: 1439-1	Inv No: 1459-1
Panel Damage				
08/08/2020	Odometer:	Total: \$2,618.30	Job No: 1001448	Inv No: 1460

Incident Repairs, Painting

16/06/2020	Odometer:	Total: \$2,135.54	Job No: 1001271	Inv No: 1291
Valve bank Solenoid oil leak, Hydraulic Repair				

04/05/2020	Odometer: 14,393	Total: \$1,625.04	Job No: 1001067	Inv No: 1001078
Minor Service				
