

Vehicle History Summary



Fleet #	54
Registration	073QLL
Make	FTE
Model	FTE3A
VIN / Chassis #	6B9FTE3BR5MAA5069
Build Date	2005

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
S-5094	23/10/2022	90262	0	A - 30000km		Kelvyn Fuller
S-5015	05/09/2022	80235	0	A - 30000km		Colin Scott
S-4855	04/08/2022	63801	0	A - 30k / 30 Day		Colin Scott
T-1424	25/07/2022	0	0	STRIP & FIT	2 STRIP & FITMENT	Tyreright
S-4854	20/07/2022	58479	0	A - 30k / 30 Day		Colin Scott
T-1414	18/06/2022	0	0	Puncture		Tyreright
S-4748	15/06/2022	41142	0	A - 30k / 30 Day		Colin Scott
S-4741	09/05/2022	23656	0	A - 30k / 30 Day		Colin Scott
S-4740	07/04/2022	16671	0	A - 30k / 30 Day		Colin Scott
S-4620	15/03/2022	8457	0	A - 30k / 30 Day		Colin Scott
I-28	16/02/2022	0	0	HEAVY VEHICLE ANNUAL INSPECTION - TRAILERS		
S-4566	15/02/2022	0	0	C - Annual	new hubometer	SH&M Fuller Transport Repairs
S-4476	20/01/2022	748450	0	A - 20k/ 30 Day		Colin Scott
T-1329	17/01/2022	0	0	STRIP & FIT	4 STRIP AND FIT	Tyreright
S-4309	22/12/2021	739885	0	A - 20k/ 30 Day		Colin Scott
S-4308	25/11/2021	732655	0	A - 20k/ 30 Day		Colin Scott
S-4307	28/10/2021	719268	0	A - 20k/ 30 Day		Colin Scott
S-4306	25/09/2021	706942	0	A - 20k/ 30 Day		Colin Scott
S-3175	27/08/2021	694284	0	A - 20k/ 30 Day		Kelvyn Fuller
S-3176	20/07/2021	685519	0	A - 20k/ 30 Day		Kelvyn Fuller
S-3177	17/06/2021	678930	0	A - 20k/ 30 Day		Kelvyn Fuller
S-3530	14/05/2021	670161	0	A - 20k/ 30 Day		Colin Scott

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
T-1189	05/05/2021			Pressure Test		TYRE EVOLUTION
S-3619	10/04/2021	664522	0	A - 20k/ 30 Day		Colin Scott
R-1267	19/02/2021	649172		MISC	R & R WORN BEARINGS , LEAKING AIR BAGS, LEG HANDLE, LEAKING SHOCK ABSORBER. REPLACE MISSING END CAPS	SH&M Fuller
S-3658	17/02/2021	649172	0	A - 20k/ 30 Day		SH&M Fuller
S-3659	16/02/2021	649172	0	C - Annual		SH&M Fuller
T-1034	04/01/2021			Rotate		TYRE EVOLUTION
T-1033	04/01/2021			Re - Treads		TYRE EVOLUTION
S-3134	03/01/2021	636190	0	A - 20k/ 30 Day		Kelvyn Fuller
S-3135	19/12/2020	632945		A - 20k/ 30 Day		Kelvyn Fuller

Signed: _____

Name: _____

Date: _____

Vehicle History Summary



Fleet #	FU14-54
Registration	073QLL
Make	FRIDGE UNIT
Model	FRIDGE UNIT
VIN / Chassis #	FRIDGE UNIT
Build Date	

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-2146	18/10/2022	0	0	Engine	*REPAIRS DURING MAJOR SERVICE REPLACED U/S ALTERNATOR BRUSHES ADJUSTED ALL BELTS...CHECKED PULLEYS AND BEARINGS DOWNLOADED MICRO...CHECKED DATA AND SETTINGS... CHECKED TIME AND DATE CORRECT	Iceman Refrigeration Repairs
S-5092	17/10/2022	0	41308	C - Major Service	*MAJOR SERVICE...@ K&S DEPOT MAJOR SERVICE COMPLETED...CHANGED ENGINE OIL AND ALL FILTERS SERVICED BATTERY REPLACED AIR CLEANER ELEMENT CLEANED FUEL INLET SCREEN...BLED FUEL SYSTEM PERFORMED FULL UNIT CALIBRATIONS AND REFRIGERATION TESTS COMPLETED ALL ITEMS ON MAJOR SERVICE CHECK SHEET UNIT SELF CHECK = PASSED RAN AND CHECKED UNIT OPERATIONS INCL DEFROST	Iceman Refrigeration Repairs
S-4858	15/07/2022	0	40762	A - Minor Service	ADJUSTED ALL BELTS, FITTED AND SECURED MISSING REAR SNUBBER BOLTS	Iceman Refrigeration Repairs
S-4797	18/06/2022	0	40506	A - Minor Service		
R-2070	20/04/2022	0	0	ALARM	DOWN ON REFRIGERANT . REPAIRED LEAK AT DISTRIBUTOR ELBOW. REPLACE MICRO BEZEL.	Iceman Refrigeration Repairs
S-4521	04/02/2022	0	39774	C - Major Service	R & R FULL SET OF BELTS, THROTTLING VALVE AND SPRING. REPLACE AIR CLEANER ELEMENT,	Iceman Refrigeration Repairs
S-4438	19/12/2021	0	39500	A - Minor Service		Iceman Refrigeration Repairs
R-2018	19/12/2021	0	0	TEMPATURE	FOUND SYSTEM DOWN ON REFRIGERANT	Iceman Refrigeration Repairs

Number	Date	Kms	Hours	Type	Repairer Notes	Repairer
R-1503	19/07/2021		38680	TEMPATURE	NOT PULLING TEMP RAN UNIT AND CHECKED OPERATIONS REPLACE TAPPET COVER O RING, DISCHARGE MANIFOLD GASKET R & R ROCKER COVER , RESEALED COVER WIPED UP OIL AS ABLE. REFRIGERAT TOPPED UP.	Iceman Refrigeration Repairs
R-1311	27/04/2021		38388	Coolant Leak	REPLACE WATER PUMP PLATE, WATER PUMP ASSY, THERMOSTAT	Iceman Refrigeration Repairs
R-1274	01/03/2021		38077	Alarm	ALARM 26 FOUND SYSTEM DOWN ON REFRIGERANT . REPLACE THROTTLING VALVE ORING	Iceman Refrigeration Repairs
R-1236	20/01/2021		1	MISC	REPLACED EVAPORATOR BLOWER ASSY RESEALED AND SECURED PIPEWORK CHARGED SYSTEM WITH REFRIGERANT	Iceman Refrigeration Repairs

Signed: _____

Name: _____

Date: _____