






# Vehicle Service Records (VSR Explorer) Repair history D-202500

**Registration nr:** XQ82JJ      **Chassis nr:** D-202500      **VIN nr:** YV5RG40DXFD202500  
**Market type:** FH13A64T      **Country:** AUS      **Delivery date:** 2015-12-01

PC	Type	Code	Description (Original)	#
<b>2023-06-09 - Mileage: 1276609 - Order nr: 8174791</b>				
	📄		Repair without detail info	
<b>2022-10-28 - Mileage: 0 - Order nr: 8165037</b>				
📄	*	M	PLEASE FILL IN	
	📄			
	📄			
	📄		Mileage:	
	📄		Hrs:	
	📄		Next Service:	
	📄		Parked:	
📄	🔧	LO-560	reprogram apm	1
	📄		via team viewer	
📄	🔧	VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
	📄		Connect-disconnect of diagnostic tool included	
📄	*	91	WORKSHOP CONSUMABLES	
<b>2020-05-06 - Mileage: 959189 - Order nr: 8131198</b>				
📄	*	40	Sublet	
<b>2020-03-17 - Mileage: 959189 - Order nr: 8129164</b>				
📄	*	40	Sublet	
<b>2020-03-10 - Mileage: 959189 - Order nr: 7603538</b>				
	📄		Workshop/	
	📄			
📄	🔧	LO-451	JACK SHAFT FAILED	2
📄	🔧	VO-22244623	PROPELLER SHAFT	1
📄	🔧	VO-995906	BOLT M14*46 FINE 10.9G	8
📄	🔧	VO-25339078	HEXAGON NUT	8
	📄		ÄÄÄ TOWED IN BY NOLANS ÄÄÄ	
	📄		P.JACK SHAFT FAILED	
	📄		C.FAILED UNI ON JACKSHAFT	
	📄		R.-REMOVED AND REPLACED JACKSHAFT	
	📄		-REPLACED BOLTS AND TENSIONED	

PC	Type	Code	Description (Original)	#
	📄		-TEST DROVE AND FOUND CORRECT	
🔧	*	91	WORKSHOP CONSUMABLES	
<b>🔍 2019-12-10 - Mileage: 902350 - Order nr: 8125424</b>				
🔧	*	M	PLEASE FILL IN	
	📄			
🔧	🔧	LO-214	Radiator and gear box cooler leaking	5
	📄		Inspected cooling system, found leaks from radiator and	
	📄		Mileage:902350	
	📄		Hrs:11543	
🔧	🔧	LO-214	REPLACE 3 PISTON & LINERS	7
🔧	🔧	LO-210	CARRY OUT MAIN & 3 BIG END BEARING ROLL	7
🔧	*	97	ENVIRONMENTAL CHARGE	
🔧	🔧	VO-21253770	CYLINDER LINER KIT	3
🔧	🔧	AU2-9718-240002743	BBC4 BRAKE CLEANER	3
🔧	🔧	VO-1161277	LINER SILASTIC	3
🔧	🔧	OTH- WUR0674850120/MTR	EMERY CLOTH G120	1
🔧	🔧	VO-20486228	BIG END BOLT - FM/FH13(4)	12
🔧	🔧	VO-3092340	SILASTIC GREY	1
🔧	🔧	VO-21610676	BEARING SHELL	3
🔧	🔧	VO-23070440	MAIN BEARING KIT	7
🔧	🔧	VO-21948261	THRUST WASHER KIT	1
🔧	🔧	VO-8192804	SCREW	8
🔧	🔧	VO-990861	FLANGE BOLT M10 x 30mm Grey	24
🔧	🔧	AU2-WUR0673205010	Nylon Power LOC 2I	4
🔧	🔧	OTH- WUR0674850240/MTR	EMERY CLOTH G240	1
🔧	🔧	VO-85021957	RADIATOR, EXCH - FH(4)	1
🔧	🔧	VO-20592783	CLAMP	2
🔧	🔧	VO-948980	O-RING	1
🔧	🔧	VO-22560373	HOSE BOTTOM RAD - FM/FH(4)	1
🔧	🔧	VO-993977	HOSE CLAMP 60-80mm	1
🔧	🔧	VO-20840154	HOSE CLAMP 60-80mm	1
🔧	🔧	VO-993977	HOSE CLAMP 60-80mm	1
🔧	🔧	VO-21312237	CHARGE AIR HOSE - BOTTOM FH (4)	1
🔧	🔧	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
🔧	🔧	AU2-CAL8394800	VOLVO VCS COOLANT- 20LTR	2
🔧	🔧	VO-20883450	SEALING RING	2

PC	Type	Code	Description (Original)	#
		VO-21433769	SEALING RING - MANIFOLD	2
		VO-1161929	JOINTING PASTE	1
		VO-23608283	EXH MANIFOLD - FM/FH(4)	1
		VO-23609062	EXH MANIFOLD - FM/FH(4)	1
		VO-20508112	EXHAUST MANIFOLD - CENTRE	1
		VO-22630453	RADIATOR GEARBOX - FH(4)	1
		VO-21959469	HOSE G/BOX RADIATOR - FH(4)	1
		VO-21585190	PIPE SET	1
		MK-FTM62X8	JOINER 8MM TUBE NUT & OLIVE	1
		VO-20722710	HOSE CLAMP 16-27mm	2
		VO-21959962	HOSE	1
		OTH-RMHC6	CLAMP-HOSE 8-22MM	2
		VO-22306618	OIL FILLER PIPE	1
		VO-60111993	WASHER	1
		VO-1161963	RUBBER GREASE	1
		VO-25094332	P-CLAMP SIZE 15	1
		VO-995906	HEXAGON SCREW	4
		VO-25339078	HEX NUT - M14 FINE (11MM)	4
		VO-20486228	BIG END BOLT - FM/FH13(4)	24
		LO-250	Manifold slip joints are leaking.	2
			Found manifold slip joints are leaking, removed and	
		LO-2000	Oil filler pipe leaking.	0.5
			Replaced.	
			replaced exhaust manifold.	
		VO-1758500	Oil, gearbox, change	2
			Removed and replaced cooler and replaced perished hoses	
			gearbox cooler. Removed radiator, swapped over all	
			accessories to new and refit cooling pack. Replaced	
			leaking gearbox cooler. Replaced all hoses and clamps as	
			required. Filled with fresh coolant, ran up and checked.	
		261	Extra parts not covered under extended	
			coverage.	
			as required.	
		91	WORKSHOP CONSUMABLES	
 <b>2019-12-06 - Mileage: 902350 - Order nr: 8125325</b>				
		M	PLEASE FILL IN	
				
		VO-2112600	Cylinder head, replace	11.4

PC	Type	Code	Description (Original)	#
B	R	VO-21253770	CYLINDER LINER KIT	3
B	R	VO-20538793	SEAL STRIP, R/COVER GASKET	1
B	R	VO-20541940	SEALING STRIP	1
B	R	VO-85022413	EXCH CLY HEAD - D13C/D	1
B	R	VO-20486228	BIG END BOLT - FM/FH13(4)	12
B	R	VO-21610676	BEARING SHELL	3
B	R	VO-21948261	THRUST WASHER KIT	1
B	R	VO-21510072	CYLINDER HEAD GASK	1
B	R	VO-21447682	GASKET	1
B	R	VO-943177	O-RING OIL COOLER - GREEN	1
B	R	VO-20483919	HEX. SOCKET SCREW	6
B	R	VO-21050240	FLANGE BOLT M14 x 80mm	1
B	R	VO-984738	FLANGE BOLT M8 x 40mm Black	2
B	R	VO-990810	FLANGE BOLT M12 x 45mm	6
B	R	VO-995658	O-RING	1
B	R	VO-994447	FLANGE BOLT M8 x 25mm Black	6
B	R	VO-20479636	SEALING STRIP	1
B	R	VO-1547254	SEALING RING - BLACK	2
B	R	VO-975697	O-RING	1
B	R	VO-20430678	SEALING RING	1
B	R	VO-1547252	SEALING RING - BLACK	1
B	R	VO-471708	SEALING RING - BLACK	1
B	R	VO-925063	O-RING INJ HARNESS D16C	1
B	R	VO-20526428	SEALING RING - PURPLE	1
B	R	VO-1677370	SEALING RING - PURPLE	2
B	R	VO-21024032	DOWTY WASHER O.D. 26mm	2
I	R	AU2-PERM84101	PX EPOXY 5 MIN GENP	1
B	R	VO-983472	CABLE TIE, Injector Harness	8
B	R	VO-8131393	CAGE	4
B	R	VO-85136742	FILTER KIT	1
B	R	VO-22275838	SEALING RING - PURPLE	2
B	R	VO-21092243	SEALING RING - PURPLE	6
B	R	VO-994445	FLANGE BOLT M8 x 16mm Black	6
B	R	VO-984740	FLANGE BOLT M8 x 60mm Black	4
B	R	VO-22206133	TURBO FEED GASKET	1
B	R	VO-469601	O-RING TURBO - GREEN	1
B	R	VO-21940615	SEALING RING - PURPLE	1
B	R	VO-471626	SEALING RING - GREEN	6

PC	Type	Code	Description (Original)	#
		VO-20526428	SEALING RING - PURPLE	1
		VO-949656	O-RING INJ.HA D9A/D12C - GREEN	1
		VO-994441	FLANGE BOLT M8 x 50mm Black	1
		VO-990950	FLANGE NUT CRIMP M8	1
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-3979639	GASKET PREHEATER	2
		VO-21282255	GASKET INL MANIFOLD	1
		VO-20852764	DOWTY WASHER O.D. 22mm ID 14mm	4
		VO-20852765	DOWTY WASHER O.D. 24mm	4
		VO-85103205	GREEN PAINT	1
		VO-21344774	FLANGE BOLT M10 x 50mm Grey	6
		VO-948610	O-RING	2
		VO-22718180	13L KIT - HI -TEMP TURBO MTG	1
		AU2-CAL85121795	ENGINE OIL BULK*	33
		AU2-9718-240002743	BBC4 BRAKE CLEANER	3
		VO-20784537	GASKET TURBO BASE	1
		VO-85020372	TURBOCHARGER, EXCH	1
		VO-276948	O-RING KIT	5
		VO-1547254	SEALING RING - BLACK	2
		VO-85013271	UNIT INJECTOR, EXC FM/FH (4)	1
		VO-21503575	SEALING RING - BLACK	1
		VO-8192804	SCREW	8
		VO-8148729	CONNECTOR	1
		VO-944126	O-RING INJ HARNESSD9B/D12D/D13	1
		VO-21503575	SEALING RING - BLACK	1
		VO-21719872	V-CLAMP	1
		VO-2112600	Cylinder head, replace	11.4
		VO-21253770	CYLINDER LINER KIT	1
		VO-21610676	BEARING SHELL	1
		VO-990861	FLANGE BOLT M10 x 30mm Grey	24
		VO-21092243	SEALING RING - PURPLE	4
		VO-22275838	SEALING RING - PURPLE	2
		VO-994445	FLANGE BOLT M8 x 16mm Black	1
		VO-85022413	EXCH CLY HEAD - D13C/D	1
		VO-21510072	CYLINDER HEAD GASK	1
		VO-994447	FLANGE BOLT M8 x 25mm Black	7
		VO-990810	FLANGE BOLT M12 x 45mm	6
		VO-21447682	GASKET, UPPER T/COVER	1

PC	Type	Code	Description (Original)	#
		VO-8192804	SCREW	8
		VO-22879256	CAMSHAFT BEARING K	6
		VO-22879257	CAMSHAFT BEARING K	1
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-21282255	GASKET	1
		VO-21344774	FLANGE BOLT M10 x 50mm Grey	6
		OTH-FAB1	TAPE MASKING 48MM	1
		AU2-9718-240002743	BBC4 BRAKE CLEANER	3
		VO-21261987	GASKET	6
		VO-276948	O-RING KIT	6
		VO-994441	FLANGE BOLT M8 x 50mm Black	1
		VO-990950	FLANGE NUT CRIMP M8	1
		VO-21211715	V-CLAMP	1
		VO-22206133	TURBO FEED GASKET	1
		VO-420643	TURBO DRAIN GKT	1
		AU2-CAL85121795	ENGINE OIL BULK*	33
		VO-984733	FLANGE BOLT M8 x 16mm Black	1
			knock in engine after start up	
		VO-2135700	Piston and liner, replace (one). Cylinde	1.9
			Cylinder head and sump removed	
		VO-2170600	Oil sump, remove	0.3
		VO-2170800	Oil sump, install	1
			ENGINE BLOWING WHITE SMOKE - TAMWORTH	
		VO-2135700	Piston and liner, replace (one). Cylinde	1.9
			Cylinder head and sump removed	
		VO-2170600	Oil sump, remove	0.3
		VO-2170800	Oil sump, install	1
		VO-2220700	Oil filter, engine, replace. Incl. by-pa	0.2
			by-pass filter, excl. oil change	
		LO-255	TURBO COMPRESSOR	0.01
			Old Serial number: TW1706186323	
			New Serial Number: TW1904175406	
			Mileage: 902350	
			Hrs: 11543	
			TOWED IN - POSSIBLE DROPPED VALVE.	
		LO-451	refit driveshaft after tow to dealership	0.2
			ATTENDED THE BREAKDOWN AND DIAGNOSED IT HAS A DROPPED	
			VALVE THIS IS AN INFORMATION GIVEN BY . THE HEADS	

PC	Type	Code	Description (Original)	#
	📄		WAS REPLACED 200K AGO.	
<b>🔍 2019-08-05 - Mileage: 826820 - Order nr: 8118018</b>				
🔧	*	352	LH Headlamp Panel	
🔧	📄	VO-21874450	PANEL H/LAMP LH	1
🔧	📄	VO-82884080	AIR DUCT	1
🔧	*	30		
<b>🔍 2018-11-13 - Mileage: 653416 - Order nr: 8268119</b>				
🔧	🔧	LO-430	RECTIFY VEHICLE NOT SELECTING GEARS	1
	📄		WILL GET LOW AND DRIVE BUT NOTHING ELSE	
🔧	🔧	VO-1921200	Transfer time to breakdown site and back	1
🔧	*	92	UTE MILEAGE 27 km's Ö Å1.48/km.	
🔧	📄	VO-22647976	GEAR SELECTOR	1
	📄		& RETURN TO WORKSHOP	
	📄		Travelled to vehicle and spoke with driver. His	
	📄		description sounded like transmission going into limp	
	📄		mode. Connected laptop and checked faults. None relevant.	
	📄		Visually checked gear selector. Limp button on back of	
	📄		selector seems to be stuck in. Performed selector test	
	📄		with laptop. Limp button stuck on. Removed and replaced	
	📄		selector, cleared codes and tested operation, all OK	
🔧	*	91	WORKSHOP CONSUMABLES	
<b>🔍 2018-11-12 - Mileage: 653169 - Order nr: 8109230</b>				
🔧	*	M	PLEASE FILL IN	
	📄			
🔧	🔧	LO-3000	recalibrate ecu's as required.	0.7
🔧	🔧	LO-430	slow to get into reverse	0.7
	📄		Mileage:653169	
	📄		Hrs:	
	📄		Next Service:	
	📄		Reprogrammed DACC. Checked for codes and tested for	
	📄		Reprogrammed Transmission ECU. Checked for codes and	
	📄		tested for operation.Ok.	
	📄		operation.Ok.	
🔧	*	91	WORKSHOP CONSUMABLES	
<b>🔍 2018-10-23 - Mileage: 660462 - Order nr: 8108400</b>				
🔧	*	818	Rear cab air bag insulators	
🔧	📄	MK-9739-16488479	CAB AIR BAG ISULAT	2
<b>🔍 2018-09-03 - Mileage: 623441 - Order nr: 8106261</b>				

PC	Type	Code	Description (Original)	#
		VO-4132000	Clutch cylinder, replace. Gearbox remove	0.2
		VO-2112600	Cylinder head, replace	8.4
		VO-85013933	CYL HEAD, EXC - FM(4) / FH(4)	1
		VO-20538793	SEAL STRIP, R/COVER GASKET	1
		VO-276948	O-RING KIT	6
		VO-8192804	SCREW	8
		VO-21282255	GASKET	1
		VO-21503575	SEALING RING	2
		VO-21447682	GASKET	1
		VO-20852765	DOWDY WASHER O.D. 24mm	4
		VO-20526428	SEALING RING	1
		VO-20855371	GASKET EXH/MANIFOLD	6
		VO-471708	SEALING RING	1
		VO-22206133	TURBO FEED GASKET	1
		VO-20479636	SEALING STRIP	1
		VO-420643	TURBO DRAIN GKT	1
		VO-1547254	SEALING RING	2
		VO-21940615	SEALING RING	1
		VO-1677370	SEALING RING	2
		VO-994447	FLANGE SCREW	6
		VO-990810	FLANGE BOLT M12 x 45mm	6
		AU2-CAL85108913	VOLVO VCS COOLANT - 5LTR	1
		VO-948211	STRIP CLAMP	15
		VO-21344774	FLANGE BOLT M10 x 50mm Grey	6
		AU2-CAL85121799	VDS4 ENG OIL 5L	1
		VO-21510072	CYLINDER HEAD GASK	1
		MK-9718-BBC4	Brake Cleaner 400G	1
		VO-20483426	SEALING RING- INPUT SEAL	1
		VO-85013166	CYLINDER	1
		MK-9718-BBC4	Brake Cleaner 400G	2
		VO-990818	STUD	2
		VO-990951	FLANGE NUT CRIMP M10	2
		VO-22485772	SEALING KIT	1
		VO-20860677	SEALING RING	1
		MK-NARV56306	CABLE TIE 1=25PK	1
		VO-995906	HEXAGON SCREW	4
		VO-25339078	HEX NUT M14 FINE (11MM)	4
		VO-22879256	CAMSHAFT BEARING K	1



PC	Type	Code	Description (Original)	#
		VO-20938963	SEAL	1
		VO-21433769	SEALING RING	2
		VO-22343361	CABLE HARNESS - FM/FH(4)	1
		AU2-PERM84101	PX EPOXY 5 MIN GENP *	1
		VO-983472	CABLE TIE, Injector Harness	8
		VO-1161963	RUBBER GREASE	1
		VO-20784537	GASKET TURBO BASE	1
		VO-995680	HOSE CLAMP	1
		VO-2860000	Engine wires and mounting parts. Seconda	5
		VO-8131393	CAGE	4
		MK-NARV56310	CABLE TIE 1=10PK	1
		VO-22996281	VACUUM SWITCH	1
		VO-990037	BULB H/LAMP H7 24V 70W	1
			Head change over.	
		VO-2117700	Cylinder head, transfer parts	0.5
		VO-3510400	Headlight bulb, replace (one). 1 unit, e	0.1
			excludes headlight adjustment	
			removed	
		VO-4317000	Gearbox, remove	0.9
		VO-4317200	Gearbox, install	1.5
		VO-4313100	Sealing ring input shaft, replace. Gearb	1.5
			Gearbox removed	
			Clutch fault codes.	
		VO-4007000	Clutch, gearbox, pulling position, calib	0.2
			calibration	
	*	97	ENVIRONMENTAL CHARGE	
	*	91	WORKSHOP CONSUMABLES	
<b>2018-04-26 - Mileage: 539396 - Order nr: 8101052</b>				
	*	352	Headlamp surround broken R/H side	
		VO-21874457	PANEL H/LAMP RH	1
		VO-82884084	AIR DUCT	1
	*	30	Paint and reinforce R/H headlamp panel	
<b>2018-03-13 - Mileage: 528819 - Order nr: 8099237</b>				
		VO-8842000	Airbag module, replace	0.3
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
	*	M		
		LO-3000	Dash faults.	1.6

PC	Type	Code	Description (Original)	#
	🔧		HARD RESET INSTRUMENT CLUSTER, CHECKED OPERATION.	
🔧	🔧	VO-84433698	AIRBAG MODULE	1
	🔧		(DACU) FCW HUD POWER SUPPLY CIRCUIT SHORT TO BATTERY OR	
	🔧		OPEN CIRCUIT. REMOVE DASH PANEL, FOUND 2 PINS IN PLUG LOOSE.	
	🔧		SECURED CONNECTIONS & ERASED ALL FAULT CODES. ROAD TEST	
🔧	*	91	WORKSHOP CONSUMABLES	
<b>🔍 2018-02-02 - Mileage: 497541 - Order nr: 8097227</b>				
🔧	*	371	Battery earth terminal fracture	
🔧	*	30	Sublet to CMV	
	🔧		Travel to vehicle at Morundah. Inspect and found earth	
	🔧		cables to chassis broken off at chassis. Remove and repair	
	🔧		cable and refit to vehicle. test, all ok. Return home.	
<b>🔍 2018-01-23 - Mileage: 497541 - Order nr: R08008858</b>				
🔧	🔧		customer reported no battery power	
🔧	🔧	VO-3730000	REMOVE, REPAIR AND REFIT BROKEN CABLE	6.66
<b>🔍 2017-10-11 - Mileage: 394425 - Order nr: 8092880</b>				
🔧	*	258	Ad-Blu filler neck leaking	
🔧	🔧	VO-23121198	FILLER NECK	1
<b>🔍 2017-05-02 - Mileage: 318735 - Order nr: 8085791</b>				
🔧	*	2540000	Ad-Blu filler neck broken	
🔧	🔧	VO-22022508	FILLER NECK	1
<b>🔍 2017-01-03 - Mileage: 257364 - Order nr: 8081933</b>				
🔧	🔧	VO-2510400	Gaskets, exhaust manifold, replace	1.8
🔧	🔧	VO-20784537	GASKET TURBO BASE	1
🔧	🔧	VO-21344787	FLANGE BOLT M10 x 90mm Black	12
🔧	🔧	VO-22655437	SPACER SLEEVE - S/STEEL	10
🔧	🔧	VO-993811	FLANGE BOLT M10 x 50mm Black	4
🔧	🔧	VO-20573472	SPACER SLEEVE	4
🔧	🔧	VO-420643	TURBO DRAIN GKT	1
🔧	🔧	VO-469601	TURBO O-RING	1
🔧	🔧	VO-21940615	SEALING RING	1
🔧	🔧	VO-420641	TURBO FEED GKT	1
🔧	🔧	VO-20526428	SEALING RING	1
🔧	🔧	MK-9718-BBC4	CLEANER 400G BRAKE	1
🔧	🔧	VO-20855371	GASKET EXH/MANIFOLD	6
🔧	🔧	VO-20883450	SEALING RING	2
🔧	🔧	VO-1161963	RUBBER GREASE	1
🔧	🔧	AU2-WUR0673205010	NYLON POWER LOC 2I	2

PC	Type	Code	Description (Original)	#
		VO-85103205	GREEN PAINT	1
		VO-21312238	CHARGE AIR HOSE	1
		VO-20592787	CLAMP	2
			C3628 Cab, interior lights, cable harness, install. FH (4)	
		LO-3540800	C3628 Interior light cable harness	0.5
			S3652 ACM, SW update. FH/FM (4)	
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		20	Sublet to EE to machine manifold	
		VO-22935545	WIRES	8
		VO-21887528	ACTUATOR SERVICE K	1
		VO-2530400	Solenoid valve exhaust brake, replace	0.6
		LO-261	Charge air hose, replace	1.2
		VO-2549400	ACM, SW, update. only campaign	0.2
		VO-1820200	Localised wash for fault tracing	0.3
		VO-8131393	CAGE	1
		VO-983472	CABLE TIE, Injector Harness	8
		97	ENVIRONMENTAL CHARGE	
		91	WORKSHOP CONSUMABLES	
<b>2016-11-04 - Mileage: 222191 - Order nr: 8079731</b>				
		M	PLEASE FILL IN	
			Mileage:222191	
		LO-3000	Adjust speed to 100km/h	1.5
			only doing 97km/h	
			Hrs:2842	
		91	WORKSHOP CONSUMABLES	
<b>2016-06-30 - Mileage: 150299 - Order nr: 8075540</b>				
		252	SILENCER AND EXHAUST LINE	
		258	Ad-Blu filler neck	
		VO-22321908	EXHAUST PIPE	1
		VO-22022508	FILLER NECK	1
<b>2016-06-30 - Mileage: 145106 - Order nr: 8074924</b>				
		VO-1702600	Program control unit	0.1
		VO-22861085	REPAIR KIT	1
		LO-8600100	C3538 Cab tilt pump, filler plug	0.5
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-4005300	Clutch pulling position, calibration	0.3
<b>2016-05-11 - Mileage: 114154 - Order nr: 8073034</b>				

PC	Type	Code	Description (Original)	#
		VO-4650000	Final drive (front and rear). Secondary	12.5
		VO-20701331	DIFFERENTIAL CARRI	1
		MK-9718-BBC4	CLEANER 400G BRAKE	1
		AU2-WURNBB0000853	NYLON POWER LOC 2I	2
		VO-3092340	SILASTIC GREY	1
		VO-990312	FLANGE NUT M16 Grey	4
		VO-995906	HEXAGON SCREW	8
		VO-25339078	HEXAGON NUT	8
		AU2-CAL85121715	GEAR OIL 85W140 BULK	20
		VO-3199066	SEAL RING	2
		VO-949329	COPPER WASHER	1
		VO-984849	HOUSING, 4 PIN	1
		VO-984846	CABLE TERMINAL	2
		VO-20734499	ANTI-TAMPER SEALIN	2
		VO-970771	CABLE SEAL	2
			TRUCK IS BROUGHT IN (FLOATED) BY NOLANS.	
		97	ENVIRONMENTAL CHARGE	
			Replace damaged rear drive centre. Degrease and steam clean	
			Rear drive axle, mudguard assemblies, rear chassis rails and	
			ice maker as it?s covered in diff oil.	
			Please Note: This does not include removal of rear wheel hub	
			assemblies to inspect inner hub seal or hub bearings for	
			any metal contaminates. Hub bearings are not serviceable and	
			Will need to be replaced if contaminated.	
			Extra time was taken to repair the melted diff sensor wiring	
		91	WORKSHOP CONSUMABLES	
<b>2016-05-01 - Mileage: 5 - Order nr: 202500</b>				
		96000		0
<b>2016-04-05 - Mileage: 90940 - Order nr: 8071670</b>				
		VO-2530400	Solenoid valve exhaust brake, replace	0.5
		VO-21887528	ACTUATOR SERVICE K	1
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
		VO-1701200	Fault codes, reading	0.2
		VO-2533600	Engine brake function, test	0.4
		VO-2534000	Warm hold function, test	0.2
<b>2016-04-01 - Mileage: 4 - Order nr: 202500</b>				
		96000		0
<b>2016-03-01 - Mileage: 3 - Order nr: 202500</b>				

PC	Type	Code	Description (Original)	#
		96000		0
<b>  2016-02-25 - Mileage: 61998 - Order nr: 8070223</b>				
	*	601	Deliver unit to Straight wheels	
	*	50	Sublet --- Straight wheels.	
			STEER	
			WHEEL ALIGN STEER & SET	
			TOE-IN	
			DRIVE	
			WHEEL ALIGN DRIVE AXLE	
			VOLVO FH13 REGO:QV11BC	
			61986KLMS	
			CARRIED OUT TOE SETAND	
			CENTERED STEERING	
			WHEEL, ALIGNED BOTH	
			DRIVES AS REQUESTED.	
			REQUIRES AXLE OUT	
			CASTOR CORRECTION AS	
			EVEN CASTOR AND ALSO	
			CAMBER CORRECTION	
			RIGHT SIDE. NOTIFIED	
			CUSTOMER OF WORKED	
			REQUIRED AND NEEDS TO	
			BE REBOOKED TO BE	
			CARRIED OUT.	
<b>  2016-02-01 - Mileage: 2 - Order nr: 202500</b>				
		96000		0
<b>  2016-01-11 - Mileage: 20206 - Order nr: 8068459</b>				
	*	M	Next Service Due:49,000KM OR 11/04/16.	
		VO-1721000	Warranty service. After 4 weeks or maxim	2
<b>  2016-01-01 - Mileage: 1 - Order nr: 202500</b>				
		96000		0
<b>  2015-11-12 - Mileage: 384 - Order nr: 8066317</b>				
		VO-1701000	Connect-disconnect of diagnostic tool	0.2
			S3485 Instrument cluster, SW update. FH/FM (4)	
		VO-3815800	IC, SW update. Campaign only	0.3
<b>  2015-11-11 - Mileage: 348 - Order nr: 8066241</b>				
		LO-856	Bunk Hinge Mounting	1

PC	Type	Code	Description (Original)	#
<b>2015-11-10 - Mileage: 68 - Order nr: 8065410</b>				
		LO-171	PRE DELIVERY WITH PLATES	6.5
	*	MTELEC186	RIVETS	
	*	10	VEHICLE DETAIL	
	*	10	TARE WEIGHT	
	*	10	CUSTOM BADGE	
		LO-350	3 LED LIGHTS TO EACH MIRROR	3.75
		LO-350	3 LED LIGHTS TO EACH SIDE OF CAB	3.6
		LO-852	DRIVERS SEAT SHEEP SKIN COVER	0.5
			NOLANS LOGO	
		LO-863	WEATHERSHIELDS LEFT AND RIGHT	1.6
	*	860	NOLANS PARS KIT	
		LO-360	CALIBRATE LOAD SCALES SOFTWARE IN TRUCK	1
		LO-350	RELOCATE EXISTING REAR OF CAB WORK LIGHT	3
			Å300 labour	
		LO-610	IMEX FULL STAINLESS STEEL DRESS RING	1.35
			Å492	
		LO-360	PROGRAM 4 MINUTE IDLE SHUT DOWN	1
		LO-360	ENSURE 12 & 24 VOLT PLUGS ARE LED OK	1
	*	610	STEER TYRE & VOLVO POLISHED DURABRITE RI	
			GOODYEAR S100 295/80.22.5	
		LO-250	EXHAUST TAIL PIPE CHANGE	1.5
	*	10	WINDOW TINT	
	*	20	EXHAUST	
		LO-360	CHECK IF FMS IS FITTED	0.5
		OTH-VSHEEPNOLANSRH	SHEEPSKIN NOLANS	1
		OTH-26260CK	LUCIDITY MARKER WHITE STAINLES	6
		VO-25087755	TORX SCREW M4 x 16mm Silver	12
		VO-990976	LOCK NUT	12
		MK-NARV56707	TUBING 7MM 1=10M	1
		OTH-AMB25B	STICKY PAD	8
		OTH-26260AK	LUCIDITY MARKER AMBER STAINLES	6
		VO-21244697	RELAY	1
		VO-25087755	TORX SCREW M4 x 16mm Silver	12
		VO-25392050	RELAY RETAINER	1
		VO-949597	SLEEVE LOCKING	5
		VO-979002	TERMINAL FEMALE	5
		VO-990976	LOCK NUT	12

PC	Type	Code	Description (Original)	#
		VO-84165756	WEATHERSHIELD (FH4)	1
		VO-990060	CABLE TERMINAL	6
		VO-20378934	FUSE, BLADE MINI 10 AMP	1
		VO-20464675	V-RIBBED BELT	1
		VO-22275091	V-RIBBED BELT	1
		VO-22273743	HOSE	1
		VO-21133830	HOSE	1
		VO-FK18B	FILTER KIT	1
		MK-37AX138U	WASHER	4
		VO-25154637	WASHER	8
		MK-9711-4017RSVVS6S	DRESS DISC H/CAP	1
		VO-8394442	CLIPS, HUBCAP FIT	12
		60	RIM SWAP	
		VO-25171459	TORX SCREW M4 x 18mm	12
		VO-8141219	Grommet, antenna coaxial cable	2
		MK-NARV56650	DUAL WALL HEAT SHR	1
		MTELEC6	4000- Twin Core Cable	
		VO-984849	HOUSING, 4 PIN	1
		VO-20738621	CABLE JOINT	4
		VO-984846	CABLE TERMINAL	4
		MK-NARV56306	CABLE TIE 1=25PK	1
		VO-3985597	ADAPTER STRAIGHT	1
		MTELEC6	4000- Twin Core Cable.	
		MTELEC90	4000- YELLOW SPLICE JOINERS	
		MTELEC26	4000- 7mm conduit	
		MTELEC26	4000- 7mm conduit.	
		AU2-22606571	WHEEL 22.5 X 8.25	1
			Å600	
			Å250	
			Å363	
			Å600	
			TO STEER AXLE	
			CHROME NUT COVERS TO ALL AXLES	
			HUBCAPS TO REAR AXLES	
			1.5 labour plus parts	
			TO THE AERO KIT SIDE WINGS	
			CHECKED. REPOSITIONED PLUG FROM UNDER DASH AS FUTURE FLEET	

PC	Type	Code	Description (Original)	#
	🔍		COMPLAINED THEY COULD NOT FIND THE PLUG	
ⓘ	*	MTELEC6	4000- Twin Core Cable..	
ⓘ	*	MTELEC26	4000- 7mm conduit..	