

Job Card

NSW | VIC | QLD | SA

ALLLIFT
F O R K L I F T S
& A C C E S S E Q U I P M E N T

A.B.N. 85 633 838 561

PO Box 6705
Silverwater B.C. NSW 2128

P
F

Customer Details:

WO Number: RPB069411
Date: 27/11/2023
Deliver Time
Work Type: Retail - Onsite Serv

Meter Reading: 5549	Customer PO:	Brand: JCB
Item No:	Model: 550-140 Serial Number: 1528852	Technician: Subcontractor

Task Description

2 Years / 2000 hours - Major Service & Comprehensive Machine Inspection & Checkover

Replace:

- Engine Oil & Filter
- Fuel Filter(s)
- Air & Cabin Filters
- Grease & Check All Fluid Levels
- Driveline, Axle & Hub Oils
- Transmission Filter & Oil
- Hydraulic Filter
- Hydraulic Breather
- Hydraulic oil (& any tank filters)
- Coolant
- Brake Fluid
- Complete Telehandler Safety Maintenance Log Book

Labour

<u>Technician</u>	<u>Work Required</u>	<u>Date</u>	<u>Hours</u>
-------------------	----------------------	-------------	--------------

<u>Part Code</u>	<u>Parts</u>
------------------	--------------

<u>Part Description</u>	<u>Qty</u>
-------------------------	------------

Customer:	Technician:
Print Name: _____	Print Name: _____
Signature: _____	Signature: _____
Contact No. _____	

Job Card

NSW | VIC | QLD | SA

ALLLIFT
F O R K L I F T S
& A C C E S S E Q U I P M E N T

A.B.N. 85 633 838 561

PO Box 6705
Silverwater B.C. NSW 2128

P
F

Customer Details:

WO Number: RPB069411
Date: 27/11/2023
Deliver Time
Work Type: Retail - Onsite Serv

Meter Reading: 5549	Customer PO:	Brand: JCB
Item No:	Model: 550-140 Serial Number: 1528852	Technician: Subcontractor

Customer:

Technician:

Print Name: _____

Print Name: _____

Signature: _____

Signature: _____

Contact No. _____

Type: Retail [] Warranty [] Internal [] Quote [] Service [] Repair [] Customer Damage []

Company	Address	
Contact	Date <i>13-06-23</i>	
Phone	Order # <i>RPB065769</i>	

Make	JCB	Model	550-140	Serial No	1528852
Unit No	167	Hours	5496		

Engine	I	R				Electrical	I	R
Replace engine oil and filter			Check bell crank/steer axle			Check starter motor/ring gear operation		
Check engine mounts			Check trunion bushes & lubricate			Check alternator and charging system		
Check for oil leaks			Check wheel bearings			Fill battery		
Replace spark plugs			Cooling system	I	R	Check lights		
Replace air filter			Check water pump			Check motion alarm		
Check leads			Check radiator & cap			Check horn operation		
Check ignition system			Check for water leaks			Check all gauges and meters operational		
Check fuel system			Check all cooling hoses			Visual		
Replace fuel filter			Check over flow system & coolant level			Check seat for rips and runners		
Check air intake hoses & filter housing			Brakes			Check all tyres and wheel nuts		
Check accelerator cable & linkages			Inspect brakes and record approx wear (%)			Paint/tyres and rims		
Check gas/fuel level			Adjust and test brakes			Check operators cab for cracks and safety		
Transmission			Check for leaks and safe operation			Check rating plate		
Replace oil and filter			Adjust and test hand brake			Check all safety decals fitted		
Check mounts			Mast/hydraulics			Check LPG plate		
Check for oil leaks			Check mast & carriage bearings			Check ALF decals		
Adjust inching & test			Adjust hoses and chains			Road test machine		
Check trans hoses			Lube chains			Complete service job and log book		
Check drive of unit			Check carriage and side shift			Bonnet catch and cable check		
Steering system			Check lift and tilt cylinders, mount, pins & bushes			General clean and detail of unit		
Check steering operation			Check hydraulic oil and filter			PARTS AND MATERIALS		
Check kingpins & bearings			Check tynne condition					
Check steer links & pins - tie rod ends			Check hydraulic hoses			QTY	Part No.	Description

FAULTS/REPORT CARRY OUT SOON

SENWICE.

- REPLACED 2x GREASE NIPPLES.

PARTS AND MATERIALS		
QTY	Part No.	Description
1	ALJCB7170	FRL
1	AL-JCB7124	FVER
1	AL-JCB9125759	ATL
1	AL-JCB804133	OL
1	AL-ADM32/917805	ATL
1	AL-JCB917804	ATL
1	AL-JCB9125346	HYD.
1	AL-JCB8563	TRANS.
1	AL-JCB85959	CABIN

Hydraulic Oil <u>20</u> Lts	Engine Oil <u>13</u> Lts	Gear Oil Lts
ATF Lts	Coolant Lts	

NOTED DAMAGES BOOM HOSES REAR LINE

REPLACING ASAP.

11. Front + rear diffs weeping
from centre + pinion seals.

Service Technician: OS4 W

Signature:

Date Completed: 13.6.23

Customer: _____ Signature: _____ Date: _____