A 25 Quarimor Rd, Bibra Lake WA 6163

T +61 8 9499 6500

F +61 8 9418 4160

E admin@amlequip.com.au

## INSPECTION CERTIFICATE

## 10 YEAR MAJOR INSPECTION

**CLIENT** 

**BIS INDUSTRIES** 

CONTACT

**GRAHAM DAVIS** 

INSPECTOR

**ANTHONY GROSSER** 

**TEST LOCATION** 

PERTH WORKSHOP

Plant Number

Road Registration

1BBW-836

Plant Registration

WC20221

Serial Number

3351

Make

Franna

Model

AT20

Year of Manufacture

2001

**Axles** 

2

Maximum Load

20T

(Tonne)

Hours

4035

**Kilometres** 

5.4 (new)

CraneSafe Report Number

AC 22645

Refer to attached report

Inspection Date

January 2016

This machine has completed its statutory inspection requirements and at the time of inspection was found to be in a safe working condition and complies with AS1418/ AS2550 major inspection guidelines and industry standards.

ANTHONY GROSSER: **QG**905569.

MACHINE IS CONSIDERED SAFE FOR USE AT THE TIME OF INSPECTION AND IS TO BE OPERATED AS PER THE MANUFACTURERS SPECIFICATIONS.



