



VEHICLE ASSESSMENT FORM

Vendor Number	71466
Item Number	565

Vehicle Details		Optional Accessories (Y / N)	
Year, Make & Model	1993 FORD FAIRLANE GHIA	ABS Brakes	Y
Body Type	SEDAN	Front Air Bags	N
Build Date	MAY-93	Side Impact Air Bags 1st Row	N
Compliance Date	MAY-93	Air Conditioning	Y
Engine Type & Capacity	6 CYL 4.0 LTR	Alloy Wheels	Y
Transmission	AUTOMATIC	Remote Central Locking	Y
Odometer (Showing)	356171	CD Player	Y
Registration Number	SOLD UNREGISTERED (NO PLATES)	Multi-Function Steering Wheel	Y
Registration Expiry		Electric Seats	N
Colour (Exterior / Interior)	RED / GREY	Power Windows	N
VIN / Chassis Number	6FPAAAJGLWPB92023	Satellite Navigation	N
Engine Number	NOT SIGHTED	Leather Trim	N
Engine turns over	Yes	Sunroof	N
Battery Condition	Starts	Roof Racks	N
Keys	Yes	Dual Fuel	Y
Spare Keys	No	Tow Bar	Y
Owner's Manual	No	DVD Player	N
Service History	None	Driving Lights	N
		Bull Bar	N
		Cruise Control	Y
		Park Assist	N
General Condition for Age & kms			
Seats & Upholstery	Good		
Floors	Good		
Controls and Dash	Good		
Paint	Fair		
Marks & Scratches - Location	Consistant for age		
Stone Chips - Location	Bonnet and F bumper		
Dents - Location	RHS F and R guard, LHS R guard and R door		
Other Damage	LHS R tailgate cracked		
Other Notes	Clear coat paint peel on roof and boot lid, Roof lining R/A, Check ABS light on, Key remote R/A		
Vehicle Location	19 Hewitt Street, Cheltenham, VIC, 3192		
Abbreviations	F - Front R - Rear	R/A - Requires Attention	RHS - Right hand side LHS - Left hand side

NOTE: This report is based on an external walk around and engine start-up only – the vehicles are not driven. There may be other damage, mechanical issues or body blemishes that have not been sighted or contained in this report, therefore a full inspection is highly recommended. This report is intended as a guide only.

Please note: When buying a car at Auction you will not have the same statutory warranty, cooling-off period or Certificate of Roadworthiness you would receive when buying from a licensed motor car trader.