

Truck "A" Inspection / Service Report



Truck ID:	M93	Date:	2/6/21
Current kms:	335451	Next Due kms:	330k

Item	Condition	Action Required / Comments	Rectified
Grease (where applicable)	Good / Faulty		
Check Engine Oil Level	Good / Faulty		
Check Washer Fluid	Good / Faulty		
Check Clutch Adjustment	Good / Faulty		
Check Lamp Function	Good / Faulty		
Check Wiper Condition / Function	Good / Faulty		
Check Horn Operation	Good / Faulty		
Check Door Lock Lubrication	Good / Faulty		
Check Battery Condition	Good / Faulty		
Check Drive Belt Condition	Good / Faulty		
Check for Fluid Leaks	Good / Faulty		
Check for Air Leaks	Good / Faulty		
Check Steering Components	Good / Faulty	Sway Bar movement / LH Shock Bush, Front Drive LH Shock Leak.	
Visual Check of Tyres	Good / Faulty		
Check Brake Adjustment (✓ or x)	Good / Faulty		
Check camera alignment	Visual / Program		

Further Action Read: Yes No : (list actions below)

Inspected By (Name):	Deana De	Signature:	
Mechanics Coordinator (Name):	DLS	Signature:	