

CARHISTORY.COM.AU DEALER REPORT INCLUDING A PPSR SEARCH

VEHICLE DESCRIPTION - WVGZZZ5NZJW810673

VIN : WVGZZZ5NZJW810673

Make : VOLKSWAGEN

Model : TIGUAN

Variant / Series : 110 TSI COMFORTLINE/ 5NA

Body : 4D WAGON

Year (first retail date) : 2017

Colour :

- Primary WHITE

- Secondary



*Picture provided is a sample only

REPORT SUMMARY

No odometer history reported

No Encumbrances reported

Written-Off Status reported

No Stolen Status recorded

Insurance Claims not available

IDENTIFICATION

Engine Number : CZE496870

Plate

Registered State : QLD

VEHICLE STATUS

Last Odometer Reading : 85716

Last Sale Listing

Rego. Expiry Date

Warranty Expiry Date

VEHICLE RATINGS

ANCAP Safety Rating

Air Pollution Rating

Greenhouse Rating :

Overall Green Rating

VEHICLE DETAILS

Fuel Type : PREMIUM UNLEADED PETROL

Engine Size : 1.4L

Cylinders/Rotors : T4

Fuel Consumption

Transmission : 6 SP AUTO DIRECT SHI

Power (KW) : 110

Torque (Nm) : 250

FIRST SALE DATA

First Sale Date : 15-09-2017

First Sold in Postcode : 3179

First Buyer Type : PRIVATE

REPORTED ODOMETER HISTORY No odometer history reported Kilometers Date Reported Notes 85716 03/08/2022 Odometer History Graph → Your Car Low Average High 100000 80000 60000 40000 20000 2021 2023 2017 2019 Years

REPORTED SALES LISTING

The below is a list of known sales listings for your vehicle

Price Date Reported Where

REPORTED INSURANCE CLAIMS

Insurance Claims Not Available

FINANCE CHECK

No Encumbrances reported

PPSR has reported that this vehicle has no encumbrances

Encumbrance: NO

VEHICLE HISTORY

Written-Off Status

Written-off: Impact | Passenger front | Heavy structural

Impact | Driver front | Heavy structural

Impact | Driver rear | Heavy structural

Impact | Passenger rear | Heavy structural

Impact | Interior | Light panel

Impact | Chassis/structural rail (passenger) | Light structural

Impact | Chassis/structural rails (driver) | Light structural

Date recorded: 25 Jun 2019

State recorded: QLD

Type: Inspected

Written-off: Impact | Chassis/structural rails (driver) | Light structural

Impact | Driver front | Heavy structural

Impact | Passenger front | Heavy structural

Impact | Passenger rear | Heavy structural

Impact | Driver rear | Heavy structural

Impact | Chassis/structural rail (passenger) | Light structural

Impact | Interior | Minor mechanical damage

Date recorded: 08 Nov 2018

State recorded: VIC

Type: Repairable Write-off

Written-off: Malicious/vandalism/stripped | Driver rear | Major vandalism

Malicious/vandalism/stripped | Interior | Major vandalism

Date recorded: 28 Jan 2022

State recorded: QLD

Type: Repairable Write-off

Stolen Status NO STOLEN STATUS RECORDED ON THIS VEHICLE

CERTIFICATE NUMBER (VCN)

For any individual to be able to access this report, simply provide them with the following link or Certificate Number (VCN).

URL Link:https://secure.carhistory.com.au/VCN.aspx?VCN=A5-FSCG

VCN:A5-FSCG





VIN

03-08-2022

Serial Number Search Certificate

This is a serial number search certificate for a serial number search

This search certificate is provided under section 174 of the Personal Property Securities Act 2009

Search certificate number: 9249999553180001 Search number: 924999955318

This search certificate reflects the data contained in the PPSR as 03-08-2022 10:27:33 (Canberra Time)

Search Criteria Details

Serial number search type: VIN

Motor vehicle: WVGZZZ5NZJW810673

PPSR Registration state searched: Current

PPSR Registration Details

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

Additional Motor Vehicle Details - NEVDIS

Identifier number: WVGZZZ5NZJW810673 Identifier type:

Vehicle type: CAR / SMALL PASSENGER VEHICLE Make: VOLKSWAGEN

Body type:STATION WAGONModel:TIGUANColour:WHITEEngine number:CZE496870

Registration plate number: No data recorded. State vehicle registered: QLD Registration expiry: No data recorded.

Year of manufacture: 2017 Year/Month of 2017-08

compliance:

NEVDIS Written off Vehicle Notifcation:

QLD, 25 Jun 2019, Inspected

- I01C [Impact | Passenger front | Heavy structural]
- I02C [Impact | Driver front | Heavy structural]
- I04C [Impact | Driver rear | Heavy structural]
- I05C [Impact | Passenger rear | Heavy structural]
- I09B [Impact | Interior | Light panel]
- I17D [Impact | Chassis/structural rail (passenger) | Light structural]
- I21D [Impact | Chassis/structural rails (driver) | Light structural]

VIC, 08 Nov 2018, Repairable Write-off

- I21D [Impact | Chassis/structural rails (driver) | Light structural]
- I02C [Impact | Driver front | Heavy structural]
- I01C [Impact | Passenger front | Heavy structural]
- I05C [Impact | Passenger rear | Heavy structural]
- I04C [Impact | Driver rear | Heavy structural]
- I17D [Impact | Chassis/structural rail (passenger) | Light structural]
- I09G [Impact | Interior | Minor mechanical damage]

QLD, 28 Jan 2022, Repairable Write-off

- M04J [Malicious/vandalism/stripped | Driver rear | Major vandalism]
- M09J [Malicious/vandalism/stripped | Interior | Major vandalism]

NEVDIS Stolen Vehicle Notification:

· Not recorded as stolen.

Tasmanian stolen vehicle information is currently unavailable from this service. For information about the status of Tasmanian vehicles, go to:

https://www.transport.tas.gov.au/MRSWebInterface/public/regoLookup/registrationLookup.jsf (Note: you will need to provide the vehicle registration plate number to search this site)

A stolen vehicle notification, or the absence of one, does not necessarily mean a vehicle is or is not stolen.

If there is a stolen vehicle notification you wish to enquire about, you should contact the police force in the State or Territory indicated immediately after the date in the notification. The reference number at the end of the notification should be quoted as a part of your enquiry.

Please note that there may be multiple stolen notifications shown. A stolen notification can be for a VIN, Plate, Chassis and/or Engine.

Vehicle information is requested from Austroads NEVDIS database for each transaction involving a vehicle VIN or Chassis Number on the PPSR. The data is not part of interests registered on the PPSR and it is presented without any guarantee regarding its accuracy.

The NEVDIS data is intended to assist users with checking that the VIN or Chassis Number they entered, along with information they have about the vehicle from other sources, is accurate and to provide users with any data held on NEVDIS about a vehicle's stolen or written off status.

State and territory road agencies are the source of NEVDIS data and the primary point of contact for enquiries, errors and corrections.

Access to and use of data provided through the PPSR is subject to the PPSR General Conditions of Use and applicable third party data conditions (which can be obtained at www.ppsr.gov.au). To the extent permitted by law, all data provided through the PPSR is made available without any representation or warranty of any kind (without limitation in respect to accuracy) and the Commonwealth, and our third party data providers (which includes any person mentioned in the Third Party Data Conditions as providing information through the PPSR), have no liability to you in respect of any loss or damage that you might suffer no matter how arising (including negligence) that is directly or indirectly related to the NEVDIS Data.

How to verify this certificate on the PPSR

You can use the search number from an original search (as shown on this certificate) to retrieve the original search results and to issue a copy of the search certificate at https://transact.ppsr.gov.au/ppsr/Home. There is no fee, however this process will not provide any update to the information in the original search.

Privacy and Terms and Conditions

The Australian Financial Security Authority is subject to the *Privacy Act 1988* which requires that we comply with the Australian Privacy Principles (APPs) set out in the Act. The APPs set out how Australian Government agencies should collect, use, store and disclose personal information and how individuals can access records containing their personal information.

Access to and use of the PPSR is subject to the General Conditions of Use, as well as other relevant terms and conditions. All relevant terms and conditions can be found at www.ppsr.gov.au

End of search certificate

EMAIL: enquiries@ppsr.gov.au WEBSITE: www.ppsr.gov.au

GPO Box 1944 Adelaide SA 5001 1300 00 77 77

| TERMS AND DEFINITIONS | |
|-------------------------------------|---|
| Terminology | Definition |
| Air Pollution Rating | The Air Pollution Rating is based on the level of air pollutant emissions allowable under the standard to which the particular |
| | vehicle has been successfully tested to for supply to the Australian market. |
| ANCAP Safety Rating | The Australasian New Car Assessment Program (ANCAP) gives consumers consistent information on the level of occupant |
| | protection provided by vehicles in serious front and side crashes. The score is a star rating, between 1 to 5 stars. The higher |
| | scores are awarded more stars. |
| Body | A vehicle's body type. |
| Cylinders/Rotors | Engine cylinder configuration. |
| Dealer Price | An indicative vehicle value for non-franchise dealer trade or wholesale transactions. Trade low must be adjusted for (Back 10 |
| | Years) kilometres and condition. Please refer to the 'Guide Condition' definition. |
| Dealer Trade Price | A median value achieved by a franchise dealer, e.g. Ford dealer would achieve for a Ford, (Back 10Years) for a vehicle in |
| | 'Guide Condition' and average kilometres. Please refer to the 'Guide Condition'. |
| Encumbrance reported | Vehicle has an outstanding finance. Ensure finance is cleared prior to purchase of vehicle. |
| Fuel Consumption | Vehicle fuel consumption. |
| Fuel Type | Recommended fuel type. |
| Make | Manufacturers name. |
| Model | Vehicle family. |
| No Registrations Found (PPSR | Means that there is no encumbrance registered on the PPSR for that serial number. |
| Certificate) | |
| Odometer Discrepancy Reported | The vehicle has odometer-related problems. These may include discrepancies such as not actual miles, a broken odometer, a |
| | mileage discrepancy, or suspect miles. |
| Overall Green Rating | The Overall Rating is based on the sum of the air pollution and greenhouse ratings. |
| Personal Price | The median price paid for a vehicle when purchased through a private transaction. |
| Plate | Vehicle Registration No. |
| Purpose of use | Type of use as registered with State Registration Offices. |
| Refer jurisdiction | Contact the registration authority displayed in the 'state of registration'. |
| Registered State | State of vehicle registration. |
| Registration Found (PPSR | Means that there are encumbrances registered on the PPSR for that serial number. |
| Certificate) | |
| Sales Listings | Sales listing data displays sales advertisements derived from various vehicle eCommerce sites. |
| Series Name | Series Name, Eg. VZ, VE, MY05, MY08. |
| Variant Name | Variant Name, Eg. GL, CSi, SPORTIVO, SS, Executive. |
| Vehicle Identification Number (VIN) | A unique alphanumeric combination of 17 characters assigned to a vehicle. It does not contain the letters I, O or Q. |
| Year (first retail date) | Is the first year the vehicle was sold and may or may not be the year in which the vehicle was manufactured. |
| GENERAL DISCLAIMERS | |
| Glass's | Glass's Information Services has exercised all reasonable care and skill in producing this information. Glass's Information |
| | Services gathers its information from independent sources within the motor trade, unconnected with it, and as a result can |
| | accept no responsibility for the accuracy or completeness of information. Furthermore, information on valuations supplied are |
| | |

intended as a guide only to current market value; they can not be considered in any way a substitute for a full and detailed

| GENERAL DISCLAIMERS | |
|-----------------------------|---|
| | inspection of any vehicle. |
| Insurance Claim Information | Equifax's Auto service gathers its Insurance Claim information from independent sources within the insurance industry and as |
| | a result can accept no responsibility for the accuracy or completeness of information. |
| General | This report is supplied on the Terms set out on the Auto website and accepted by you before you purchased this report. |
| No odometer discrepancies | Equifax's Auto service gathers odometer history from independent third party sources within the automotive industry and as |
| reported | a result can accept no responsibility for the accuracy or completeness of information. Equifax's Auto service recommends |
| | you review the vehicle's log books and service history in conjunction with the CarHistory report to determine the accuracy of |
| | the vehicle's odometer reading. |