

CarHistory Dealer Report & PPSR Certificate

Report generated on 15/05/2023

11939145

VIN	YV1CZ985681434631
Make	VOLVO
Model	XC90
Variant/series	3.2MY07
Body	4D WAGON
Transmission	6 SP AUTOMATIC GEART
Year (first retail date)	2007
Colour	GREY



*Picture provided is a sample only

QUICK SUMMARY



No stolen status reported



Written-off status reported



No financial interests reported



No odometer rollback reported



Vehicle registered

VEHICLE DETAILS



✓ Vehicle registered

VEHICLE REGISTRATION

Registration plate	437DF6
Registration state	QLD
Registration expiry date	02-12-2023

FIRST SALE INFORMATION

First sale date	31-10-2007
Postcode of first sale	2015
First buyer type	NON-PRIVATE

ENGINE DETAILS

Engine number	B6324S06070711134
Engine size	3.2L
Cylinders/rotors	6
Fuel type	PREMIUM UNLEADED PETROL
Power (KW)	175
Torque (Nm)	320

VEHICLE RATINGS

ANCAP safety rating	****
Overall green rating	-
Air pollution rating	-
Greenhouse rating	-



CarHistory notes:

Vehicle registration information is sourced via the PPSR. Refer to the PPSR Certificate below.

REPORTED ODOMETER HISTORY



No odometer rollback reported

LAST REPORTED ODOMETER READING


Kilometres	112,822
Date reported	24/10/2019

READING ENTERED BY YOU

Kilometres	142,516
Date reported	15/05/2023

The odometer history for this vehicle has been supplied to CarHistory by various sources within the automotive industry.

Kilometres	Date reported	Alerts
142,516	15/05/2023	
112,822	24/10/2019	
7,299	05/05/2008	
7,298	18/04/2008	
152	27/11/2007	





CarHistory notes:

CarHistory relies on data received from third parties. We recommend you review the vehicle's log book and service history to determine the accuracy of the vehicle's odometer reading.

REPORTED SALES LISTINGS

No known sales listings for this vehicle.



CarHistory notes:

Reported sales listings are sales advertisements derived from various ecommerce sites and provide an indication of how often the vehicle has been listed for sale.

FINANCE CHECK



No financial interests reported

PPSR has reported that this vehicle is not encumbered.



CarHistory notes:

Financial encumbrance information is sourced via the PPSR. Refer to the PPSR Certificate below.

WRITTEN-OFF CHECK



Written-off status reported

PPSR has reported that this vehicle has been written-off.

Written-off	Impact Passenger front Light panel Impact Driver front Heavy panel Impact Driver side Heavy panel Impact Driver rear Light panel
-------------	--

	Impact Passenger rear Light panel Impact Passenger side Light panel Impact A pillar driver Light structural
Date recorded	15 Oct 2020
State recorded	QLD
Туре	Inspected

Written-off	Impact Passenger front Light panel Impact Driver front Heavy panel Impact Driver side Heavy panel Impact Driver rear Light panel Impact Passenger rear Light panel Impact Passenger side Light panel Impact A pillar driver Light structural
Date recorded	21 Apr 2020
State recorded	QLD
Туре	Repairable Write-off



CarHistory notes:

Written-off information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

STOLEN CHECK



No stolen status reported

PPSR has reported that this vehicle is not stolen.



CarHistory notes:

Stolen information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

ACCESS YOUR REPORT ONLINE

To allow an individual to view this report online, simply provide them with the following link: https://secure.carhistory.com.au/vcn?vcn=A6-WJGR

GENERAL DISCLAIMERS

This report has been supplied on the <u>Terms and Conditions</u> set out on the CarHistory website, and accepted by you before you purchased this report.

The data used to compile this report has been sourced from various independent and Government sources, as a result CarHistory can accept no responsibility for the accuracy or completeness of information.

PPSR CERTIFICATE

The following certificate has been issued by the Australian Financial Security Authority.



15/05/2023

Serial Number Search Certificate

This is a serial number search certificate for a serial number search

This Search certificate is provided under section 174 of the *Personal Property Securities Act* 2009

 Search certificate number:
 4765658067850001

 Search number:
 476565806785

This search certificate reflects the data contained in the PPSR at 15/05/2023 11:41:00 (Canberra Time).

Search Criteria Details

Serial number search type: VIN

Motor vehicle: YV1CZ985681434631

PPSR registration state searched: Current

PPSR Registration Details

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

Additional Motor Vehicle Details - NEVDIS

Identifier number:YV1CZ985681434631Identifier type:VINVehicle type:CAR / SMALLMake:VOLVO

PASSENGER VEHICLE

Body type: STATION WAGON Model: XC90

Colour: GREY Engine number: B6324S06070711134

Registration plate number: 437DF6 State vehicle registered: QLD

Registration expiry: 02 Dec 2023

Year of manufacture: 2007 Year/Month of compliance: 2007-10

Important NEVDIS notifications about the Vehicle

Written-off:

QLD, 15 Oct 2020, Inspected

- I01B [Impact | Passenger front | Light panel]
- I02A [Impact | Driver front | Heavy panel]
- I03A [Impact | Driver side | Heavy panel]
- I04B [Impact | Driver rear | Light panel]
- I05B [Impact | Passenger rear | Light panel]
- I06B [Impact | Passenger side | Light panel]
- I23D [Impact | A pillar driver | Light structural]

QLD, 21 Apr 2020, Repairable Write-off

- I01B [Impact | Passenger front | Light panel]
- I02A [Impact | Driver front | Heavy panel]

This search certificate reflects the data contained in the PPSR at 15/05/2023 11:41:00 (Canberra Time).

- I03A [Impact | Driver side | Heavy panel]
- I04B [Impact | Driver rear | Light panel]
- I05B [Impact | Passenger rear | Light panel]
- I06B [Impact | Passenger side | Light panel]
- I23D [Impact | A pillar driver | Light structural]

Stolen:

· Not recorded as stolen.

Tasmanian stolen vehicle information is currently unavailable from this service. For information about the status of Tasmanian vehicles, go to:

https://www.transport.tas.gov.au/MRSWebInterface/public/regoLookup/registrationLookup.jsf (Note: you will need to provide the vehicle registration plate number to search this site).

A stolen vehicle notification, or the absence of one, does not necessarily mean a vehicle is or is not stolen.

If there is a stolen vehicle notification you wish to enquire about, you should contact the police force in the State or Territory indicated immediately after the date in the notification. The reference number at the end of the notification should be quoted as a part of your enquiry.

Please note that there may be multiple stolen notifications shown. A stolen notification can be for a VIN, Plate, Chassis and/or Engine.

Vehicle information is requested from Austroads NEVDIS database for each transaction involving a vehicle VIN or Chassis Number on the PPSR. The data is not part of interests registered on the PPSR and it is presented without any guarantee regarding its accuracy.

The NEVDIS data is intended to assist users with checking that the VIN or Chassis Number they entered, along with information they have about the vehicle from other sources, is accurate and to provide users with any data held on NEVDIS about a vehicle's stolen or written off status.

State and territory road agencies are the main source of NEVDIS data and the primary point of contact for enquiries, errors, and corrections.

Access to and use of data provided through the PPSR is subject to the PPSR General Conditions of Use and applicable third party data conditions (which can be obtained at www.ppsr.gov.au). To the extent permitted by law, all data provided through the PPSR is made available without any representation or warranty of any kind (without limitation in respect to accuracy) and the Commonwealth, and our third party data providers (which includes any person mentioned in the Third Party Data Conditions as providing information through the PPSR), have no liability to you in respect of any loss or damage that you might suffer no matter how arising (including negligence) that is directly or indirectly related to the NEVDIS Data.

How to verify this certificate on the PPSR

You can use the search number from an original search (as shown on this certificate) to retrieve the original search results and to issue a copy of the search certificate at https://transact.ppsr.gov.au/ppsr/Home.

There is no fee, however this process will not provide any update to the information in the original search.

Privacy and Terms and Conditions

The Australian Financial Security Authority is subject to the *Privacy Act 1988* which requires that we comply with the Australian Privacy Principles (APPs) set out in the Act. The APPs set out how Australian Government agencies should collect, use, store and disclose personal information and how individuals can access records containing their personal information.

Access to and use of the PPSR is subject to the General Conditions of Use, as well as other relevant terms and conditions. All relevant terms and conditions can be found at www.ppsr.gov.au.

This search certificate reflects the data contained in the PPSR at 15/05/2023 11:41:00 (Canberra Time).

End of search certificate

EMAIL: enquiries@ppsr.gov.au WEBSITE: www.ppsr.gov.au

GPO Box 1944 Adelaide SA 5001

1300 00 77 77