

# **CarHistory Dealer Report & PPSR Certificate**

Report generated on 29/05/2023

# REPORT ID 11978517

VIN	KMHTC61ELDU174206
Make	HYUNDAI
Model	VELOSTER
Variant/series	SR TURBOFS MY13
Body	3D COUPE
Transmission	6 SP MANUAL
Year (first retail date)	2013
Colour	GREY



\*Picture provided is a sample only

# **QUICK SUMMARY**



No stolen status reported



Written-off status reported



No financial interests reported



No odometer rollback reported



Vehicle unregistered

# **VEHICLE DETAILS**

• Vehicle unregistered

### **VEHICLE REGISTRATION**

Registration plate	1HRK140
Registration state	WA
Registration expiry date	22-05-2023

#### **ENGINE DETAILS**

Engine number	G4FJHU459703
Engine size	1.6L
Cylinders/rotors	T4
Fuel type	UNLEADED PETROL
Power (KW)	150
Torque (Nm)	265

### FIRST SALE INFORMATION

First sale date	23-10-2013
Postcode of first sale	6112
First buyer type	PRIVATE

#### **VEHICLE RATINGS**

ANCAP safety rating	-
Overall green rating	-
Air pollution rating	-
Greenhouse rating	-

#### CarHistory notes:

Vehicle registration information is sourced via the PPSR. Refer to the PPSR Certificate below.

# **REPORTED ODOMETER HISTORY**

No odometer rollback reported


### LAST REPORTED ODOMETER READING

# **READING ENTERED BY YOU**

Kilometres	133,479	Kilometres	152,550
Date reported	28/01/2021	Date reported	29/05/2023

The odometer history for this vehicle has been supplied to CarHistory by various sources within the automotive industry.

Kilometres	Date reported	Alerts
152,550	29/05/2023	
133,479	28/01/2021	
81,551	27/10/2017	
81,147	09/10/2017	
38,180	23/03/2016	



#### **CarHistory notes:**

CarHistory relies on data received from third parties. We recommend you review the vehicle's log book and service history to determine the accuracy of the vehicle's odometer reading.

### **REPORTED SALES LISTINGS**

No known sales listings for this vehicle.

#### CarHistory notes:

Reported sales listings are sales advertisements derived from various ecommerce sites and provide an indication of how often the vehicle has been listed for sale.

# **FINANCE CHECK**

#### No financial interests reported

PPSR has reported that this vehicle is not encumbered.

#### CarHistory notes:

Financial encumbrance information is sourced via the PPSR. Refer to the PPSR Certificate below.

# WRITTEN-OFF CHECK

#### Written-off status reported

PPSR has reported that this vehicle has been written-off.

#### Written-off

Impact | Passenger front | Light panel Impact | Driver front | Light panel Impact | Engine | Major mechanical damage

Date recorded	23 Aug 2022
State recorded	WA
Туре	Inspected

Written-off	Impact   Engine   Major mechanical damage Impact   Driver front   Light panel Impact   Passenger front   Light panel
Date recorded	23 Aug 2022
State recorded	WA
Туре	Repairable Write-off

Written-off	Impact   Engine   Major mechanical damage Impact   Driver front   Light panel Impact   Passenger front   Light panel
Date recorded	24 Dec 2021
State recorded	WA
Туре	Repairable Write-off

#### CarHistory notes:

Written-off information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

### **STOLEN CHECK**

### 🕑 No stolen status reported

PPSR has reported that this vehicle is not stolen.



#### CarHistory notes:

Stolen information is sourced via the PPSR. Refer to the PPSR Certificate below.

WARNING: We have no control over when third parties choose to report information or events and in some cases there may be a delay between when an event occurs and when that information is recorded, including via the National Exchange of Vehicle and Driver Information System (NEVDIS) or on the Personal Property Securities Register (PPSR).

### ACCESS YOUR REPORT ONLINE

To allow an individual to view this report online, simply provide them with the following link: <u>https://secure.carhistory.com.au/vcn?vcn=A5-FTKV</u>

### **GENERAL DISCLAIMERS**

This report has been supplied on the **Terms and Conditions** set out on the CarHistory website, and accepted by you before you purchased this report.

The data used to compile this report has been sourced from various independent and Government sources, as a result CarHistory can accept no responsibility for the accuracy or completeness of information.

### **PPSR CERTIFICATE**

The following certificate has been issued by the Australian Financial Security Authority.





29/05/2023

# Serial Number Search Certificate

This is a serial number search certificate for a serial number search

This Search certificate is provided under section 174 of the *Personal Property Securities Act* 2009

Search certificate number:	4838465395790001
Search number:	483846539579

This search certificate reflects the data contained in the PPSR at 29/05/2023 11:00:42 (Canberra Time).

# Search Criteria Details

Serial number search type:	VIN
Motor vehicle:	KMHTC61ELDU174206
PPSR registration state searched:	Current

# **PPSR Registration Details**

There is no security interest or other registration kind registered on the PPSR against the serial number in the search criteria details.

### Additional Motor Vehicle Details – NEVDIS

Identifier number:	KMHTC61ELDU174206	Identifier type:	VIN
Vehicle type:	CAR / SMALL	Make:	HYUNDAI
	PASSENGER VEHICLE		
Body type:	CAR/SEDAN	Model:	VELOSTER FS
Colour:	GREY	Engine number:	G4FJHU459703
Registration plate number:	1HRK140	State vehicle registered:	WA
Registration expiry:	22 May 2023		
Year of manufacture:	2013	Year/Month of compliance:	2013-10

### Important NEVDIS notifications about the Vehicle

### Written-off:

- WA, 23 Aug 2022, Inspected
  - I01B [Impact | Passenger front | Light panel]
  - I02B [Impact | Driver front | Light panel]
  - I07F [Impact | Engine | Major mechanical damage]
- WA, 23 Aug 2022, Repairable Write-off
  - I07F [Impact | Engine | Major mechanical damage]
  - I02B [Impact | Driver front | Light panel]
  - I01B [Impact | Passenger front | Light panel]
- WA, 24 Dec 2021, Repairable Write-off
  - I07F [Impact | Engine | Major mechanical damage]
  - I02B [Impact | Driver front | Light panel]

This search certificate reflects the data contained in the PPSR at 29/05/2023 11:00:42 (Canberra Time).

• I01B [Impact | Passenger front | Light panel]

### Stolen:

• Not recorded as stolen.

Tasmanian stolen vehicle information is currently unavailable from this service. For information about the status of Tasmanian vehicles, go to:

<u>https://www.transport.tas.gov.au/MRSWebInterface/public/regoLookup/registrationLookup.jsf</u> (Note: you will need to provide the vehicle registration plate number to search this site).

A stolen vehicle notification, or the absence of one, does not necessarily mean a vehicle is or is not stolen.

If there is a stolen vehicle notification you wish to enquire about, you should contact the police force in the State or Territory indicated immediately after the date in the notification. The reference number at the end of the notification should be quoted as a part of your enquiry.

Please note that there may be multiple stolen notifications shown. A stolen notification can be for a VIN, Plate, Chassis and/or Engine.

Vehicle information is requested from Austroads NEVDIS database for each transaction involving a vehicle VIN or Chassis Number on the PPSR. The data is not part of interests registered on the PPSR and it is presented without any guarantee regarding its accuracy.

The NEVDIS data is intended to assist users with checking that the VIN or Chassis Number they entered, along with information they have about the vehicle from other sources, is accurate and to provide users with any data held on NEVDIS about a vehicle's stolen or written off status.

State and territory road agencies are the main source of NEVDIS data and the primary point of contact for enquiries, errors, and corrections.

Access to and use of data provided through the PPSR is subject to the PPSR General Conditions of Use and applicable third party data conditions (which can be obtained at *www.ppsr.gov.au*). To the extent permitted by law, all data provided through the PPSR is made available without any representation or warranty of any kind (without limitation in respect to accuracy) and the Commonwealth, and our third party data providers (which includes any person mentioned in the Third Party Data Conditions as providing information through the PPSR), have no liability to you in respect of any loss or damage that you might suffer no matter how arising (including negligence) that is directly or indirectly related to the NEVDIS Data.

### How to verify this certificate on the PPSR

You can use the search number from an original search (as shown on this certificate) to retrieve the original search results and to issue a copy of the search certificate at <u>https://transact.ppsr.gov.au/ppsr/Home</u>. There is no fee, however this process will not provide any update to the information in the original search.

### **Privacy and Terms and Conditions**

The Australian Financial Security Authority is subject to the *Privacy Act 1988* which requires that we comply with the Australian Privacy Principles (APPs) set out in the Act. The APPs set out how Australian Government agencies should collect, use, store and disclose personal information and how individuals can access records containing their personal information.

Access to and use of the PPSR is subject to the General Conditions of Use, as well as other relevant terms and conditions. All relevant terms and conditions can be found at www.ppsr.gov.au.

### End of search certificate

EMAIL: enquiries@ppsr.gov.au WEBSITE: <u>www.ppsr.gov.au</u>

This search certificate reflects the data contained in the PPSR at 29/05/2023 11:00:42 (Canberra Time).

GPO Box 1944 Adelaide SA 5001

1300 00 77 77