

VEHICLE ASSESSMENT FORM

Vendor Number	71466
Item Number	508

Vehicle Details Optional Accessories (Y/N)1991 SUBARU LIBERTY GX Year, Make & Model **ABS Brakes** Ν SEDAN Ν **Body Type** Front Air Bags **Build Date** 1991 Ν Side Impact Air Bags 1st Row Υ JAN-91 **Compliance Date** Air Conditioning 4 CYL 2.0 LTR **Engine Type & Capacity** Ν Alloy Wheels **Transmission AUTOMATIC** Ν Remote Central Locking 247 875 Ν **Odometer (Showing)** CD Player **Registration Number** RRK179 SOLD UNREGISTERED (NO PLA Ν Multi-Function Steering Wheel **Registration Expiry Electric Seats** Ν Colour (Exterior / Interior) WHITE / GREY Υ Power Windows VIN / Chassis Number JF1BC6BR0EK011885 Ν Satellite Navigation **Engine Number NOT SIGHTED** Ν Leather Trim Υ Engine turns over Yes Sunroof **Battery Condition** Starts Roof Racks Ν Yes Ν Keys **Dual Fuel** No Ν Spare Keys Tow Bar Yes Ν Owner's Manual **DVD Player** Partial Ν Service History **Driving Lights** Ν **Bull Bar** Υ Cruise Control General Condition for Age & kms Park Assist Ν Seats & Upholstery Good Fair **Floors** Good **Controls and Dash Paint** Good Marks & Scratches - Location Various-general Stone Chips - Location Minor-bonnet **Dents - Location** RHS F guard, LHS R door and bumper Other Damage LHS tail light lens cracked Other Notes Vehicle Location 19 Hewitt Street, Cheltenham, VIC, 3192 Abbreviations F - Front RHS - Right hand side R - Rear LHS - Left hand side

NOTE: This report is based on an external walk around and engine start-up only – the vehicles are not driven. There may be other damage, mechanical issues or body blemishes that have not been sighted or contained in this report, therefore a full inspection is highly recommended. This report is intended as a guide only.