

## VEHICLE ASSESSMENT FORM

Vendor Number	71466
Item Number	534

**Vehicle Details Optional Accessories** (Y/N)1997 MITSUBISHI MAGNA ALTERA Year, Make & Model **ABS Brakes** Ν **SEDAN** Ν **Body Type** Front Air Bags **Build Date** SEP-97 Ν Side Impact Air Bags 1st Row SEP-97 Υ **Compliance Date** Air Conditioning Ν **Engine Type & Capacity** V6 Alloy Wheels **Transmission AUTOMATIC** Ν Remote Central Locking 227 726 Ν **Odometer (Showing)** CD Player **Registration Number** ORB864 SOLD UNREGISTERED (NO PLA Ν Multi-Function Steering Wheel Registration Expiry **Electric Seats** Ν GOLD / GREY Υ Colour (Exterior / Interior) Power Windows VIN / Chassis Number 6MMTF6U42VT011318 Ν Satellite Navigation **Engine Number NOT SIGHTED** Ν Leather Trim Engine turns over Yes Sunroof Ν **Battery Condition** Starts Roof Racks Ν Yes Ν Keys **Dual Fuel** Yes Ν Spare Keys Tow Bar Yes Ν Owner's Manual **DVD Player** Partial Ν Service History **Driving Lights** Ν **Bull Bar** Υ Cruise Control General Condition for Age & kms Park Assist Ν Seats & Upholstery Good Good **Floors** Good **Controls and Dash Paint** Good Marks & Scratches - Location Consistent for age Stone Chips - Location Minor bonnet and F bumper **Dents - Location** Other Damage Other Notes Minor paint cracking R bumper Vehicle Location 19 Hewitt Street, Cheltenham, VIC, 3192 Abbreviations R/A - Requires Attention F - Front RHS - Right hand side R - Rear LHS - Left hand side

NOTE: This report is based on an external walk around and engine start-up only – the vehicles are not driven. There may be other damage, mechanical issues or body blemishes that have not been sighted or contained in this report, therefore a full inspection is highly recommended. This report is intended as a guide only.

Please note: When buying a car at Auction you will not have the same statutory warranty, cooling-off period or Certificate of Roadworthiness you would receive when buying from a licensed motor car trader.